



89 AUG 15 PM 2:44
OFFICE OF TOXIC SUBSTANCES
EPA

Form Approved
OMB No. 2010-0019
Approval Expires 12-31-8

EPA-OTS



000667918.

90.890000596

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Comprehensive Assessment Information Rule
REPORTING FORM

When completed, send this form to:

Document Processing Center
Office of Toxic Substances, TS-790
U.S. Environmental Protection Agency
401 M Street, SW
Washington, DC 20460
Attention: CAIR Reporting Office

For Agency Use Only:

Date of Receipt: _____

Document
Control Number: _____

Docket Number: _____

PART A GENERAL REPORTING INFORMATION

[] a. If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal Register, list the CAS No. [0][2][6][4][7][1]-[6][2]-[3]

(i) Chemical name as listed in the rule NA

(ii) Name of mixture as listed in the rule NA

(iii) Trade name as listed in the rule NA

Name of category as listed in the rule NA

CAS No. of chemical substance [] [] [] [] [] [] - [] [] - []

Name of chemical substance

CBI Manufacturer 1

[] Importer 2

Processor (3)

X/P manufacturer reporting for customer who is a processor 4

X/P processor reporting for customer who is a processor 5

3

1.03 Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice?

CBI
☐ Yes ☒ Go to question 1.04
☐ No ☐ Go to question 1.05

1.04 a. Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the Federal Register Notice? Circle the appropriate response.

CBI
☐ Yes 1
☒ No 2

b. Check the appropriate box below:

☐ You have chosen to notify your customers of their reporting obligations
Provide the trade name(s) NA

☐ You have chosen to report for your customers

☐ You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting.

1.05 If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.

CBI
Trade name NA
☐ Is the trade name product a mixture? Circle the appropriate response.
Yes 1
No 2

1.06 Certification -- The person who is responsible for the completion of this form must sign the certification statement below:

CBI
☐ "I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate."

Bruce E. Hood
NAME

[Signature]
SIGNATURE

30 June 1989
DATE SIGNED

President
TITLE

(617) 639-2682
TELEPHONE NO.

☐ Mark (X) this box if you attach a continuation sheet.

- 1.07 Exemptions From Reporting -- If you have provided EPA or another Federal agency with the required information on a CAIR Reporting Form for the listed substance within the past 3 years, and this information is current, accurate, and complete for the time period specified in the rule, then sign the certification below. You CBI ☐ are required to complete section 1 of this CAIR form and provide any information now required but not previously submitted. Provide a copy of any previous submissions along with your Section 1 submission.

"I hereby certify that, to the best of my knowledge and belief, all required information which I have not included in this CAIR Reporting Form has been submitted to EPA within the past 3 years and is current, accurate, and complete for the time period specified in the rule."

NA _____
NAME SIGNATURE DATE SIGNED

TITLE () TELEPHONE NO. DATE OF PREVIOUS SUBMISSION

- 1.08 CBI Certification -- If you have asserted any CBI claims in this report you must certify that the following statements truthfully and accurately apply to all of those confidentiality claims which you have asserted.

CBI ☐ "My company has taken measures to protect the confidentiality of the information, and it will continue to take these measures; the information is not, and has not been, reasonably ascertainable by other persons (other than government bodies) by using legitimate means (other than discovery based on a showing of special need in a judicial or quasi-judicial proceeding) without my company's consent; the information is not publicly available elsewhere; and disclosure of the information would cause substantial harm to my company's competitive position."

NA _____
NAME SIGNATURE DATE SIGNED

TITLE () TELEPHONE NO.

☐ Mark (X) this box if you attach a continuation sheet.

1.09 Facility Identification

[illegible]

[W] [A] [R] [E] [F] [F] [E] [L] [D] [] [] [] [] [] [] [] [] [] [] [] [] [] []
City

State Zip

Dun & Bradstreet Number[0][7]-[5][3][6]-[2][6][6][5]

EPA ID Number[9][8][2][7][4][9][0][9][5]

Employer ID Number[4][2][5][7][5][0][3][9]

Primary Standard Industrial Classification (SIC) Code[3][0][8][6]

Other SIC Code[][][][]

Other SIC Code() () () ()

1.10 Company Headquarters Identification

Same as above 1.09

[illegible]

City

 --
 State Zip

Dun & Bradstreet Number[]-[]-[]

Employer ID Number[][][][][][][][]

☐ Mark (X) this box if you attach a continuation sheet.

NA

[illegible][illegible]

[] [] [] [] [] [] [] -- [] [] [] []
State Zip

Dun & Bradstreet Number[]-[]-[]-

CBI Name [B][R][U][C][E][][G][][H][O][O][D][][][][][][][][][][][][][][][][]

Address [B][R][A][D][L][E][E] [R][O][A][D] [] [] [] [] [] [] [] [] [] [] [] []
Street

[M][A][R][B][L][E][H][E][A][D][][][][][][][][][][][][][][][][]
City

[M] [A] [0] [1] [2] [4] [5] -- [] [] [] []
State Zip

Telephone Number[4][1][7]-[6][3][9]-[2][6][8][2]

1.13 This reporting year is from [0] [7] [3] [8] to [7] [2] [8] [8]
Mo. Year Mo. Year

☐ Mark (X) this box if you attach a continuation sheet.

1.14 Facility Acquired -- If you purchased this facility during the reporting year, provide the following information about the seller:

[illegible][illegible][illegible]

 --
State Zip

Employer ID Number[][][][][][][][]

Date of Sale [] [] [] [] [] []
Mo. Day Year

[illegible]

Telephone Number[][]-[][]-[][][]

1.15 Facility Sold -- If you sold this facility during the reporting year, provide the following information about the buyer:

[illegible][illegible]

City

 --

State Zip

[illegible]

Date of Purchase [] [] [] [] [] []
Mo. Day Year

Contact Person []

Telephone Number[][]-[][][]-[][][][]

☐ Mark (X) this box if you attach a continuation sheet.

1.16 For each classification listed below, state the quantity of the listed substance that was manufactured, imported, or processed at your facility during the reporting year.

CBI

<input type="checkbox"/> <u>Classification</u>	<u>Quantity (kg/yr)</u>
Manufactured	<u>NA</u>
Imported	<u>NA</u>
Processed (include quantity repackaged)	<u>1,692,362</u>
Of that quantity manufactured or imported, report that quantity:	
In storage at the beginning of the reporting year	<u>NA</u>
For on-site use or processing	<u>NA</u>
For direct commercial distribution (including export)	<u>NA</u>
In storage at the end of the reporting year	<u>NA</u>
Of that quantity processed, report that quantity:	
In storage at the beginning of the reporting year	<u>35,000</u>
Processed as a reactant (chemical producer)	<u>1,692,362</u>
Processed as a formulation component (mixture producer)	<u>NA</u>
Processed as an article component (article producer)	<u>NA</u>
Repackaged (including export)	<u>NA</u>
In storage at the end of the reporting year	<u>35,000</u>

☐ Mark (X) this box if you attach a continuation sheet.

1.17 Mixture -- If the listed substance on which you are required to report is a mixture or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average percentage of each component chemical for all formulations.)

[]

☐ Mark (X) this box if you attach a continuation sheet.

2.04 State the quantity of the listed substance that your facility manufactured, imported, or processed during the 3 corporate fiscal years preceding the reporting year in descending order.

CBI

☐ Year ending [1][2] [8][7]
Mo. Year

Quantity manufactured NA kg

Quantity imported NA kg

Quantity processed 1,818,017 kg

Year ending [1][2] [8][6]
Mo. Year

Quantity manufactured NA kg

Quantity imported NA kg

Quantity processed 1,811,213 kg

Year ending [1][2] [8][5]
Mo. Year

Quantity manufactured NA kg

Quantity imported NA kg

Quantity processed 1,326,771 kg

2.05 Specify the manner in which you manufactured the listed substance. Circle all appropriate process types.

CBI

☐ Continuous process 1

Semicontinuous process 2

Batch process 3

☐ Mark (X) this box if you attach a continuation sheet.

2.06 Specify the manner in which you processed the listed substance. Circle all appropriate process types.

- ☐ Continuous process 1
- ☐ Semicontinuous process 2
- ☐ Batch process 3

2.07 State your facility's name-plate capacity for manufacturing or processing the listed substance. (If you are a batch manufacturer or batch processor, do not answer this question.)

- ☐ Manufacturing capacity NA kg/yr
- ☐ Processing capacity UK kg/yr

2.08 If you intend to increase or decrease the quantity of the listed substance manufactured, imported, or processed at any time after your current corporate fiscal year, estimate the increase or decrease based upon the reporting year's production volume.

<input type="checkbox"/>	Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
Amount of increase	<u>NA</u>	<u>NA</u>	<u>UK</u>
Amount of decrease	<u>NA</u>	<u>NA</u>	<u>UK</u>

☐ Mark (X) this box if you attach a continuation sheet.

- 2.09 For the three largest volume manufacturing or processing process types involving the listed substance, specify the number of days you manufactured or processed the listed substance during the reporting year. Also specify the average number of hours per day each process type was operated. (If only one or two operations are involved, list those.)

CBI

☐

Days/Year Average
Hours/Day

Process Type #1 (The process type involving the largest quantity of the listed substance.)

Manufactured NA _____

Processed 250 2

Process Type #2 (The process type involving the 2nd largest quantity of the listed substance.)

Manufactured NA _____

Processed NA _____

Process Type #3 (The process type involving the 3rd largest quantity of the listed substance.)

Manufactured NA _____

Processed NA _____

- 2.10 State the maximum daily inventory and average monthly inventory of the listed substance that was stored on-site during the reporting year in the form of a bulk chemical.

CBI

☐

Not Required

Maximum daily inventory kg

Average monthly inventory kg

☐ Mark (X) this box if you attach a continuation sheet.

2.11 Related Product Types -- List any byproducts, coproducts, or impurities present with the listed substance in concentrations greater than 0.1 percent as it is manufactured, imported, or processed. The source of byproducts, coproducts, or impurities means the source from which the byproducts, coproducts, or impurities are made or introduced into the product (e.g., carryover from raw material, reaction product, etc.).

CBI

☐

<u>CAS No.</u>	<u>Chemical Name</u>	<u>Byproduct, Coproduct or Impurity¹</u>	<u>Concentration (%) (specify ± % precision)</u>	<u>Source of By-products, Coproducts, or Impurities</u>
<u>NA</u>				

¹Use the following codes to designate byproduct, coproduct, or impurity:

B = Byproduct
C = Coproduct
I = Impurity

☐ Mark (X) this box if you attach a continuation sheet.

- 2.12 Existing Product Types -- List all existing product types which you manufactured, imported, or processed using the listed substance during the reporting year. List the quantity of listed substance you use for each product type as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to ☐ the instructions for further explanation and an example.)

a. Product Types ¹	b. % of Quantity Manufactured, Imported, or Processed	c. % of Quantity Used Captively On-Site	d. Type of End-Users ²
<u>B</u>	<u>100%</u>	<u>100%</u>	<u>I</u>

¹Use the following codes to designate product types:

A = Solvent	L = Moldable/Castable/Rubber and additives
B = Synthetic reactant	M = Plasticizer
C = Catalyst/Initiator/Accelerator/ Sensitizer	N = Dye/Pigment/Colorant/Ink and additives
D = Inhibitor/Stabilizer/Scavenger/ Antioxidant	O = Photographic/Reprographic chemical and additives
E = Analytical reagent	P = Electrodeposition/Plating chemicals
F = Chelator/Coagulant/Sequestrant	Q = Fuel and fuel additives
G = Cleanser/Detergent/Degreaser	R = Explosive chemicals and additives
H = Lubricant/Friction modifier/Antiwear agent	S = Fragrance/Flavor chemicals
I = Surfactant/Emulsifier	T = Pollution control chemicals
J = Flame retardant	U = Functional fluids and additives
K = Coating/Binder/Adhesive and additives	V = Metal alloy and additives
	W = Rheological modifier
	X = Other (specify) _____

²Use the following codes to designate the type of end-users:

I = Industrial	CS = Consumer
CM = Commercial	H = Other (specify) _____

☐ Mark (X) this box if you attach a continuation sheet.

- 2.13 Expected Product Types -- Identify all product types which you expect to manufacture, import, or process using the listed substance at any time after your current corporate fiscal year. For each use, specify the quantity you expect to manufacture, import, or process for each use as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to the instructions for further explanation and an example.)

CBI

☐

a.	b.	c.	d.
Product Types ¹	% of Quantity Manufactured, Imported, or Processed	% of Quantity Used Captively On-Site	Type of End-Users ²
B	100%	100%	I

¹Use the following codes to designate product types:

A = Solvent	L = Moldable/Castable/Rubber and additives
B = Synthetic reactant	M = Plasticizer
C = Catalyst/Initiator/Accelerator/ Sensitizer	N = Dye/Pigment/Colorant/Ink and additives
D = Inhibitor/Stabilizer/Scavenger/ Antioxidant	O = Photographic/Reprographic chemical and additives
E = Analytical reagent	P = Electrodeposition/Plating chemicals
F = Chelator/Coagulant/Sequestrant	Q = Fuel and fuel additives
G = Cleanser/Detergent/Degreaser	R = Explosive chemicals and additives
H = Lubricant/Friction modifier/Antiwear agent	S = Fragrance/Flavor chemicals
I = Surfactant/Emulsifier	T = Pollution control chemicals
J = Flame retardant	U = Functional fluids and additives
K = Coating/Binder/Adhesive and additives	V = Metal alloy and additives
	W = Rheological modifier
	X = Other (specify) _____

²Use the following codes to designate the type of end-users:

I = Industrial	CS = Consumer
CM = Commercial	H = Other (specify) _____

☐ Mark (X) this box if you attach a continuation sheet.

2.14 Final Product -- Complete the following table for each type of final product manufactured, imported, or processed at your facility that contains the listed substance other than as an impurity.

☐

a.	b.	c.	d.
Product Type ¹	Final Product's Physical Form ²	Average % Composition of Listed Substance in Final Product	Type of End-Users ³
<u>NA</u>			

¹Use the following codes to designate product types:

A = Solvent	L = Moldable/Castable/Rubber and additives
B = Synthetic reactant	M = Plasticizer
C = Catalyst/Initiator/Accelerator/Sensitizer	N = Dye/Pigment/Colorant/Ink and additives
D = Inhibitor/Stabilizer/Scavenger/Antioxidant	O = Photographic/Reprographic chemical and additives
E = Analytical reagent	P = Electrodeposition/Plating chemicals
F = Chelator/Coagulant/Sequestrant	Q = Fuel and fuel additives
G = Cleanser/Detergent/Degreaser	R = Explosive chemicals and additives
H = Lubricant/Friction modifier/Antiwear agent	S = Fragrance/Flavor chemicals
I = Surfactant/Emulsifier	T = Pollution control chemicals
J = Flame retardant	U = Functional fluids and additives
K = Coating/Binder/Adhesive and additives	V = Metal alloy and additives
	W = Rheological modifier
	X = Other (specify) _____

²Use the following codes to designate the final product's physical form:

A = Gas	F2 = Crystalline solid
B = Liquid	F3 = Granules
C = Aqueous solution	F4 = Other solid
D = Paste	G = Gel
E = Slurry	H = Other (specify) _____
F1 = Powder	

³Use the following codes to designate the type of end-users:

I = Industrial	CS = Consumer
CM = Commercial	H = Other (specify) _____

☐ Mark (X) this box if you attach a continuation sheet.

2.15 Circle all applicable modes of transportation used to deliver bulk shipments of the listed substance to off-site customers.

☐ Truck NA 1
Railcar NA 2
Barge, Vessel NA 3
Pipeline NA 4
Plane NA 5
Other (specify) NA 6

2.16 Customer Use -- Estimate the quantity of the listed substance used by your customers or prepared by your customers during the reporting year for use under each category of end use listed (i-iv).

☐

Category of End Use

i. Industrial Products

Chemical or mixture NA kg/yr
Article NA kg/yr

ii. Commercial Products

Chemical or mixture NA kg/yr
Article NA kg/yr

iii. Consumer Products

Chemical or mixture NA kg/yr
Article NA kg/yr

iv. Other

Distribution (excluding export) NA kg/yr
Export NA kg/yr
Quantity of substance consumed as reactant NA kg/yr
Unknown customer uses NA kg/yr

☐ Mark (X) this box if you attach a continuation sheet.

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

PART A GENERAL DATA

- 3.01 Specify the quantity purchased and the average price paid for the listed substance for each major source of supply listed. Product trades are treated as purchases.
CBI The average price is the market value of the product that was traded for the listed substance.

<input type="checkbox"/> <u>Source of Supply</u>	<u>Quantity (kg)</u>	<u>Average Price (\$/kg)</u>
The listed substance was manufactured on-site.	<u>NA</u>	
The listed substance was transferred from a different company site.	<u>NA</u>	
The listed substance was purchased directly from a manufacturer or importer.	<u>1,692,362</u>	<u>2.0723</u>
The listed substance was purchased from a distributor or repackager.	<u>NA</u>	
The listed substance was purchased from a mixture producer.	<u>NA</u>	

- 3.02 Circle all applicable modes of transportation used to deliver the listed substance to your facility.

<input type="checkbox"/>	Truck	①
	Railcar	2
	Barge, Vessel	3
	Pipeline	4
	Plane	5
	Other (specify) _____	6

☐ Mark (X) this box if you attach a continuation sheet.

3.03 a. Circle all applicable containers used to transport the listed substance to your facility.
CBI

- ☐ Bags 1
Boxes 2
Free standing tank cylinders 3
Tank rail cars 4
Hopper cars 5
Tank trucks 6
Hopper trucks 7
Drums 8
Pipeline 9
Other (specify) 10

b. If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.

Tank cylinders NA mmHg
Tank rail cars NA mmHg
Tank trucks 260 ± 50 mmHg

☐ Mark (X) this box if you attach a continuation sheet.

PART B RAW MATERIAL IN THE FORM OF A MIXTURE

3.04 If you obtain the listed substance in the form of a mixture, list the trade name(s) of the mixture, the name of its supplier(s) or manufacturer(s), an estimate of the average percent composition by weight of the listed substance in the mixture, and the amount of mixture processed during the reporting year.

CBI

☐

<u>Trade Name</u>	<u>Supplier or Manufacturer</u>	<u>Average % Composition by Weight (specify \pm % precision)</u>	<u>Amount Processed (kg/yr)</u>
<u>NA</u>			

☐ Mark (X) this box if you attach a continuation sheet.

PART C RAW MATERIAL VOLUME

3.05 State the quantity of the listed substance used as a raw material during the reporting year in the form of a class I chemical, class II chemical, or polymer, and the percent composition, by weight, of the listed substance.

☐

	Quantity Used (kg/yr)	% Composition by Weight of Listed Sub- stance in Raw Material (specify \pm % precision)
Class I chemical	<u>1,692,362</u>	<u>99.9 \pm 0.05</u>
	<u> </u>	<u> </u>
	<u> </u>	<u> </u>
Class II chemical	<u>NA</u>	<u> </u>
	<u> </u>	<u> </u>
	<u> </u>	<u> </u>
Polymer	<u>NA</u>	<u> </u>
	<u> </u>	<u> </u>
	<u> </u>	<u> </u>

☐ Mark (X) this box if you attach a continuation sheet.

SECTION 4 PHYSICAL/CHEMICAL PROPERTIES

General Instructions:

If you are reporting on a mixture as defined in the glossary, reply to questions in Section 4 that are inappropriate to mixtures by stating "NA -- mixture."

For questions 4.06-4.15, if you possess any hazard warning statement, label, MSDS, or other notice that addresses the information requested, you may submit a copy or reasonable facsimile in lieu of answering those questions which it addresses.

PART A PHYSICAL/CHEMICAL DATA SUMMARY

- 4.01 Specify the percent purity for the three major¹ technical grade(s) of the listed substance as it is manufactured, imported, or processed. Measure the purity of the substance in the final product form for manufacturing activities, at the time you import the substance, or at the point you begin to process the substance.

CBI

☐

	<u>Manufacture</u>	<u>Import</u>	<u>Process</u>
Technical grade #1	NA % purity	NA % purity	99.9 % purity
Technical grade #2	NA % purity	NA % purity	NA % purity
Technical grade #3	NA % purity	NA % purity	NA % purity

¹Major = Greatest quantity of listed substance manufactured, imported or processed.

- 4.02 Submit your most recently updated Material Safety Data Sheet (MSDS) for the listed substance, and for every formulation containing the listed substance. If you possess an MSDS that you developed and an MSDS developed by a different source, submit your version. Indicate whether at least one MSDS has been submitted by circling the appropriate response.

Yes (1)

No 2

Indicate whether the MSDS was developed by your company or by a different source.

Your company 1

Another source (2)

☐ Mark (X) this box if you attach a continuation sheet.

MATERIAL SAFETY DATA SHEET

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 1

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

1. INGREDIENTS: (% w/w, unless otherwise noted)

Toluene-2,4-diisocyanate (TDI)	CAS# 000584-84-9	80%
Toluene-2,6-diisocyanate	CAS# 000091-08-7	20%

This document is prepared pursuant to the OSHA Hazard Communication Standard (29 CFR 1910.1200). In addition, other substances not 'Hazardous' per this OSHA Standard may be listed. Where proprietary ingredient shows, the identity may be made available as provided in this standard.

2. PHYSICAL DATA:

BOILING POINT: 250C (482F)
VAP PRESS: 0.01 mmHg @ 20C
VAP DENSITY: 6.0
SOL. IN WATER: Insoluble
SP. GRAVITY: 1.22 @ 25/15.5C
APPEARANCE: Water white to pale yellow liquid.
ODOR: Sharp pungent odor.

3. FIRE AND EXPLOSION HAZARD DATA:

FLASH POINT: 127C (260F)
METHOD USED: PMCC, ASTM D-93

FLAMMABLE LIMITS
LFL: Not determined
UFL: Not determined

EXTINGUISHING MEDIA: Carbon dioxide, dry chemical, or foam.
If water is used, it should be in very large quantity.
The reaction between water and hot isocyanate may be vigorous.

FIRE & EXPLOSION HAZARDS: Down-wind personnel must be evacuated.

(Continued on Page 2)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

M A T E R I A L S A F E T Y D A T A S H E E T

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 2

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

3. FIRE AND EXPLOSION HAZARD DATA: (CONTINUED)

Do not reseal contaminated containers since pressure build-up may cause rupture. Fire point: 146C (295F).

FIRE-FIGHTING EQUIPMENT: People who are fighting isocyanate fires must be protected against nitrogen oxide fumes and isocyanate vapors by wearing positive pressure self-contained breathing apparatus and full protective clothing.

4. REACTIVITY DATA:

STABILITY: (CONDITIONS TO AVOID) Stable when stored under recommended storage conditions. Store in a dry place at temperatures between 18-41C (65-105F).

INCOMPATIBILITY: (SPECIFIC MATERIALS TO AVOID) Water, acid, base, alcohols, metal compounds, surface active materials. Avoid water as it reacts to form heat, CO₂ and insoluble urea. The combined effect of the CO₂ and heat can produce enough pressure to rupture a closed container.

HAZARDOUS DECOMPOSITION PRODUCTS: Isocyanate vapor and mist, carbon dioxide, carbon monoxide, nitrogen oxides and traces of hydrogen cyanide.

HAZARDOUS POLYMERIZATION: May occur with incompatible reactants, especially strong bases, water or temperatures over 41C (105F).

5. ENVIRONMENTAL AND DISPOSAL INFORMATION:

ACTION TO TAKE FOR SPILLS/LEAKS:

Evacuate and ventilate spill area, dike spill to prevent entry into water system, wear full protective equipment including respiratory equipment during clean up.

Major spill: Call Dow Chemical U.S.A. (409) 238-2112. If

(Continued on Page 3)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

MATERIAL SAFETY DATA SHEET

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 3

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

5. ENVIRONMENTAL AND DISPOSAL INFORMATION: (CONTINUED)

transportation spill involved call CHEMTREC (800) 424-9300. If temporary control of isocyanate vapor is required a blanket of protein foam (available at most fire departments) may be placed over the spill. Large quantities may be pumped into closed but not sealed containers for disposal.

Minor spill: Absorb the isocyanate with sawdust or other absorbent and shovel into open top containers. Do not make pressure tight. Transport to a well-ventilated area (outside)

and treat with neutralizing solution consisting of a mixture of water and 3-8% concentrated ammonium hydroxide or 5-10% sodium carbonate. Add about 10 parts of neutralizer per part of isocyanate with mixing. Allow to stand for 48 hours letting evolved carbon dioxide to escape.

Clean-up: Decontaminate floor using water/ammonia solution with 1-2% added detergent letting stand over affected area for at least 10 minutes. Cover mops and brooms used for this with plastic and dispose properly (often by incineration).

DISPOSAL METHOD: Follow all federal, state and local regulations. Liquids are usually incinerated in a proper facility. Solids are usually also incinerated or landfilled. Empty drums should be filled with water. Let drum stand unsealed for 48 hours. Before disposal drums should be drained, triple rinsed, and holed to prevent reuse. Dispose of drain and rinse fluid according to federal, state and local laws and regulations. The most commonly accepted method is in an approved wastewater treatment facility. Drums should be disposed of in accordance with federal, state and local laws and regulations. Commonly accepted methods for disposal of plastic drums are disposal in an approved landfill after shredding or incineration in an approved industrial incinerator or other appropriate incinerator facility. Steel drums are commonly disposed in an approved landfill after crushing or in accordance with other approved procedures.

(Continued on Page 4)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

MATERIAL SAFETY DATA SHEET

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 4

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

6. HEALTH HAZARD DATA:

EYE: May cause pain, severe eye irritation and moderate corneal injury. Vapors may irritate eyes.

SKIN CONTACT: Prolonged or repeated exposure may cause severe irritation, even a burn. Skin contact may result in allergic reaction even though it is not expected to result in absorption of amounts sufficient to cause other adverse effects.

SKIN ABSORPTION: The LD50 for skin absorption in rabbits is >9400 mg/kg.

INGESTION: Single dose oral toxicity is low. The oral LD50 for rats is 5800 mg/kg. Ingestion may cause gastrointestinal irritation or ulceration.

INHALATION: Excessive vapor concentrations are attainable and could be hazardous on single exposure. Single and repeated excessive exposure may cause severe irritation to upper respiratory tract and lungs (choking sensation, chest tightness), respiratory sensitization, decreased ventilatory capacity, liver effects, cholinesterase depression, gastrointestinal distress and/or neurologic disorders. The 4-hour LC50 for TDI for rats is 13.9 ppm.

SYSTEMIC & OTHER EFFECTS: Based on available data, repeated exposures are not anticipated to cause any additional significant adverse effects. For hazard communication purposes under OSHA standard 29 CFR Part 1910.1200, this chemical is listed as a potential carcinogen by Nat'l. Tox. Program and IARC. An oral study in which high doses of TDI were reported to cause cancer in animals has been found to contain numerous deficiencies which compromise the validity of the study. TDI did not cause cancer in laboratory animals exposed by inhalation, the most likely route of exposure. Birth defects are unlikely. Exposures having no effect on the mother should have no effect on the fetus. Did not cause birth defects in animals; other effects were seen in the fetus only at doses which caused toxic effects to the mother. Results of in vitro ("test tube") mutagenicity

(Continued on Page 5)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

MATERIAL SAFETY DATA SHEET

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 5

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

6. HEALTH HAZARD DATA: (CONTINUED)

tests have been inconclusive.

7. FIRST AID:

EYES: Irrigate with flowing water immediately and continuously for 15 minutes. Consult medical personnel.

SKIN: In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Call a physician if irritation persists. Wash clothing before reuse. Destroy contaminated shoes.

INGESTION: Do not induce vomiting. Call a physician and/or transport to emergency facility immediately.

INHALATION: Remove to fresh air. If not breathing, give mouth-to-mouth resuscitation. If breathing is difficult, give oxygen. Call a physician.

NOTE TO PHYSICIAN: May cause tissue destruction leading to stricture. If lavage is performed, suggest endotracheal and/or esophagoscopy control. If burn is present, treat as any thermal burn, after decontamination. No specific antidote. Supportive care. Treatment based on judgment of the physician in response to reactions of the patient. The manifestations of the respiratory symptoms, including pulmonary edema, resulting from acute exposure may be delayed. May cause respiratory sensitization. Cholinesterase inhibition has been noted in human exposure but is not of benefit in determining exposure and is not correlated with signs of exposure.

(Continued on Page 6)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

M A T E R I A L S A F E T Y D A T A S H E E T

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 6

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

8. HANDLING PRECAUTIONS:

EXPOSURE GUIDELINE(S): OSHA PEL is 0.02 ppm as a ceiling limit for toluene 2,4-diisocyanate. ACGIH TLV is 0.005 ppm; 0.02 ppm STEL for toluene 2,4-diisocyanate. Dow Industrial Hygiene Guide is 0.02 ppm as a ceiling limit for toluene diisocyanate.

VENTILATION: Provide general and/or local exhaust ventilation to control airborne levels below the exposure guidelines.

RESPIRATORY PROTECTION: Atmospheric levels should be maintained below the exposure guideline. When respiratory protection is required for certain operations, use an approved supplied-air respirator. For emergency and other conditions where the exposure guideline may be greatly exceeded, use an approved positive-pressure self-contained breathing apparatus.

SKIN PROTECTION: Use protective clothing impervious to this material. Selection of specific items such as gloves, boots, apron, or full-body suit will depend on operation. Remove contaminated clothing immediately, wash skin area with soap and water, and launder clothing before reuse. Safety shower should be located in immediate work area.

EYE PROTECTION: Use chemical goggles. If vapor exposure causes eye irritation, use a full-face, supplied-air respirator. Eye wash fountain should be located in immediate work area.

9. ADDITIONAL INFORMATION:

REGULATORY REQUIREMENTS:

SARA HAZARD CATEGORY: This product has been reviewed according to the EPA 'Hazard Categories' promulgated under Sections 311 and 312 of the Superfund Amendment and Reauthorization Act of 1986 (SARA Title III) and is considered, under applicable definitions, to meet the following categories:

(Continued on Page 7)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

MATERIAL SAFETY DATA SHEET

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92097

Page: 7

PRODUCT NAME: VORANATE (R) T-80 TYPE I TOLUENE DIISOCYANATE

Effective Date: 12/13/88 Date Printed: 02/03/89

MSDS:000609

9. ADDITIONAL INFORMATION: (CONTINUED)

An immediate health hazard
A delayed health hazard
A reactive hazard

SPECIAL PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: Warning properties of this material (irritation of eyes, nose and throat) not adequate to prevent chronic overexposure from inhalation. This material can produce asthmatic sensitization upon either single inhalation exposure to a relatively high concentration or upon repeated inhalation exposure to lower concentrations. Exposures to vapors of heated TDI can be extremely dangerous. (Have TDI neutralizer available for spills.)

MSDS STATUS: Revised Section 9

SARA 313 INFORMATION:

This product contains the following substances subject to the reporting requirements of section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372:


CHEMICAL NAME	CAS NUMBER	CONCENTRATION
TOLUENE-2,6-DIISOCYANATE	000091-08-7	20 %
TOLUENE-2,4-DIISOCYANATE	000584-84-9	80 %

(R) Indicates a Trademark of The Dow Chemical Company
The Information Herein Is Given In Good Faith, But No Warranty, Express Or Implied, Is Made. Consult The Dow Chemical Company For Further Information.

* An Operating Unit of The Dow Chemical Company

DOW

Safe Handling and Storage of VORANATE T-80 Toluene Diisocyanates



Safe Handling and Storage of VORANATE T-80 Toluene Diisocyanates

- A mixture of the 2,4- and 2,6-isomers of toluene diisocyanate in a ratio, by weight, of 80 to 20 percent.
- Available in both high- and low-acidity grades.
- Produced in accordance with exacting standards of product purity and quality.
- Widely used in a broad range of industrial applications, including the production of flexible polyurethane foams for furniture, bedding, and automotive seating and padding.
- Also used in the production of elastomers, coatings, adhesives, semi-flexible foams, and carpet underlayment and backing.
- Manufactured and marketed by The Dow Chemical Company — a leading supplier of quality products and services to the polyurethane industry.

Contents

VORANATE* T-80 Toluene Diisocyanates	2
Part One — Properties, Handling Precautions, and Industrial Hygiene	3
Properties	4
Typical Physical Properties	4
Specifications	5
Density	5
Viscosity	6
Refractive Index	6
Handling Precautions	7
VORANATE T-80 Toluene Diisocyanates	7
Moisture Control	7
Temperature Control	8
Contamination by Strong Bases	8
Contamination by Amines and Other Active Hydrogen-Containing Compounds	8
Fire Hazards	9
Spills and Leaks (Containment and Cleanup)	9
Pressurized Drums	12
Drum Decontamination	13
Disposal	13
Other Polyurethane Chemicals	13
Polyols	13
Catalysts	13
Blowing Agents	14
Miscellaneous Products	14
Application Hazards of Polyurethane Foams	14
Dust	14
Combustibility	15
Handling Precautions Summary	16

*Trademark of The Dow Chemical Company

©1988, The Dow Chemical Company
All rights reserved

Industrial Hygiene	17
Hazard and Exposure Guidelines	17
Health Hazards	18
Inhalation	18
Skin Contact	18
Eye Contact	19
Ingestion	19
Chronic Toxicity	19
First Aid	19
Inhalation	19
Skin Contact	19
Eye Contact	19
Ingestion	19
Note to Physician	20
 Part Two — Shipment, Handling, and Storage ...	21
Shipment and Handling	22
General Specifications for Tank Trucks and Tank Cars	22
Unloading Procedures	22
Tank Trucks	22
Tank Cars	24
Drums	28
Storage	29
Drum Storage	29
Bulk Storage	29
Tanks	29
Linings	29
Insulation	30
Pumps	30
Relief Valves	30
Pressure Gauges	30

Sample Valves	30
Piping	30
Heating	30
Heat Exchangers	30
Pad Gas	30
Pressure Control Valves (PCV)	30
Temperature Indicators (TI)	30
Level Indicators (LI)	30
Strainers	31
Filters	31
Meters	31
Valves	31
Gaskets	31
Hoses	32
Electrical	32
Foundations	32
Paint	32
Dual-Service Equipment	32
Drains	32
Ventilation	32
Miscellaneous	32
 Appendix A — Equipment Manufacturers and Suppliers: Bulk Handling and Storage Equipment	33
 Appendix B — Equipment Manufacturers and Suppliers: Respiratory Protective Equipment ..	39
 Appendix C — References	42

This publication was printed in February 1988. Since The Dow Chemical Company is continually updating its product safety and handling information, please contact Dow for updated information or revisions to this bulletin if a significant period of time has passed since the publication date.

VORANATE T-80
Safe Handling and Storage

VORANATE T-80 Toluene Diisocyanates

VORANATE* T-80 Type I Toluene Diisocyanate and VORANATE T-80 Type II Toluene Diisocyanate are two members of a family of quality isocyanate products manufactured and marketed by The Dow Chemical Company. These products are a mixture of the 2,4- and 2,6-isomers of toluene diisocyanate (TDI) in a ratio, by weight, of 80 to 20 percent. Type I is a low-acidity grade and Type II is a high-acidity grade. Both products are produced in accordance with exacting standards of quality and product purity.

VORANATE T-80 Toluene Diisocyanates are widely used in a variety of industrial applications, including the production of flexible polyurethane foams for use in furniture, bedding, and automotive applications. They are also widely used in the production of elastomers, coatings, adhesives, semi-flexible foams, and carpet underlayment and backing.

A second group of quality isocyanate products — VORANATE Specialty Isocyanates — is manufactured and marketed by The Dow Chemical Company, primarily for use in the production of "rigid" polyurethane foams, which are used by the home appliance industry to insulate refrigerators, freezers, and water heaters. These materials are also widely used in such rigid foam applications and products as rigid foam

insulation, "spray up" or "spray on" foam insulation, wood simulation products, and various other structural items. VORANATE Specialty Isocyanates are discussed in detail in the Dow bulletin, *Safe Handling and Storage of VORANATE Specialty Isocyanates* (Form No. 109-546-82), copies of which are available upon request from any Dow sales office or The Dow Chemical Company, Plastics Group, 2040 Willard H. Dow Center, Midland, MI 48674.

VORANATE T-80 Toluene Diisocyanates are hazardous materials which must be handled and stored only by knowledgeable and experienced personnel who are thoroughly familiar with the hazards associated with their shipment, storage, distribution, and use.

The purpose of this booklet is to inform customers of the hazards associated with VORANATE T-80 Toluene Diisocyanates — particularly the hazards of inhaling TDI vapors and the possible explosive rupture of restricted lines and vessels caused by product contamination and the subsequent formation of carbon dioxide gas — and to outline in detail those practices and procedures which have been developed to assist in their safe storage and handling. In short: "Chemicals in any form can be safely stored, handled, or used if the physical, chemical, and hazardous properties are fully understood and the necessary precautions, including the use of proper safeguards and personal protective equipment, are observed."¹

WARNING

VORANATE T-80 Toluene Diisocyanates are hazardous materials which must be handled, used, and stored with extreme care and in strict compliance with the safety recommendations and precautions outlined on the product label and described in this booklet.

Note: The recommendations contained in this booklet are based on the results of numerous tests and on actual experiences in the field, and are believed to be accurate and reliable. However, since the specific circumstances associated with a customer's use of VORANATE T-80 Toluene Diisocyanates are unknown to The Dow Chemical Company and are beyond its control, the company cannot guarantee that adherence to these recommendations will insure absolute safety. Inquiries about specific operations and procedures or about matters relating to the safe use, handling, and storage of VORANATE T-80 Toluene Diisocyanates may be addressed to The Dow Chemical Company, Plastics Group, 2040 Willard H. Dow Center, Midland, MI 48674.

*Trademark of The Dow Chemical Company

¹Quoted from a publication of the Chemical Manufacturers Association.

PART ONE

Properties,
Handling
Precautions,
and
Industrial
Hygiene

Properties

Table 1 — Typical Physical Properties:
VORANATE T-80 Toluene Diisocyanates

Properties ¹	Values
Molecular Weight	174.2
Physical Form	Colorless to Pale Yellow Liquid
Odor	Very Sharp and Pungent
Density (@ 20°C), lbs/gal	10.2
Specific Gravity (25°C/25°C)	1.22
Boiling Point at 10 mm Hg	248°F (120°C)
at 760 mm Hg	482°F (250°C)
Viscosity @ 77°F (25°C) cst	2.5
Freezing Point	57°F (14°C)
Flash Point	
Cleveland Open Cup	270°F (132°C)
Pensky-Martens Closed Cup	260°F (127°C)
Tag Open Cup	270°F (132°C)
Fire Point	
Cleveland Open Cup	295°F (146°C) ²
Refractive Index @ 77°F (25°C)	1.5662
Specific Heat, Btu/lb, °F	0.35 @ 68°F
	0.41 @ 212°F
Specific Heat, cal/gram, °C	0.35 @ 20°C
	0.41 @ 100°C
Heat of Evaporation	Btu/lb cal/g
@ 250°F (121°C)	131 73
@ 355°F (197°C)	121 67
Decomposition Temperature	530°F (287°C)
Vapor Density (Air = 1)	6.0
Vapor Pressure @ 77°F (25°C), mm Hg	0.01

¹Typical properties; not to be construed as specifications.

²Results of small scale tests are not intended to reflect behavior of this or any other material under actual fire conditions.

Table 2 — Specifications: VORANATE T-80
Toluene Diisocyanates

Properties	Type I Low Acidity Grade	Type II High Acidity Grade
Assay (wt % TDI) min	99.5	99.5
Acidity (wt % HCl) limits	0.0010-0.0040	0.0070-0.0120
Hydrolyzable Chloride (wt %) limits	0.0015-0.0070	0.0070-0.0150
Total Chloride (wt %) max	0.06	0.07
Color (APHA) max	25	25
Isomer Content,		
% 2,4 Isomer	79-81	79-81
% 2,6 Isomer	19-21	19-21

Method of analysis for data is ASTM D1638-70. Copies of ASTM D1638-70 can be obtained from the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.

Figure 1 — Density vs. Temperature of VORANATE T-80 TDI




Figure 2 — Viscosity vs. Temperature of VORANATE T-80 TDI





Figure 3 — Refractive Index vs. Temperature of VORANATE T-80 TDI



Handling Precautions

VORANATE T-80 Toluene Diisocyanates

To minimize the hazards associated with their use and to insure product quality, VORANATE T-80 Toluene Diisocyanates should be handled and stored only by knowledgeable and experienced personnel. Extreme care must be exercised to avoid exposing the products to water, heat, strong bases, and amines or other active hydrogen-containing compounds, all of which are among the most common sources of product contamination — a condition which can result in the explosive rupture of restricted lines and vessels due to the subsequent formation of carbon dioxide gas. Extreme care must also be exercised to minimize the hazards of fire and accidental spills — conditions which can release potentially harmful concentrations of isocyanate vapors. It is essential, therefore, before handling, using, or storing VORANATE T-80 Toluene Diisocyanates, that all personnel carefully read and understand each of the safety recommendations and precautions described in this booklet.

Moisture Control

The most common contaminant of isocyanates, and one of the more hazardous, is water, which, at room temperature, reacts readily with isocyanates to form both an insoluble urea compound and carbon dioxide. This insoluble urea derivative will be deposited on the surfaces of the equipment in which it is formed. Should lines and orifices become plugged, thus closing or restricting the vessel, liberated carbon dioxide could present an extreme pressure hazard. In short, the presence of water or large amounts of moisture can produce sufficient carbon dioxide to rupture the container. Even small quantities of water can cause significant problems. For example, at standard temperature and pressure, as little as 1 lb (0.454 kg) of water can release as much as 21 cu ft (0.6 cu meter) of CO₂.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Do *not* tightly close vessels containing isocyanate if the product has been, or is suspected of having been, contaminated with water.

- To protect VORANATE T-80 Toluene Diisocyanates from atmospheric moisture, use a dry, -40°F (-40°C) dew point, inert gas pad. Dry air with the same dew point may also be used. However, nitrogen is preferred.
- Carefully clean equipment or containers to be used for isocyanates; then purge with a dry gas before using. The purge gas, in addition to being moisture-free, must also be free of oil and rust. Filter traps in the dry gas lines are recommended for the removal of rust particles.
- For small installations, manifold cylinders of dry nitrogen arranged into banks may be adequate. Larger installations, however, may call for a nitrogen generator, a compressed air system, or a tie-in to existing plant gas systems. If a plant air system is used, purification equipment, such as oil traps, a bauxite absorber to keep oil out of the drying beds, and an air dryer, should be installed between the compressor and the isocyanate system. Also, a final filter should be fitted just in front of the isocyanate system. Stainless steel pipe or tubing should be used between the filter and the system.
- Instrumentation for detecting the failure of the drying equipment for the purge gas is recommended when large quantities of isocyanate are handled and stored. Several moisture-detecting instruments are commercially available and may be readily obtained from manufacturers and suppliers listed on pages 33-36.
- When lines leading to and from storage tanks are not in use, they should be tightly plugged or capped. This will prevent moisture from coming in contact with residual isocyanate left in the lines. Also, all flexible connection lines should be rinsed with methylene chloride or another suitable solvent.¹ These fittings should be dried and stored in a dry place. A plastic bag containing a desiccant, such as silica gel, makes a convenient, portable dry place for storing such items.

¹Most solvents possess hazardous properties and should be used with care. Also, be sure to read and follow all label directions and precautions.

Temperature Control

Ideally, VORANATE T-80 Toluene Diisocyanates should be stored at temperatures between 65°F (18°C) and 105°F (40°C). This may be accomplished by equipping the storage tank with either a heat exchanger installed in the storage tank recycle line or an external plate coil mounted on the outside of the tank. In addition, storage tanks should be insulated or otherwise protected from ambient weather conditions. Prolonged storage of VORANATE T-80 Toluene Diisocyanates at higher temperatures may cause the percent NCO (i.e., isocyanate) and viscosity to vary from product specifications.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Before using VORANATE T-80 Toluene Diisocyanates that have been stored in tanks or drums for a lengthy period, warm, mix thoroughly, and inspect the products to be sure that no solids are present. **WARNING:** Do *not* breathe vapor. Vapor is extremely irritating if inhaled. See the "Toxicity" and "Health Hazards" sections under "Industrial Hygiene" on pages 17 and 18.
- If a storage tank is to be equipped with an external plate coil, be sure it is mounted on the exterior of the tank. This will not only eliminate the possibility of contamination of the isocyanate by a water leak in the heating coils, but will also minimize the possibility of localized overheating.
- If TDI should freeze — the freeze point is approximately 57°F (14°C) — the 2,4- and 2,6-isomers may separate. If this occurs, the TDI should be warmed to a maximum temperature of 95°F (35°C) and thoroughly mixed. Do *not* heat TDI above 105°F (40°C) as discoloration and dimerization may occur. Also, at temperatures above 212-248°F (100-120°C), TDI will trimerize in an exothermic reaction to form isocyanurates. This reaction may furnish enough heat (i.e., greater than 347°F [175°C]) to cause the formation of

carbodiimides and the subsequent formation of carbon dioxide. This second reaction may create a pressure hazard in a closed or restricted vessel.

- During the winter, drum deliveries may arrive in a solid state. If this occurs, the TDI can be readily liquefied by heating the product to a maximum temperature of 95°F (35°C). Be sure that the liquefied TDI is thoroughly mixed before use. Also, do *not* use partially melted material. Since the 2,4-isomer melts at a higher temperature than the 2,6-isomer, the supernatant liquid in contact with the crystals will have a higher 2,6-isomer content than the completely liquid product. Also, since the 2,6-isomer reacts more slowly with compounds having an active hydrogen than does the 2,4-isomer, the supernatant liquid will have a slower reaction rate than the material as a whole. This could cause serious processing difficulties.

Contamination by Strong Bases

The presence of strong bases — even in small amounts — can cause any isocyanate to react with itself to form isocyanurates and carbodiimides. The carbodiimide formation is accompanied by the liberation of carbon dioxide, which may present a pressure hazard.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Avoid any contact between isocyanates and strong bases, such as sodium and potassium hydroxide or alkoxides. Such compounds catalyze the rapid formation of isocyanurates and carbodiimides. Normally, the trimerization reaction occurs first, furnishing heat to cause the carbodiimide reaction. This second reaction liberates carbon dioxide and forms a hard solid or foam which can only be removed from the vessel or line by mechanical means. **WARNING:** The liberation of carbon dioxide in a tightly closed or restricted vessel may result in an explosive rupture.
- A likely source of contamination by strong bases is from industrial cleaning. Do *not* use, or permit the use of, sodium or potassium hydroxide or other strong bases in cleaning lines or vessels.

Contamination by Amines and Other Active Hydrogen-Containing Compounds

The primary dangers of contamination by amines and other active hydrogen-containing compounds are product contamination and the liberation of heat.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Avoid contamination of VORANATE T-80 Toluene Diisocyanates by such compounds as alcohols, glycols, phenols, amines, amides, and acid anhydrides. Such compounds will react readily with isocyanates to form their corresponding addition products. Although reactions caused by contamination from amines or other active hydrogen-containing compounds do not release a gas, they do release considerable quantities of heat, which could ultimately lead to the homopolymerization of the isocyanate to carbodiimides, with a concurrent release of carbon dioxide. Contamination by heavy metal salts can also cause homopolymerization and should therefore be avoided. (See below.)
- In the event of gross contamination, the exothermic reaction could raise the temperature of the mixture above 212-248°F (100-120°C). This could result in the secondary reaction of trimerization — an exothermic reaction which, in turn, could raise the temperature of the mixture above 347°F (175°C). At this temperature, another secondary reaction — the homopolymerization of the isocyanate to carbodiimides — can occur, with a concurrent release of carbon dioxide. Finally, the release of quantities of carbon dioxide — especially in a closed or restricted vessel — could lead to an explosive rupture.

Fire Hazards

VORANATE T-80 Toluene Diisocyanates have been classified as Class III B combustible materials by the National Fire Protection Association. (Depending on the method used, the flash point of TDI is between 260 and 270°F [126-132°C]. The flammability limits in air are 0.9 to 9.5 percent.) In short, VORANATE T-80 Toluene Diisocyanates will burn in the presence of an existing fire or high heat source and adequate oxygen. The low volatility of isocyanates minimizes the potential hazard of explosion; however, under fire conditions in which a large concentration of isocyanate vapor is generated, explosive limits could be attained and an explosion could occur.

Read and follow carefully each of the safety recommendations and precautions listed below:

- In the event of an isocyanate fire, use a carbon dioxide or dry chemical extinguisher. For fires covering large areas, use a protein foam, Halon 1211 polymer, or water spray. When spraying water, be careful not to disperse any leaked or spilled isocyanate. Also, once the fire is out, any leaked or spilled isocyanate should be promptly contained and cleaned up. See "Spills and Leaks (Containment and Cleanup)."
- Personnel engaged in fighting isocyanate fires must be protected against nitrogen dioxide vapors as well as isocyanate fumes. Fire fighters should wear an approved¹ positive-pressure, self-contained breathing apparatus and fire-resistant clothing, footwear, and gloves.

Spills and Leaks (Containment and Cleanup)

Spills and leaks of VORANATE T-80 Toluene Diisocyanates should be contained by diking, if necessary, and cleaned up only by properly trained and equipped personnel. All others should promptly leave the contaminated area. Protective equipment should include appropriate respiratory protective devices (e.g., a positive-pressure, self-contained breathing apparatus) and impervious clothing, footwear, and gloves. In addition, all work areas should be equipped with safety showers and eye baths in good working order. Any isocyanate or other chemical accidentally spilled or leaked onto the skin should be quickly washed off. Also, an approved¹ respiratory protective device *must* be worn whenever there is any possibility of exposure to concentrations of vapors of TDI-based Specialty Isocyanates exceeding 0.02 ppm (0.14/mg/cu m). A positive-pressure, air-supplied, or self-contained breathing apparatus, equipped with a full facepiece, hood, or helmet, is recommended. See "Respirator Selection Guide" on page 17. (Note: Purchasers of VORANATE T-80 Toluene Diisocyanates automatically receive current Material Safety Data Sheets, which contain information about safe "spill and leak" handling procedures.)

¹The authority for approving or certifying respiratory protective devices is held jointly by the National Institute for Occupational Safety and Health (NIOSH) and the Mine Safety and Health Administration (MSHA). For current information on the status of approvals for respiratory protective devices, contact any of the manufacturers or suppliers listed on pages 39-41 or write to the National Institute for Occupational Safety and Health, 944 Chestnut Ridge Road, Morgantown, WV 26505 (phone: 304-291-4126).

Minor and Major Spills

In considering spills, it is useful to distinguish between minor incidents, such as may occur in a laboratory or workshop regularly handling isocyanates, and major spills, involving, for example, a railcar, storage tank, or bulk road tanker. The most important criterion for distinguishing between them is the ability of personnel on the scene to deal with the occurrence, rather than the actual scale of the incident. Hence, a minor spill is defined as one which can be dealt with using existing facilities, while a major spill is one that necessitates summoning outside assistance from, for example, the supplier, the police, fire services, or other emergency response personnel. It is important to remember, however, that even minor spills are potentially as hazardous as major spills, especially if they are not handled with care.

Drivers of tank trucks containing VORANATE T-80 Toluene Diisocyanates carry an "Emergency Response Information Sheet," which contains information on the safe handling of spills and leaks. In the event of a major spill, or for advice and/or assistance in containing and cleaning up spills and leaks of any size, call CHEMTREC (phone: 800-424-9300) or The Dow Chemical Company Distribution Emergency/Response Center in Freeport, TX (phone: 409-238-2112), or Midland, MI (phone: 517-636-4400). You may call these numbers at any time — day or night. See "Major Spills," page 11.

VORANATE T-80
Safe Handling and Storage

Minor Spills and Leaks

Method I: Using an Absorbent Material

All spills and leaks should be contained immediately to prevent further contamination of the surrounding area.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Ventilate the contaminated area. Open all doors and windows. To avoid inhaling vapors of either the isocyanate or the decontaminants used, workers should wear appropriate respiratory protective devices; e.g., a positive-pressure, self-contained breathing apparatus. See "Respirator Selection Guide" on page 17.
- If the source of the leak is a damaged or leaking drum, it should be immediately moved outdoors or to an isolated, well-ventilated area and the contents carefully transferred to other suitable, leak-free containers. The damaged drum or container should be decontaminated as recommended on page 13. Also, the new container should be carefully checked to ensure that atmospheric moisture does not cause overpressurization. Leaking stationary containers should be temporarily patched, emptied, and thoroughly decontaminated. Permanent repairs can then be made.
- Completely cover the leak or spill with an absorbent material, such as sawdust, vermiculite, an all-purpose commercial oil absorbent, or sand. Use an amount greater than is estimated to be necessary to absorb the isocyanate.
- Carefully shovel the absorbent/isocyanate mixture into an open-top steel container; cover but do *not* make pressure tight. **Remove to a safe disposal site, away from the operating area, for neutralization.**
- Soak the mixture in the container with a solution of 5 percent ammonia in water and allow it to stand undisturbed for at least 48 hours. **WARNING:** Considerable heat, which could cause ignition, may be generated when the aqueous ammonia solution is first applied. After standing for 48 hours, however, the drum may be closed (though *not* pressure tight) and properly disposed of. See "Disposal" on page 13. To limit the amount of heat generated during the neutralization process, soak small quantities of the absorbent/isocyanate mixture in separate containers.
- Immediately after shoveling the absorbent/isocyanate mixture from the floor, complete the decontamination by mopping the floor using a water/ammonia solution with 1-2% added detergent. Be sure the area is well ventilated both during and after cleanup.
- Carefully test the atmosphere for residual isocyanate vapor. Instruments designed for TDI monitoring are available from several firms. See "VAPOR DETECTORS" in "Appendix A — Equipment Manufacturers and Suppliers: Bulk Handling and Storage Equipment," page 38.
- When safe working conditions have been reestablished, remove and decontaminate protective and return to normal operation.

Method II: Using a Premixed Isocyanate Neutralizer

The following is an effective alternative method for handling spills and leaks. All leaks and spills should be contained and immediately "neutralized" to prevent further contamination of the surrounding area.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Always have a sufficient quantity of premixed isocyanate neutralizer, such as the one described, in storage. Premixed neutralizer may be stored in tightly closed heavy-duty polyethylene bags. Seal bags with wire twists. Also, the use of neutralizing solvents and other chemicals may introduce additional hazards of toxicity and flammability. Such materials, therefore, must be used in strict compliance with the manufacturer's recommendations and precautions.
- Ventilate the area. Open all doors and windows. To avoid inhalation of isocyanate vapors or the vapors of the decontaminants used, workers should wear appropriate respiratory protective devices (e.g., a positive-pressure, self-contained breath apparatus). See "Respirator Selection Guide" on page 17.
- If the source of the leak is a damaged or leaking drum, it should be immediately removed to the outdoors or to an isolated, well-ventilated area and the contents carefully transferred to other suitable, leak-free containers. The damaged drum or container should be decontaminated as recommended on page 13. Also, the new container should be carefully checked to ensure that atmospheric moisture does not cause overpressurization. Leaking stationary

containers should be temporarily patched, emptied, and thoroughly decontaminated. Permanent repairs can then be made.

- Promptly cover the spilled or leaked material with the neutralizer. For more effective coverage, and to ensure greater contact between the neutralizer and the isocyanate, use an industrial type heavy-duty broom to sweep the neutralizer into the spill.
- After the neutralizer has been on the spill for at least two hours, shovel the material into a steel container and dispose of properly. The broom should be wrapped carefully in plastic to contain the contaminants and then burned in an incinerator. See "Disposal" on page 13.
- Carefully test the atmosphere for residual isocyanate vapor. Instruments designed for TDI monitoring are available

from a number of firms. See "VAPOR DETECTORS" in "Appendix A—Equipment Manufacturers and Suppliers: Bulk Handling and Storage Equipment," page 38.

- When safe working conditions have been reestablished, remove and decontaminate protective equipment and return to normal operation.
- Note: The use of neutralizing solvents and other chemicals may introduce additional hazards of toxicity and flammability. Such materials, therefore, *must* be used in strict compliance with the manufacturer's recommendations and precautions.

This spill removal procedure is very effective in decontaminating an area. In situations where ventilation may be restricted, Method I was found to produce lower concentrations of isocyanate vapor during standardized tests.

ISOCYANATE NEUTRALIZER

Ingredients:

Sawdust	22 lbs (10 kg)
Fuller's Earth	38 lbs (17.3 kg)
Total Carrier Solids	60 lbs (27.3 kg)
Ethanol or Isopropyl Alcohol ¹	19 lbs (8.6 kg)
Triethanolamine ²	4 lbs (1.8 kg)
Ammonium Hydroxide	4 lbs (1.8 kg)
Water	12.8 lbs (5.8 kg)
Dye	0.2 lbs (0.1 kg)
Total Active Solution	40 lbs (18.1 kg)
Total Neutralizer Mixture	100 lbs (45.4 kg)

Directions:

1. Mix the water, dye and solids.
2. Add the remaining ingredients and stir.
3. Store in neutralizer in polyethylene bags.

¹CAUTION: Alcohols are highly flammable. Keep neutralizer mixture away from heat or open flame. Propylene glycol (flash point at 210°F [99°C]) can be substituted for isopropyl alcohol to reduce the flammability problem that occurs with alcohol.

²Conventional urethane amine catalysts may be substituted for triethanolamine.

Major Spills

In the event of a major spill, a *State of Emergency* should be assumed to exist in the affected area. The declaration of a *State of Emergency* usually requires the involvement and close cooperation of various local emergency response services, such as police and fire units, etc. Thus, contingency arrangements and safe handling and decontamination procedures should be discussed in detail beforehand with emergency response personnel.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Note: In the event of a *major* spill (such as overturned tank trucks or tank cars, ruptured storage tanks, etc.), or a spill of *any* size about which there is doubt or uncertainty, alert local emergency response service units, then call CHEMTREC (see box) or The Dow Chemical Company Distribution Emergency/Response Center immediately in Freeport, TX (phone: 409-238-2112), or Midland, MI (phone: 517-636-4400). You may call these numbers at any time — day or night.

CHEMTREC

FOR CHEMICAL EMERGENCY
Spill, Leak, Fire, Exposure, or Accident
**CALL CHEMTREC
DAY OR NIGHT**

***800-424-9300**

Toll-free in the continental U.S.

*Add long-distance access number if required

483-7616 in District of Columbia

For calls originating outside the
Continental U.S.: 202-483-7616

— Washington, DC, Collect
ALL CALLS ARE RECORDED

CM^A

- All persons not properly equipped with protective clothing and appropriate respiratory devices should immediately leave the site of the spill and should remain upwind.
- Only experienced and properly equipped personnel should be authorized to attempt to isolate or contain the spill. Do *not* wash spilled isocyanates down a drain or into a river, creek, or other body of water.
- Keep all improperly equipped and unauthorized personnel away from the area of the spill.
- To contain the spill temporarily, to minimize vapor contamination of the air, and to "buy time" until the spill can be properly "diked" and the necessary decontamination materials assembled, cover the isocyanate with a coating of 3% protein (fire-fighting) foam. Most fire-fighting services have protein foams or similar foam systems. Also, the foam may have to be reapplied to the spill every 30 minutes until effective neutralizing materials can be obtained.

Note: Although, under certain circumstances, water is an acceptable decontaminant for isocyanates, mixing water and isocyanates in confined areas — even in small amounts — is hazardous. Protein and other water-based foam systems, therefore, should be used only in open areas. Also, be sure the equipment is producing a good quality foam before applying the mixture to the spill.

- **CAUTION:** Decontamination and clean-up of major spills can be a complex and hazardous operation, and all the details and operating procedures are not outlined above. A more extensive discussion of the subject, however, can be found in the International Isocyanate Institute Technical Bulletin No. 1, *Recommendations for the Handling of Toluene Diisocyanate (TDI)*. For a copy, write to the International Isocyanate Institute, Inc., 119 Cherry Hill Road, Parsippany, NJ 07054.

Cold Weather Spills

During cold weather, spilled or leaked VORANATE, T-80, Toluene Diisocyanates may freeze. Under these conditions, the use of ammonia and water will merely coat the material with an insoluble urea, stopping further reaction. It is essential, therefore, to use a solution that will not only dissolve the isocyanate, but will also form a liquid product during decontamination.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Ventilate the contaminated area. Open all doors and windows. To avoid inhalation of the vapors of either the isocyanate or the decontaminants used, workers should wear appropriate respiratory protective devices (e.g., a positive-pressure, self-contained breathing apparatus). See "Respirator Selection Guide," page 17.
- If any of the leaked or spilled isocyanate is still in liquid or absorbable form, cover it immediately with an absorbent material, such as sawdust, vermiculite, an all-purpose commercial oil absorbent, or sand. Use an amount greater than is estimated to be necessary to absorb the isocyanate.
- Carefully shovel the absorbent/isocyanate mixture into an open-top steel drum; cover, but do *not* make pressure tight. Remove to a safe site, away from the operating area, for neutralization.
- For that part of the spill or leak which is no longer liquid or absorbable, estimate the quantity spilled, and make up a mixture of approximately 50% isopropyl alcohol¹ and 50% 1,1,1-trichloroethane by volume, using the same volume of each solvent as the estimated volume of spilled isocyanate.
- Completely cover the spilled material with the alcohol/1,1,1-trichloroethane solution. Allow the solution to remain in place for at least one hour.

¹CAUTION: Alcohols are highly flammable. Keep neutralizer mixture away from heat or open flame.

- Cover the area with enough absorbent material to soak up all the liquid. Shovel this material into open-top steel containers, treat, and dispose of properly. Finally, if the temperature is above freezing, carefully wash down the contaminated area with copious amounts of water. (Special efforts should be made to prevent the spilled material from entering waterways or drains. If spilled material does enter waterways or drains, notify local authorities at once.) Also, thoroughly air or ventilate the decontaminated area to remove all traces of vapor.

- Note: The use of decontaminating solvents and other chemicals may introduce additional hazards of toxicity and flammability. Thus, such materials must be used with care and in strict compliance with the manufacturer's recommendations and precautions.

Pressurized Drums

Any drums seen to be in a pressurized state (i.e., misshapen due to the presence of carbon dioxide gas) should be covered immediately (e.g., with heavy tarpaulins), isolated, and watched carefully. These operations should be carried out only by competent and experienced personnel, wearing full emergency protective equipment. If, after careful inspection by a competent person, the drum is judged not to be in an explosive or immediately dangerous state, the pressure should be relieved either by carefully loosening the bung or, in severe cases, by puncturing with a long-handled device.

If the pressure is successfully relieved by simply loosening the bung, the product, if not contaminated or otherwise unusable, should be used immediately. If, however, the product is unusable, re-cover the drum with the tarpaulin and watch for signs

of further reaction. Then, when it is deemed safe, carefully dispose of both the product and drum. See "Disposal," page 13. If puncturing action is to be taken, be sure that all necessary materials and equipment for cleanup and decontamination are readily available. See the following sections on "Drum Decontamination" and "Disposal." Also, in cases of doubt or uncertainty, call The Dow Chemical Company Emergency/Response Center in Freeport, TX (phone: 409-238-2112).

Drum Decontamination

Read and follow carefully each of the safety recommendations and precautions listed below:

Isocyanates remaining after the emptying of drums may be decontaminated by the following procedures:

- Remove emptied drums from the work area to a well-ventilated location or to the out-of-doors.
- Remove all bungs and fill drums with water. Wear protective equipment and keep face away from bungholes while filling. Also, **DO NOT REINSTALL BUNGS.**
- Allow drums to stand undisturbed for 24 hours or until the residual TDI has been completely converted to solid urea. (Note: A dilute solution of aqueous ammonia or isopropyl alcohol may be added to the water to speed up the reaction.) Please refer to disposal method on the Material Safety Data Sheet and label.
- All drums should be scrapped. They should be drained and holed or crushed to render them totally unusable. Please refer to disposal method on the Material Safety Data Sheet and label.
- Dispose of drums and rinse fluid according to federal, state, and local regulations.

Disposal

Read and follow carefully each of the safety recommendations and precautions listed below:

- Only thoroughly trained and properly equipped persons should be permitted to participate in disposal operations.
- Keep waste isocyanate and waste polyols widely separated.
- Be certain that all disposal procedures are conducted in strict compliance with all applicable federal, state, and local regulations and ordinances. Isocyanate is listed as a hazardous waste (U223) and falls under Section 3001 of the Resource Conservation and Recovery Act (RCRA). Users of isocyanates should be aware of and follow the disposal provisions of that act, as well as other state and local environmental control regulations.

Other Polyurethane Chemicals

Each of these chemicals has its own profile of hazards and recommended safety precautions. It is essential, therefore, that users contact their suppliers for specific instruction on the safe handling, use, storage, and disposal of each of these products.

Polyols

Most polyols are very low in acute oral toxicity and are considered only mildly irritating to eyes and skin. However, despite their relatively innocuous characteristics (compared with those of the various isocyanates), they should be handled with appropriate caution and in strict accordance with the manufacturer's recommendations. *Skin and eye contact should be avoided.* Eye protection, such as safety glasses or their equivalent, should be worn whenever polyols are handled or used. Also, because polyols are frequently used with

chemicals that present an inhalation hazard, appropriate caution dictates thorough ventilation of all storage, handling, and manufacturing facilities.

Flash points for most polyols — including polyesters and polyethers — range from approximately 300° to 500°F (149° to 260°C). They can, therefore, be categorized as Class IIB combustible liquids, and, as such, do not present an unreasonable fire risk. However, it should be noted that, if exposed to sufficient heat and oxygen, *they will burn.* Fires involving polyols can be readily extinguished with water spray, foam, carbon dioxide, or dry chemical extinguishers. Furthermore, polyols, like most organic substances, could, if heated to decomposition in a confined location, generate sufficient volatile decomposition products to present an explosion risk. See supplier's literature.

Catalysts

Catalysts are used in polyurethane chemistry to control both the polymer and gas-formation reactions. They are generally metal salts (e.g., stannous octoate) or tertiary amines (e.g., triethylenediamine). Both types of catalysts can be toxic, can burn intact skin, and can induce sensitization. Eye contact can cause severe irritation, or possibly a burn. *With either type of catalyst, therefore, skin and eye contact must be avoided.* Follow the manufacturer's recommendations for safe handling.

Many liquid amine catalysts have Tag Open Cup flash points in the range of 20° to 115°F (-6° to 46°C) and are classified, depending upon the flash point, as flammable or combustible liquids. Because of their volatility and flammability, therefore, tertiary amines should be considered fire hazards.

Users are cautioned to secure specific handling and disposal information from their catalyst suppliers.

VORANATE T-80
Safe Handling and Storage

Blowing Agents

Halocarbon blowing agents are commonly used in polyurethane foam manufacture and represent a significant health hazard.

Commonly used halocarbons are listed below.

Although fluorocarbon blowing agents are generally considered nonflammable, they can, when heated to decomposition (as when drawn through a lit cigarette), generate quantities of highly toxic carbonyl chloride (phosgene) and carbonyl fluoride. Thus, smoking, open flames, or use of electrical equipment which might arc should be strictly prohibited. In addition, when confined and subjected to high temperatures, fluorocarbon blowing agents may also present a serious pressure hazard.

Like the fluorocarbons, methylene chloride has neither a flash point nor a fire point as reported by any of the standard test methods: Tag Open Cup, Tag Closed Cup, Cleveland Open Cup. However, the National Fire Protection Association reports flammable limits in pure oxygen between 15.5% and 66% by volume of MeCl_2 , and Dow laboratory data indicate flammable limits in air of 13-23% by volume at 77°F (25°C). However, when heated to decomposition, it too will produce a variety of hazardous and toxic materials, such as hydrochloric acid, chlorine, carbon dioxide, and carbon monoxide.

Methylene chloride has been shown to increase the rate of spontaneously occurring tumors in certain laboratory animals following lifetime inhalation exposures. However, methylene chloride is not believed to pose a measurable carcinogenic risk to man when handled as recommended.

The Occupational Safety and Health Administration (OSHA) Permissible Exposure Limit (PEL) for methylene chloride is currently 500 ppm, with an acceptable ceiling limit concentration at 1,000 ppm. The acceptable maximum peak above the acceptable ceiling concentration for any 8-hour shift is 2,000 ppm (as 5 minutes in any 2 hours). The TLV adopted by the American Conference of Governmental Industrial Hygienists (ACGIH) is 100 ppm (TWA). (This TWA value is on the 1987-88 intended change list, with a suggested value of 50 ppm.)

Users are urged to contact their suppliers for detailed information and instructions on the handling and disposal of these blowing agents.

Miscellaneous Products

Many other additives, such as surfactants, fillers, fire retardants, pigments, and dyes, are used in various polyurethane applications. Each has its own profile of hazards and recommended safety precautions. It is essential, therefore, that users contact their suppliers for specific instructions on the safe handling, use, storage, and disposal of each of these products.

Application Hazards of Polyurethane Foams

Polyurethane chemicals and foams, like many other industrial materials, can be hazardous if misused or improperly handled. However, when potential hazards are recognized and procedures for safe handling and storage are understood and practiced, polyurethane chemicals can be used safely.

Dust

Dust produced during the cutting and sawing of rigid polyurethane foam can cause irritation of the eyes, nose, and throat. In addition, laboratory studies with rats indicate that long-term respiratory difficulties may be caused by exposure to large quantities of finely ground polyurethane dust. It is imperative, therefore, that the generation and accumulation of dusts be carefully controlled during fabrication. If it is not feasible to install control devices, such as ventilators, then suitable equipment for respiratory and eye protection (such as dust masks, etc.) should be worn by all persons who may be exposed to such dusts.

In addition, finely divided airborne polyurethane dust can, under the proper conditions, produce a "dust explosion." Even settled dust can be made potentially explosive by relatively low order concussions which can raise the dust into airborne "clouds." To ensure safe working conditions, therefore, it is essential that workers exercise extreme care and practice good housekeeping in all polyurethane foam fabrication areas.

Note: VORANATE T-80 Toluene Diisocyanates are normally used in the manufacture of flexible and semi-flexible foams, which are cut by a slicing or scissoring action — procedures which are not likely to produce dust. In contrast, VORANATE Specialty Diisocyanates are generally used to produce rigid foams — materials which are usually cut by "sawing," a process which frequently produces a dust-like by-product.

Trichlorofluoromethane (R-11) 75°F (23°C) boiling point

Dichloromethane
(methylene chloride) 104°F (40°C) boiling point

Trichlorotrifluoroethane (R-113) 114°F (45°C) boiling point

CAUTION: Inhalation of high concentrations of the vapors of these products can be dangerous and may cause anesthesia and unconsciousness. Cases have also been cited showing that severe acute exposures to some fluorocarbons have caused cardiac arrhythmias, including ventricular fibrillation. Also, since halocarbon vapors are heavier than air (i.e., have a higher vapor density), they can, at high concentrations, accumulate in confined or low-lying areas, where they can displace the air or oxygen supply. Thus, adequate ventilation in all work areas is essential.

Combustibility

While product composition may vary, virtually all polyurethane foams will burn, often generating a variety of toxic gases and dense clouds of black smoke. *Even when fire retardant chemicals have been added to the formulation, the end product — under the right conditions of heat and oxygen supply — will burn.* It is essential, therefore, that urethane foam producers, fabricators, and end users know and understand the combustibility hazards and burning characteristics of the final foam product.

Products of Combustion

When polyurethane burns, many products of combustion are released. What and how much are released varies with product composition, fire conditions, oxygen level, and other factors. As in all organic fires, however, large quantities of carbon monoxide, as well as other products can be anticipated. In addition, large quantities of dense, dark smoke will be quickly generated, which may make it difficult to escape from the fire area.

Burning Characteristics

While many different tests are used to define the burning characteristics of polyurethane foam — some are small-scale tests useful only in comparing different products — none is comprehensive enough to define the hazards in all potential fire situations. In short, no two fires are the same. Fire conditions vary with room size, ventilation, available oxygen, fuel load, ignition sources, types of materials present, and other factors. Also, how a given polyurethane material will react to such varying conditions depends on the type of foam, the type of covering or flame barrier, the character and source of ignition, the proximity to ignition or heat, etc. It is unlikely, therefore, that all potential hazards can be defined for a fire condition. However, when used and stored with known limitations, polyurethane foams can be handled with minimal hazard.

Slabstock Foam Fires

The producer of polyurethane foam slabstock must be aware of *both* the exothermic (heat generating) nature of the polyurethane foam reaction and of the insulating properties of the foam produced. On occasion, extremely reactive systems and those which have been improperly formulated (i.e., "off-ratio" due to mechanical failure or errors in calculation) can develop "time-temperature" conditions in the bun center, which can result in autoignition. This can occur several hours after bun manufacture, when the material is largely unattended. It is important, therefore, that the heat generated in the center of a bun be safely dissipated through correct storage procedures.

Although the potential for fire exists, serious risk situations can usually be recognized during, or right after, foam manufacture, when protective action can be taken. Also, similar conditions may exist in other polyurethane applications, particularly in spraying operations, where large masses of polyurethane polymer may be formed. Safety precautions similar to those for slabstock should be carefully followed.

Read and follow carefully each of the safety recommendations and precautions listed below:

- Allow buns to cure and cool completely before stacking or storing. High air flow along the sides of fresh or hot buns may draw off reaction products and cause an influx of oxygen. This can cause rapid depletion of the antioxidant and could result in autoignition.
- Monitor bun temperatures at the center of the mass on a routine basis. This is particularly important with new formulations or new bun sizes.
- Design and construct slabstock pouring equipment to ensure "on-ratio" metering. Be sure equipment is kept carefully calibrated and in good working order.
- Cure bunstock in isolated areas equipped with effective fire detection equipment and sprinkler systems. Raw foam and

fabricated items should be stored indoors, away from fabricating operations, and should be protected by automatic sprinklers. Also, access aisles should be maintained between columns of stacked buns. See Factory Mutual System bulletin *Storage of Flexible Polyurethane* (8-178) for recommendations on stacking foam and installing sprinkler systems.

- Do *not* smoke in storage areas. Large quantities of stored polyurethane foams or products can be a tremendous fuel source in the event of a small fire. In laying out manufacturing and storage areas, therefore, designers should consider maximum storage area, possible source of ignition, and the location and effectiveness of fire and smoke detection equipment and sprinkler systems.

Construction Foam Fires

Polyurethane foam used for insulation can be a combustion hazard if left exposed or unprotected. For example, fire statistics show that most fires involving rigid polyurethane foam insulation have occurred in buildings under construction, where foam was left exposed or unprotected by an approved thermal barrier and was ignited by welding, cutting, or burning operations. Since VORANATE T-80 Toluene Diisocyanates are not normally used to make the type of rigid foam used in construction applications, see Dow bulletin *Safe Handling and Storage of VORANATE Specialty Isocyanates* (Form No. 109-546-82) for a full discussion of construction foam fires. Copies are available upon request from any Dow sales office or The Dow Chemical Company, Plastics Group, 2040 Willard H. Dow Center, Midland, MI 48674.

Cushion Foam Fires

Many of the fire deaths in the U.S. are attributed to the misuse of smoking materials. Such fires frequently start in upholstered furniture and bedding. As a consequence, various regulations have been passed or proposed requiring mattresses and other upholstered furniture to meet specified combustibility tests. Although these regulations vary, depending upon the intended use of the item to be tested, a proper combination of foam and covering material can now be selected to meet the standards established by these tests. It is essential, therefore, that manufacturers of polyurethane foam and foam products keep themselves fully informed of both the combustibility hazards associated with the use of polyurethane foams and of the changing regulations at the federal, state, and local levels.

For additional information on the fire hazard associated with flexible polyurethane foam, see the following bulletins: *Using Flexible Polyurethane Foam Safely* (U106) and *Fire Safety Guidelines on Flexible Polyurethane Foams Used in Upholstered Furniture and Bedding* (U111). Copies are available from The Society of the Plastics Industry, 355 Lexington Avenue, New York, NY 10017. Another bulletin, *The Toxicity for the Airborne Combustion Products of Polyurethane Foams*, which reviews current data on fire gas toxicity in polyurethane foam fires, is available from the International Isocyanate Institute, Inc. 119 Cherry Hill Road, Parsippany, NJ 07054.

Extinguishing Fires

Read and follow carefully each of the safety recommendations and precautions listed below:

- Know where all fire extinguishers are located and how to use them.
- For small polyurethane foam fires, use water, foam, dry chemicals, or carbon dioxide. Large fires of burning foam, however, should be drenched with large quantities of water from sprinklers or fire hoses.
- Because polyurethane foam is a good insulator, it is necessary to disperse and carefully inspect the foam after drenching to be certain that the fire has been completely extinguished.

- Hazards of rapid heat buildup, rapid flashover, and oxygen depletion exist when fighting fires in enclosed areas. Thus, fire fighters should be equipped with approved, positive-pressure, self-contained breathing apparatus and protective clothing when extinguishing polyurethane fires of any magnitude.

Fire Safety and Prevention

Read and follow carefully each of the safety recommendations and precautions listed below:

- All workers should be thoroughly familiar with the plant's fire emergency procedures.
- Workers should know where all exits are located. Also, access to exits should be kept clear and unobstructed.
- Smoking in areas where foams are made or stored should be strictly prohibited. No smoking areas should be clearly posted with large "NO SMOKING" signs.
- Welding torches, open flames, or other sources of high heat or ignition should be prohibited in areas where foams are made or stored.
- Keep work areas clean. Promptly and properly dispose of foam scraps, dust, and other waste materials.

Handling Precautions Summary

To minimize the hazards associated with the handling, use, and storage of polyurethane chemicals and polymers...

Read and follow carefully each of the safety recommendations and precautions listed below:

- Never work alone when using or handling reactive chemicals.
- Do *not* inhale vapors or mists. Be sure work areas are adequately ventilated to control vapors below employee exposure limits established by the Occupational Safety and Health Administration (OSHA)¹ and, when needed, have workers wear approved respiratory protective

devices, particularly when handling isocyanates, amines, or solvated adhesives. See "Respirator Selection Guide" on page 17.

- Avoid skin and eye contact with all formulation chemicals. Be sure all workers are properly equipped with protective clothing and eye protection.
- Candidates for employment where occupational exposure to isocyanates may occur should be examined for deficits in pulmonary function with particular emphasis on allergic history including asthma or other diseases that compromise pulmonary function. Employment in an isocyanate area may present a health risk to individuals with such abnormalities.
- Handle freshly polymerized parts with care. Be aware of the potential hazards of toxic vapors and of the heat of cure.
- Do *not* stack fresh polyurethane buns. Insulation of the heat can cause spontaneous combustion.
- Equip polyurethane foam storage areas with sprinkler systems.
- Keep adequate quantities of isocyanate neutralizer on hand for quick decontamination of work areas in the event of spills or leaks.
- Never expose isocyanate in containers to water, amines, or other reactive chemicals.
- Never expose polyurethane chemicals in closed containers to elevated temperatures.
- Never expose a polyurethane foam to an open flame or other high heat source.
- Always use proper dust handling equipment and dust filter masks when sawing or fabricating polyurethane foams or parts.

¹See "OSHA Safety and Health Standards (29 CFR 1910)." Copies are available from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

Industrial Hygiene

Hazard and Exposure Guidelines

The potential hazard of a given material is based on the degree of toxicity, the individual susceptibility of the user, and on the likelihood and level of exposure. Responsible users of chemical and industrial materials, therefore, must be concerned not only with the inherent acute and chronic toxicity of such materials, but also with the potential for exposure which may be encountered under specific use conditions. In general, the greater the toxicity, the greater must be the control over the level of exposure.

While there are potential hazards associated with such materials as catalysts and blowing agents, the primary hazard in polyurethane chemical applications is associated with the TDI component, and particularly with the inhalation of its vapors. As such, limits have been established regarding allowable TDI vapor concentrations in the work environment.

In the United States, vapor levels of TDI are to be controlled according to standards established by the Occupational Health and Safety Administration (OSHA). The OSHA Permissible Exposure Limit (PEL) for TDI is 0.02 ppm as a ceiling limit. The Dow Chemical Company has also set

0.02 ppm ceiling as its Industrial Hygiene Guide (IHG). Ceiling limit is defined as the maximum concentration which should not be exceeded during the exposure. Recent information presented at the International Isocyanate Institute's Symposium on Diisocyanates (Pittsburgh, 1987) indicates that allergic sensitization results from even brief exposure to high concentrations of TDI. Exposures to low concentrations below the OSHA PEL of 0.02 ppm are not likely to result in allergic sensitization. This information stresses the importance of controlling vapor levels below the ceiling limit. Current paper tape monitoring methodologies measure concentrations of TDI with sampling periods ranging from 0.5 to 9 minutes. However, it is an acceptable industrial hygiene practice to assess exposures to materials with ceiling limits using sample times of up to 15 minutes if instantaneous (real time) monitoring is not feasible.

Other advisory groups have also set more conservative guidelines. In 1983, the American Conference of Governmental Industrial Hygienists (ACGIH) adopted a Threshold Limit Value (TLV) for TDI of 0.005 ppm as an 8-hour time-weighted average (TWA) with 0.02 ppm as the Short-Term Exposure Limit (STEL). The TWA is the concentration to which it is believed nearly all workers may be repeatedly exposed for 8

hours a day, 40 hours a week, without adverse effect. ACGIH defines a STEL as a 15-minute TWA exposure which should not be exceeded at any time during a work day even if the 8-hour TWA is within the TLV. Other restraints of a STEL are (a) the STEL should not be longer than 15 minutes, (b) the STEL should not be repeated more than four times per day and (c) there should be at least 60 minutes between successive exposures at the STEL.

Although the National Institute for Occupational Safety and Health (NIOSH) has published two criteria documents applicable to occupational exposures to TDI, OSHA had taken no formal action on NIOSH's recommendations. The first criteria document (1973) recommended that exposure to TDI be controlled to 0.005 ppm as an 8-hour TWA or to 0.02 ppm for any 20-minute period. The second criteria document (1978) recommended that exposures to certain diisocyanates (including TDI) be controlled to a TWA limit of 0.005 ppm for a 10-hour workshift, 40-hour workweek, and a ceiling limit of 0.02 ppm for a 10-minute sampling period. Their rationale was that this type of control would afford employees protection from respiratory effects including direct irritation, sensitization, and chronic decrease in pulmonary function.

Table 3 — Respirator Selection Guide for Protection Against Diisocyanate Vapors¹

Concentration	Respirator Type (Approved Under Provision of 30 CFR 11 ²)
Less than or equal to 1,000 ppb	Type C supplied-air respirator with full facepiece operated in pressure-demand or other positive pressure mode or with full facepiece, helmet, or hood operated in continuous-flow mode.
Greater than 1,000 ppb	(1) Self-contained breathing apparatus with full facepiece operated in pressure-demand or other positive pressure mode. (2) Combination respirator including Type C supplied-air respirator with full facepiece operated in pressure-demand or other positive pressure model with auxiliary self-contained breathing apparatus operated in pressure-demand or other positive pressure mode.
Firefighting and Emergency	Self-contained breathing apparatus with full facepiece, operated in pressure-demand or other positive pressure mode.

¹Source: DHEW (NIOSH) Publication #78-215

²Use of supplied-air suits may be necessary to prevent skin contact during exposure at high concentrations of airborne diisocyanates.

Further information can be obtained by requesting the NIOSH Criteria Document for Diisocyanates (DEHW Publication No. 78-215) from the National Institute for Occupational Safety and Health, 944 Chestnut Ridge Road, Morgantown, WV 26505.

It is important to remember that while these values represent current thinking and are believed to be conservative, they offer no guarantee of absolute safety. It is imperative that personnel working with TDI understand fully the hazards associated with its use and are familiar with those procedures which have been designed to minimize the hazards involved. Exposure guidelines are reviewed regularly and changed when new information dictates a need. Users of these chemicals need to keep fully informed on the most current guidelines and regulations.

Read and follow carefully each of the safety recommendations and precautions listed below:

- All employees must be instructed and periodically retrained in the use of all protective and emergency equipment, as well as in preventive procedures. Important to any safety program is thorough worker education. In short, the best planned procedures do no good if they are not understood and followed. Similarly, the best safety equipment is useless if it is not properly used and maintained. The use of personal protective equipment must comply with OSHA regulations 29, Code of Federal Regulations (CFR) 1910.132 to 1910.140.
- Proper respiratory protective equipment should be readily available and in good working order. For nonroutine operations, or where vapor levels cannot be controlled by ventilation alone, all personnel should use appropriate respiratory protective devices. Also, only those devices approved by the National Institute for Occupational Safety and Health (NIOSH) and the Mine Safety and Health Administration (MSHA) should be used.
- Regularly inspect and repair exhaust and other ventilating equipment. Also, work area atmospheres should be tested periodically by trained industrial hygienists to be sure that airborne TDI vapors are being controlled to acceptable levels. TDI and other toxic vapor levels in the work environment are best controlled by properly designed and maintained process and exhaust equipment. Combined with safe work procedures, properly designed equipment in good working order can maintain vapor levels within acceptable limits. **WARNING:** Tests have shown that the least detectable odor level of TDI is approximately 0.2-0.4 ppm. Because this odor threshold occurs at levels significantly higher than allowable exposure concentrations, vapor levels *must* be monitored using equipment specifically designed for that purpose. Instruments designed for TDI personal and area monitoring are available from GMD Systems Inc., MDA Scientific, Inc., and National Draeger, Inc. (see Appendix A for addresses). For additional information, contact The Dow Chemical Company, Industrial Hygiene Office (phone: 517-636-0860).
- Prevent contact with TDI and other polyurethane chemicals. Skin and eye contact with TDI and other polyurethane chemicals may result in injury and, in some cases, in sensitization. It is essential, therefore, that operating and ventilating equipment be properly designed and maintained, and that all procedures for the safe handling, use, and storage of polyurethane chemicals be fully understood and followed. Also, protective clothing, gloves, boots, and chemical goggles or face shields *must* be worn whenever isocyanates are handled, stored, or used, or whenever there is *any* possibility of exposure.
- Eyewash fountains and safety showers should be installed and kept in working condition in areas where contact with TDI can occur. It is important that the number and location of such units be designed to serve both individual and multiple-employee exposures.
- Employees should have medical surveillance, designed to detect any evidence of adverse effects due to exposure to TDI.

Health Hazards

Inhalation

Toluene diisocyanate vapors are irritating to the mucous membranes of the upper and lower respiratory tracts. Even very brief exposures to these vapors may cause irritation and difficult or labored breathing, including a "burning" throat, deep coughing, and choking, as well as nausea, vomiting, and abdominal pain. Also, inhalation of isocyanate vapors may cause changes in lung function or chronic lung effects. Furthermore, exposure to isocyanate vapors may cause sensitization or hypersensitivity which on subsequent exposure, even to concentrations below 0.02 ppm, may result in severe allergic respiratory reactions.

CAUTION: Inhalation of vapors of heated isocyanates can be extremely hazardous, not only because high vapor concentrations are formed, but also because condensation may form airborne droplets. An approved respiratory protective device *must* be worn, therefore, whenever there is *any* possibility of exposure to unknown concentrations of vapors. See "Appendix B," page 39, for a list of manufacturers and suppliers of approved respiratory protective equipment.

Skin Contact

Repeated or prolonged contact with TDI may cause redness, swelling, blistering, and burns. Also, direct contact may produce sensitization (contact dermatitis as well as respiratory sensitization). Therefore, any contact with the spray, vapor, or liquid *must* be prevented. Protective clothing, including rubber or plastic aprons, rubber gloves and footwear, chemical goggles or faceshields, etc., should be worn whenever there is *any* possibility of direct contact with isocyanates. Also, safety showers should be installed, and kept in working condition, in and near all work areas where TDI is used.

Eye Contact

While brief eye contact with low concentrations of TDI vapor may cause only mild tearing or a slight burning sensation, contact with high concentrations of vapors or mists may cause severe pain and irritation. Furthermore, direct contact with TDI liquid may be extremely painful and may cause both severe irritation and permanent injury. *Chemical workers' goggles should be worn whenever TDI is handled, stored, or used, or whenever there is any possibility of direct contact with TDI liquid or mist.* In the event of contact, immediate decontamination with water will assist in preventing injury. Thus, eye baths should be installed, and kept in working condition, in all work areas where TDI is used.

Ingestion

Although VORANATE T-80 Toluene Diisocyanates have a low level of acute oral toxicity (e.g., LD₅₀ rats >4g/kg), they can irritate or burn the mucous membranes of the mouth, esophagus, and stomach. While accidental ingestion in an industrial environment is highly improbable, it is possible. Therefore, foodstuffs should not be prepared or consumed where TDI is used, handled, or stored. Also, in the event of accidental ingestion, workers should be prepared to administer emergency first aid.

A current Material Safety Data Sheet (MSDS) must be obtained and reviewed before any TDI product is used. Copies are available to customers from our toll-free number: 1-800-238-CHEM. Copies are also available from any Dow sales office or The Dow Chemical Company, Plastics Group, 2040 Willard H. Dow Center, Midland, MI 48674. Current MSDSs must also be obtained from suppliers of other products prior to handling or formulating.

Chronic Toxicity

Recently, both the National Toxicology Program (NTP) and the International Agency for Research on Cancer (IARC) designated TDI as a potential carcinogen. Both agencies based their conclusions primarily on the results of a recent NTP study which reports increased numbers of tumors in rats and mice dosed orally with TDI. The agencies accept this as a valid animal study; however, a number of deficiencies have been cited which may compromise its validity. In addition, results of a chronic inhalation study contradict the findings of the NTP study, and are deemed more relevant to the exposures experienced in occupational settings. This inhalation study, contracted by the International Isocyanate Institute, reports no increase in tumors in rats and mice exposed to TDI for their lifetime.

At this time it is not believed that TDI represents a significant cancer hazard when atmospheric levels are maintained below the recommended exposure guidelines. Based on currently available data from lifetime inhalation studies in rats and mice, Dow recommends the OSHA standard of 0.02 ppm as a ceiling limit for TDI.

First Aid

All employees working in areas where contact with isocyanate is possible should be thoroughly trained in the administration of appropriate emergency first aid. Experience has demonstrated that prompt administration of such aid can be important in minimizing the possible adverse effects of accidental exposure. CAUTION: First aid is "emergency treatment" only, and medical attention from a qualified physician should be provided as soon as possible.

Inhalation

Promptly move the affected person away from the contaminated area and to fresh air. Quickly remove all contaminated clothing. Keep the affected person calm and

warm, but not hot. If breathing stops, administer mouth-to-mouth resuscitation. Immediately transport to a medical facility and inform medical personnel about the nature and extent of the exposure. Never attempt to give anything by mouth to an unconscious person.

Skin Contact

In the event of direct contact with the skin, immediately get under a safety shower. Immediately remove all clothing and shoes while under the shower. Thoroughly wash the affected skin, using copious amounts of water. If necessary (i.e., in the event of burned or damaged skin, or if redness or irritation persists), seek medical attention. Contaminated clothing should *not* be worn again until laundered. Shoes, belts, watchbands, and other leather items should be destroyed.

Eye Contact

If VORANATE T-80 Toluene Diisocyanates contact the eyes, decontaminate immediately. Irrigate the eyes immediately and continuously with water *for at least 15 minutes. Seek medical attention at once!* For more effective flushing of the eyes, use the fingers to spread apart and hold open the eyelids. The eyes should then be frequently "rolled" or moved in all directions.

Ingestion

In the event VORANATE T-80 Toluene Diisocyanates are ingested, have the affected person drink large amounts of water or milk, if available. Do *not*, however, encourage or induce vomiting! Immediately transport to a medical facility and inform medical personnel about the nature and extent of the exposure.

VORANATE T-80
Safe Handling and Storage

Note to Physician

Toluene diisocyanate (TDI), the principal active ingredient in VORANATE T-80 Toluene Diisocyanates, is a highly reactive and potentially hazardous material which can adversely affect or injure the eyes, the skin, and both the respiratory and digestive tracts, depending upon the avenue and extent of exposure. For additional medical information, contact The Dow Chemical Company emergency phone number: 517-636-4400, anytime.

Inhalation

Inhalation of vapors or mists of TDI can severely irritate the mucous membranes of the nose, throat, bronchi, and lungs and may cause respiratory sensitization. Over-exposure may produce a variety of symptoms, a number of which may not manifest themselves for several hours. These include headaches, irritation of the upper and lower respiratory tract, tightness of the chest (including difficulty in breathing), deep coughing, and choking. Some individuals may also experience attacks of sinusitis, bronchitis, bronchial asthma, or other severe respiratory distress.

Treatment:

Patients should be kept calm and warm, but not hot. The severity of respiratory distress will determine the need for oxygen.

Skin

Although it is not likely to be absorbed in acutely toxic amounts, repeated or prolonged contact with TDI may cause irritation, redness, swelling, blistering, or burns. Also, direct contact may produce skin sensitization (e.g., contact dermatitis) and allergic response.

Treatment:

In case of skin contact, immediately irrigate skin with running water for at least 15 minutes. Remove all contaminated clothing. Treat blisters and/or burns as you would thermal burns. Also, if skin sensitization or dermatitis develops, treat as you would any contact dermatitis.

Eyes

The effects of exposure to liquid TDI may vary from slight irritation (with possible tearing and a burning sensation) to impairment of vision.

Treatment:

While prompt and thorough washing may mitigate the effects of the initial exposure, provide further medical treatment as appropriate.

Ingestion

Although TDI has a low level of acute oral toxicity, undiluted TDI is corrosive and can severely irritate or burn the mucous membranes of the mouth, esophagus, and stomach. Such injury may result in stricture or stenosis.

Treatment:

An initial or "first aid" response calls for the administration of large amounts of water or milk. Do *not*, however, encourage or induce vomiting. If gastric lavage is performed, suggest endotracheal and/or esophagoscopy control. No specific antidote is known. Treatment should be based on the judgment of the physician and individual patient response.

PART TWO

Shipment,
Handling,
and
Storage

Shipment and Handling

General Specifications for Tank Trucks and Tank Cars

VORANATE T-80 Toluene Diisocyanates are classified by the Department of Transportation as Class B Poisons, and are, therefore, shipped in specially designed tank trucks and tank cars. Table 4 and Figures 4 and 5 contain general specifications for vehicles used by The Dow Chemical Company for the bulk shipment of VORANATE T-80 Toluene Diisocyanates.

Unloading Procedures

VORANATE T-80 Toluene Diisocyanates are classified as hazardous materials under the Department of Transportation's "Hazardous Materials Regulations." Thus, the unloading of tank trucks and tank cars must be done in strict accordance with those regulations. Some, but not all, of those regulations are given below.

Tank Trucks

VORANATE T-80 Toluene Diisocyanates are shipped in pressurized and insulated stainless steel tank trucks, equipped for bottom unloading only. Dow recommends that only DOT specification MC 304 or 307 tank trucks be used. Only properly trained and equipped personnel should be permitted to unload tank trucks. Operators should wear an appropriate respiratory protective device and impervious clothing, footwear, and gloves.

Table 4 — General Specifications (Tank Trucks and Tank Cars)

Details	Tank Trucks	Tank Cars
Capacity, Gallons	6,000	10,800 17,300 ¹
Capacity, Approximate Weight, lbs	42,000	104,000 172,000
Construction Material	Stainless Steel	Baked Phenolic Lined
Temperature Gauge	Yes	Thermowell
Pressure Gauge	Yes	No
Nitrogen Pad during Shipping	Yes	Yes
Nitrogen Pad Connection Size, Type	3/4", QC ¹	2", Flange
Top Unloading	No	Yes
Top Unloading Connection Size, Type	None	2", Flange
Bottom Unloading	Yes	No
Bottom Unloading Connection Size, Type	3", MPT ²	None
Unloading Pressure, psig	25 max	25 max
Steam Plates	Yes	Yes
Steam Plate Connection Size, Type	3/4", MPT	2", Screw
Steam Pressure, psig	15	25


¹Quick Connect

²Male pipe thread. Can be reduced to 2" with adapters.

Read and follow carefully each of the safety recommendations and precautions listed below:

1. Before attempting to use the following procedure, operators should be thoroughly familiar with the potential hazards associated with the handling and storage of TDI.
2. Position the trailer as level as possible and block the wheels.
3. Carefully check the storage tank into which the contents of the truck are to be unloaded to be certain that it contains the intended VORANATE T-80 Toluene Diisocyanate product and *not* some other chemical or compound. Also, check the gauge on the storage tank to be sure that there is sufficient room to receive the entire contents of the tank truck.
4. Check all "product identification" or "bulk" tags (usually attached to product outlets, valves or seals) to be certain that the product being unloaded is, in fact, the intended VORANATE T-80 Toluene Diisocyanate.
5. Check the temperature of the contents. The temperature must be above 60°F (16°C) when the trailer is unloaded.

Figure 4 — Tank Trucks



6. If heating is required, attach a 25 psi steam supply to the heating coil inlet connection. For better control of the heating process, use a steam pressure of 15 psi. Attach a steam trap, designed for the steam pressure available, to the heating coil outlet connection. Internal coils are not advised because of severe effects due to possible water contamination of the product. Allow the contents to warm until the temperature is at least 68°F (20°C). When the temperature reaches 68°F (20°C), turn off the steam and disconnect the lines. To prevent the heating coils from freezing during cold weather, be sure to drain them or "blow them out." CAUTION: Carefully watch the thermometer during heating. Do *not* allow the temperature to rise above 104°F (40°C). See "Temperature Control," page 8.

7. Attach the unloading line. The line should be clean, dry, and preferably made of flexible metal or either Teflon¹ fluorocarbon or Viton¹ fluoroelastomer hose which can safely withstand unloading pressures.

8. Connect the dry purge gas (preferably nitrogen) line to the tank truck. This line should have a pressure gauge, a safety valve set at 30 psig, and a pressure regulator set at 25 psig.

9. Draw off a sample of the contents for analysis. A sample of the contents may be obtained by connecting stainless steel tubing to the sample connection. Flush the sample connection by drawing off at least one gallon of product into a clean, dry container. The sample to be analyzed may now be drawn off into another clean, dry container of whatever size is necessary for testing. **WARNING:** Do *not* breathe vapors. Wear proper protective equipment, including an approved respiratory protective device.

10a. *If the contents are to be unloaded by purge gas pressure alone*, the storage tank should be fitted with a vent scrubber. This will prevent vapors from being vented into the atmosphere during unloading. (CAUTION: Do *not* exceed 25 psig purge gas pressure to unload the tank truck.) When the tank truck is empty, the pressure gauge will show a drop in pressure. Close the valve at the storage tank connection *first*. Then close the truck unloading valve.

10b. *If the contents are to be unloaded by pump*, either a vapor line connecting the storage tank vent to the tank truck should be installed (closed loop) or a low-pressure, replenishable gas pad must be placed on the tank truck. If a gas pad is used, install a vent scrubber on the storage tank vent. These precautions will not only prevent isocyanate vapors from being vented to the atmosphere, but will prevent a vacuum from being pulled on the tank truck during unloading. (CAUTION: Do *not* use a closed loop system unless the dead air space in the storage tank is free of moisture; i.e., -40°F (-40°C) dew point. Also, connection hoses should be purged with dry air or nitrogen before hookup.) When the trailer is empty, allow the unloading hose to vent down to the storage tank. Be sure to close the valve at the storage tank connection *first*. Then close the tank truck unloading valve.

11. Shut off the purge gas to the tank truck. Close the tank truck purge gas valve and disconnect the purge gas line. If a closed loop system was used in conjunction with pump unloading, close the tank truck connection valve and the tank vent valve. Then disconnect the hose connecting the two. All connection hoses should now be cleaned, dried, and capped for storage.

CAUTION: Unloading must be *closely monitored*, particularly if there is no automatic "cut off" in the unloading line. For example, if gas flow is allowed to continue after unloading, the gas flowing into the storage tank could rapidly increase internal pressure. This could cause serious structural damage to the storage vessel.

The tank truck should *not* be cleaned by the customer, nor should the manway be opened for inspection. The cleaning and inspection of the tank truck should be handled by the shipper under carefully controlled conditions, designed to safeguard personnel and equipment. **WARNING:** Under no circumstances should personnel enter any "empty" tank truck.

Tank Cars

VORANATE T-80 Toluene Diisocyanates are shipped in insulated, baked-phenolic-lined tank cars, equipped with external heating coils and a safety relief valve set for 75 psi. Tank cars from The Dow Chemical Company can be unloaded only from the top. Also, only properly trained and equipped personnel are permitted to unload tank cars. Operators should wear an approved respiratory protective device, eye protection, and protective clothing, footwear, and gloves.

Read and follow carefully each of the safety recommendations and precautions listed below:

1. Before attempting to use the following procedure, operators should be thoroughly familiar with the hazards associated with the handling and storage of VORANATE T-80 Toluene Diisocyanates. Also, see page 25 for a diagrammatic drawing of a typical tank car. (Note: All letter references refer to this drawing.)
2. Verify that the proper car is being unloaded. Carefully check the car number, product identification, and commodity stenciling against the bill of lading or other appropriate document. Also, sample the contents to be sure that the material is indeed a VORANATE T-80 Toluene Diisocyanate. Product identification and information tags are attached to the metal seal.
3. Position the car on the selected siding; then set the brakes and block the wheels.

¹Trademarks and products of E.I. du Pont de Nemours Co., Inc.


4. Position caution signs on the track or car in such a way as to give adequate warning to persons approaching the car from the open end(s) of the siding. CAUTION: The signs should *not* be removed until the car has been unloaded and disconnected from the discharge connection. Code of Federal Regulations, Title 49, "Hazardous Materials Regulations of the Department of Transportation," Section 174.67, "Tank Car Unloading," states, in part, that:

The signs must be of metal or other comparable material, at least 12 inches high by 15 inches wide in size, and bear the words, "STOP — Tank Car Connected," or "STOP — Men at Work," the word "STOP" being in letters at least 4 inches high and the other words in letters at least 2 inches high. The letters must be white on a blue background.

In addition to these mandatory regulations, The Dow Chemical Company recommends that the switch(es) on the open end(s) of the siding be provided with locks, or that derails be placed on the track at least 50 feet from the end(s) of the car. This should effectively prevent the entry of other cars into the siding where the isocyanate is being unloaded. CAUTION: In the event derails are used, be sure to attach a signal flag to the track to indicate that the derail is in position. Also, attach a signal light to the flag at night.

Figure 5 — Tank Car

Note: On some 17,000-gallon DOWX series cars there is a variation in the dome valving configuration. The diagram below shows the normal configuration. However, in some cars the positions of A (the gauging device) and C (the 75# safety valve) are reversed.



5. Climb the ladder to the platform area on top of the car. All unloading apparatus on Dow tank cars is located in the manway bonnet in the center of the platform. Remove the seal from the latch pin and open the bonnet dome. When the cover is open, check to see that all valves are in the closed position.
6. Check the temperature of the tank car by removing the $\frac{3}{4}$ -inch cap from the thermowell (B) and inserting a thermometer approximately 24 inches for 15-20 minutes. The temperature of the contents must be above 60°F (16°C) when the car is unloaded.
7. Should heating be necessary, remove the cover from the magnetic gauge (A) and raise the gauge rod to where the magnet in the end of the rod engages the magnet on the float. The rod is calibrated in $\frac{1}{4}$ -inch increments and should read between 4 and 7 inches. Next, attach a steam hose to the steam inlet connection located on the bottom of the car. Attach a steam trap, designed for the steam pressure available, to the heating coil outlet connection. For greater control of the heating process — that is, to avoid hot spots and product deterioration — use a steam pressure of 25 lbs or less. Also carefully monitor the outage to be sure that expansion does not fill the car "liquid full" and cause it to "pressure relieve" through the safety valve. Finally, be sure to monitor the pressure on the tank car during heating. Do *not* allow pressure to go beyond 30 psig. Also, dry nitrogen is recommended for padding.
8. Allow the contents to warm until the temperature is at 68°F (20°C). When the temperature reaches 68°F (20°C), turn off the steam, disconnect the lines, and allow the heater coils to drain. CAUTION: Carefully watch the thermometer during heating. Do *not* allow the temperature to rise above 104°F (40°C).
9. Connect flanges holding vents or vapor lines (E) as follows:
 - a. Use the proper wrenches to remove the bolts. Both the vent and load/unload valves are equipped with 2-inch ASA Series 15 flanges with four bolts in a 4 $\frac{3}{4}$ -inch bolt circle. Although these are combination flanges to which a screw-type hookup may be made (e.g., by removing the 2-inch solid plug instead of the flange), it is strongly recommended that a flanged connection be used. Use an open-end wrench of proper size to hold the nut on the bottom of the flange and a box-end or socket wrench to turn the bolt on the top side of the flange. Pipe or other adjustable wrenches are *not* recommended. The bolts away from the operator should be removed *first*.
 - b. Carefully connect the purge line to the valve by reinstalling the gasket and bolts.
 - c. Tighten opposite bolts with equal pressure until all bolts are uniformly tight.
 - d. Equip the purge line connection with a pressure gauge regulated to a maximum pressure of 40 psig.
10. If desired, a sample of the contents may be drawn off through the sample valve (F), which is a $\frac{1}{4}$ -inch needle valve equipped with standard pipe threads. (Note: If a sample is desired from an unpressured car, use 3 to 4 lbs of purge gas pressure.) The sample valve is attached to a sample line, which is equipped with an excess flow valve. Should the excess flow valve close, turn off the sample valve. Wait approximately one minute; then reopen the sample valve. If the excess flow valve does not reopen, it may be necessary to rap with a ball-peen hammer against the manway cover plate near the sample valve to cause the ball in the excess flow valve to drop into the open position. A good preventive practice against excess flow valve closure is to draw the sample very slowly. **WARNING:** Do *not* breathe vapors. Wear proper protective equipment, including an approved respiratory protective device.
11. Attach the unloading line(s) (which should be clean, dry, and preferably made of flexible metal or either Teflon fluorocarbon or Viton fluoroelastomer hose which can safely withstand unloading pressures) to the unloading valve(s) (D and G). Follow the procedure outlined under Step 9. After proper attachment of the unloading line(s) slowly open the unloading valve(s) until discharge line(s) is liquid full.
12. Pressure on the car may now be increased to discharge the product. Be sure, however, that the amount of pressure is appropriate to the unloading method used (i.e., by purge gas pressure or pump). If the contents are to be unloaded by purge gas pressure alone, the storage tank should be fitted with a vent scrubber. Also, storage tank pressure should be carefully controlled and monitored during the unloading operation.
13. When the tank car is empty, the unloading lines should be blown clear of liquid and blocked in before being disconnected. See Step 14d. There are a number of ways to determine when the tank car is empty. For example, a rapid drop in pressure on the car would indicate that the liquid is gone and that the gas is blowing out through the unloading line. The amount of product received into the storage tank should also indicate whether or not the tank car is empty. CAUTION: Do *not* use the Magnetic Gauging Device to determine if the car is empty. This device only extends 60 inches into the car; the car itself is 102 inches in diameter. Also, do *not* breathe vapors. Wear proper protective equipment, including an approved respiratory protective device, when disconnecting the lines.



h. If steam is used, do not replace inlet and outlet plugs on the heater coils. This will allow drainage.

15. Code of Federal Regulations (CFR), Title 49, "Hazardous Materials Regulations," Section 174.69, "Removal of Placards and Car Certificates After Unloading," states, in part, that:

When lading requiring placards or car certificates is removed from a rail car other than a tank car, each placard and car certificate must be removed by the person unloading the car. For a tank car which contained a hazardous material, the person responsible for removing the lading must assure, in accordance with the provisions of Section 172.510(c) of this subchapter, that the tank car is properly placarded for any residue which remains in the tank car.

Section 172.510(c), "Special Placarding Provisions: Rail," states, in part that:

Each tank car containing the residue of a hazardous material must be placarded with the appropriate RESIDUE placards, as required in Section 172.525 and paragraph (a) of this section. The RESIDUE placard must correspond to the placard that was required for the material the tank car contained when loaded, unless the tank car —

(1) Is reloaded with a material requiring no placards or different placards; or

(2) Is sufficiently cleaned of residue and purged of vapor to remove any potential hazard.

Section 172.525, "Standard Requirements for the RESIDUE Placard," states, in part, that:

(a) Each RESIDUE placard must be as follows:

(1) The triangle at the bottom of the placard must be black. The word "RESIDUE" must be white.

14. Once the tank car is empty, return all valves and connections to their original condition:

a. Remove the thermometer from the thermometer and replace the dust cap.

b. Completely lower the Magnetic Gauging Device and replace the dust cap.

c. Close the sample valve and replace the 1/4-inch plug.

d. Liquid unloading lines should be blown dry and disconnected in accordance with the following sequence: First, blow the line to the storage tank; then close off the valve to the storage tank. Second, open the unloading valve on the tank car and blow any material left in the line back into the car. Next, determine the amount of pressure remaining in the car. If it is below 10 psig, continue flow of purge gas until pressure in the car reaches a minimum of 10 psig. (Note: Do not allow pressure to exceed 40 psig.) Now close the tank car valve, bleed off any pressure left in the unloading line, and remove the bolts. To prevent residual material or pressure from blowing toward the operator, be sure to remove the bolts away from the operator first. Finally, replace the gasket and flange on the unloading valve. Alternately tighten opposite bolts until all bolts are uniformly tight and a leak-proof seal has been made.

e. Remove the purge gas line and replace the gasket and flange.

f. Close dome cover and replace latch pin. It is recommended that the pin be sealed to preclude its removal during transit.

g. If any car defects are found, note them on the standard "Bad Order" tag and attach the tag to the dome cover latch pin.

(2) The midsection and upper triangle on the RESIDUE placard must be as specified in Appendix B to this part and as illustrated on the POISON — RESIDUE placard which, except for size and color, must be as follows:

(b) The top part of each RESIDUE placard must be as specified in Appendix B to this part and as shown in paragraph (b) of this section and may be —

(1) A separate placard.

(2) On the reverse side of a placard, or

(3) A composite made by covering the bottom triangle of the appropriate placard with a black triangle bearing the word "RESIDUE" in white letters.

16. Remove warning, open derails, unlock switches, etc. Release hand brakes and remove chocks from wheels. If an unloading rack was used for entrance to the dome platform, be sure that all parts of the rack are removed and re-located far enough away from the car to conform to AAR specified clearance for entry of the rail crew for switching operations.
17. Complete all final paperwork (e.g., "Empty Return Instructions"). After all forms have been completed and the proper carrier endorsements obtained, send the various copies to the locations designated in the instructions.

Unloading must be *closely monitored*, particularly if there is no automatic "cut off" in the unloading line. For example, if gas flow is allowed to continue after unloading, the gas flowing into the storage tank could rapidly increase internal pressure. This could cause serious structural damage to the storage vessel.

Drums¹

VORANATE T-80 Toluene Diisocyanates are shipped in DOT specification phenolic-lined steel drums or high-density polyethylene drums that are authorized for TDI. Drums are equipped with two bungs on the top.

¹Currently, in the U.S.A., VORANATE T-80 Toluene Diisocyanates are available only in bulk quantities (i.e., in tank truck or tank car shipments).

Read and follow carefully each of the safety recommendations and precautions listed below:

1. Closely examine each shipment for damaged drums. Drums should be handled and unloaded carefully to prevent damage. If damaged drums are found, they should be closely inspected for leaks. Leaking drums should be removed to a well-ventilated area and the contents transferred to other suitable containers. The empty drums should be decontaminated (see page 13) and then holed or crushed so they cannot be reused.
2. Drums may be unloaded with conventional stainless steel drum pumps. To prevent collapse of the drum during unloading, equip the drum vent with a dry air or dry nitrogen breather. This attachment will also prevent moisture contamination of the contents. When not in use, pump lines should be protected from moisture by fitting a plug or cap into the open end. Portable pumps, lines, and fittings, should be carefully rinsed, dried, and stored in a dry location. See "Moisture Control," page 7. CAUTION: Operators engaged in handling, opening, unloading, and closing drums should be completely familiar with the hazards associated with isocyanates and should be properly equipped with protective clothing and an approved respiratory protective device.

Storage

Drum Storage

Whenever possible, drums containing VORANATE T-80 Toluene Diisocyanates should be stored indoors. During cold weather, the temperature in storage areas should be kept above 68°F (20°C). If drums are received frozen, be sure the contents are completely thawed and mixed before using. Thawing may be accomplished by allowing the drums to sit in a warm storage area or by using a drum heater. CAUTION: Do *not* heat the contents above 104°F (40°C) or the drum wall above 175°F (79.5°C). Overheating may cause expansion of the contents, homopolymerization, and the subsequent formation of carbon dioxide, which can seriously weaken or completely rupture a drum. See "Temperature Control," page 8. During warm weather, drums may be stored outdoors. However, drums should be stored in such a manner as to prevent water from collecting on the tops. This may be accomplished by storing the drums under a cover or by stacking them on their sides.

Bulk Storage

A properly designed bulk storage system for VORANATE T-80 Toluene Diisocyanates must:

- Permit safe handling of the material,
- Provide both moisture and temperature control,
- Prevent contamination of the product, and
- Minimize the hazards of combustibility.

Before attempting to construct such a system, therefore, it is essential that designers familiarize themselves with the hazards, safety recommendations, and precautions associated with the handling and storage of VORANATE T-80 Toluene Diisocyanates. A genuinely practical design must not only include a physical layout of the facilities and equipment, but must also include a plan for personnel safety in all areas of the operation. In short, the establishment of safe work procedures must be an integral part of *any* bulk storage system. In addition, designers must consider all applicable insurance requirements, as well as governmental codes and regulations, and

should consult with all appropriate state and local agencies during each stage of planning and construction.

The equipment described below is suitable for use in bulk storage systems for VORANATE T-80 Toluene Diisocyanates. Such items, however, are merely components of typical systems and must not be considered a finished design. Also, other equipment similar to the items listed can be tested for performance and may give equally good results. See the lists of "Equipment Manufacturers and Suppliers" on pages 33-38.

Tanks

Tanks should be sized to meet plant and customer needs. Minimal capacity equivalent to 150% of normal monthly bulk receipt is suggested. Each storage vessel should be a welded, vertical or horizontal, cylindrical, carbon steel tank (A283C steel) built to API 650 Code and designed to hold the specified product safely when filled to capacity.

Both vertical and horizontal tanks should be equipped with the following openings:

- 1 — 20-inch of manway,
- 1 — 20-inch shell manway 12 inches off floor,
- 1 — 3- or 4-inch roof nozzle for vent,
- 3 — 1½-inch roof nozzles for gauge,
- 1 — 2-inch shell nozzle near floor leading to a dished sump for drain,
- 2 — 2- to 3-inch shell nozzle 12 inches above floor for inlet and outlet. Inlet and outlet are to be 90° apart, and
- 1 — 1-inch 3,000-lb coupling in shell 36 inches above floor for thermometer well.

Tank vents should be passed through an activated carbon bed prior to discharging to the atmosphere.

In the design of tanks to be lined, minimal radii recommended by the lining manufacturer must be observed. Full fillet interior welds should be utilized, and all splatter must be ground smooth. Welds must be continuous and smooth and should have no undercuts or porosity. The tank manufacturer should be responsible for providing the proper radii and welds and for

removing all splatter. The lining contractor should be responsible for other surface preparation.

Tanks should be water-tested to design pressure, and then dried, brush sand-blasted inside, and cleaned. A silica gel charge should be placed inside the tank prior to sealing it for shipment. Also, moisture content should be 125 ppm maximum prior to putting the tank into service. Exterior scale should be removed and the exterior primed with one coat of red inorganic zinc primer. Silica gel charges in tanks must be removed and the system must be thoroughly cleaned, dried, and purged with a dry pad gas prior to use.

Linings

Linings are desirable to prevent the pickup of rust or iron which can cause product discoloration. If a lining is to be used, surface preparation and lining application are of prime importance and should be conducted in strict accordance with the lining manufacturer's recommendations. Also, only experienced lining applicators, who are licensed or approved by the lining manufacturer, should be considered for application work.

Surfaces should be prepared and coated within 8 hours, during which proper temperature and humidity control should be maintained. In no case, however, should a lining application be attempted on a surface once evidence of rust has been detected. Also, if linings are applied in the shop, extra care must be exercised to prevent lining damage during transportation and erection of the tank. If any damage does occur, it should be thoroughly repaired prior to placing the tank in service. High-temperature baked-phenolic lining is satisfactory for storage of VORANATE T-80 Toluene Diisocyanate, provided proper application and curing methods are employed. Other satisfactory lining materials include the following: Heresite¹ P403-L66; Bisonite² 957; Plasite³ 3055, 3066 or 7122; Colturiet Phenguard⁴ 7436 and equivalent materials.

¹Trademark of Heresite-Saekaphen, Inc.

²Trademark of Bisonite Company, Inc.

³Trademark of Wisconsin Protective Coating Corp.

⁴Trademark of Sigma Coatings, Inc.

Insulation

Storage tanks located out-of-doors and which may be exposed to extremes of temperature should be insulated with either a 1- or 1½-inch thick polyurethane foam or STYROFOAM® Brand Plastic Foam, or a 2-inch thick fibrous glass. Insulation must be sealed to prevent the collection of moisture, which could corrode the external tank wall. In addition, an effective weather cover should be used to protect the tank from rain, snow, ice, etc.

If tanks are located indoors, where normal room temperatures are maintained, insulation may not be necessary. Interior storage tanks insulated with plastic foam should be covered with an effective flame barrier to minimize the hazard of combustibility. To prevent lining damage, insulation and any necessary welding should be completed before the lining is installed.

Pumps

Steel or stainless steel standard centrifugal or positive displacement pumps equipped with mechanical seals are preferred. Seal-less pumps (such as Crane Chempump®) and magnetic drive pumps (such as Kontro® and Magnatex®) are also satisfactory. Do *not* use silicone greases. Also, mechanical seals should be purged with dry gas to prevent moisture from contacting the seal face and causing urea formation and seal failure.

Depending upon preferred flow rates, two pumps for each system may be desirable. Truck unloading pumps should have a capacity of 100-150 gpm. Lower rates, however, may be preferred for process pumps. If so, two suitably sized pumps should be used.

Relief Valves

Three types of valves are required:

- Pressure-vacuum (P-V) vents for tanks,
- Relief valves for positive displacement pumps, and
- Line relief valves.

*Trademark of The Dow Chemical Company

†Trademark of Crane Company

‡Trademark of The Kontro Company

§Trademark of Bullen Pump and Equipment Company

Each storage tank must be provided with a pressure-vacuum (P-V) vent valve which, to prevent accumulation of vapors, should relieve or terminate out-of-doors.

Also, provided that all parts and equipment are rated for a working pressure of 150 psig, each positive displacement pump should be equipped with a relief system set at a maximum of 125 psig. If parts and equipment are not rated at 150 psig, the relief should be set at 75% to 95% of the system's lowest working pressure.

Finally, each line section which can be closed off by valves while full of liquid should have a relief valve which relieves back toward the tank, with the final section relieving into the tank itself. Settings for these reliefs should be the same as those for pumps.

Pressure Gauges

Gauges should be provided at the pump, before and after filters, and near the process. They should be protected by a sealed diaphragm filled with nonhydrocarbon fluid. Gauges are also advisable on steam and air lines and on equipment where gases or liquids are handled, such as chillers and heat exchangers.

Sample Valves

To facilitate product sampling, ½- to ¾-inch sample valves, which terminate in a stainless steel nipple, should be provided in each system.

Piping

Both schedule 40 seamless carbon steel pipe (A53) and welded pipe joints with flanges and flanged valves work well. Threaded couplings and valves may also be used, provided that tape made of Teflon brand fluorocarbon fiber is used on all threaded fittings. Tape must be applied carefully. Also, *no* pipe dopes may be used.

Selection of line sizes will be determined by product flow rate, system design, and pump specifications. Normally, a line 3 inches in diameter is satisfactory; however, for short, simple systems, 2 inches may be more suitable, while for longer and more complex systems, 4 inches may be required. In any event, sizes should be established in conjunction with the pump supplier, keeping the diameter to the practical and economical minimum.

Pipeline insulation and heating or cooling may be required if lines are either outdoors or in an area where normal room temperatures are not maintained.

Heating

VORANATE T-80 Toluene Diisocyanates should be maintained at slightly above room temperature (i.e., 70°-90°F [21°-32°C]). Care should be taken to prevent the product from overheating to above 104°F (40°C). For heating uninsulated indoor storage tanks, an industrial heater may prove adequate. However, for outdoor insulated tanks, external plate coils using steam to 25 psig are recommended. To maintain suitable product temperatures, pipelines may also require insulation, tracing, or both.

Heat Exchangers

Heat exchangers should have an area of 2 to 3 square feet per gallon/minute.

Pad Gas

Dry nitrogen is preferred; however, dry, oil-free air supplied by an air compressor and dryer may also be used. Either gas should have a maximum dew point of -40°F (-40°C). It is very important that TDI tank atmospheres be kept dry. If wet air is allowed to enter the tank, solid ureas will be formed. Over a period of time, a substantial amount of solids can accumulate.

Pressure Control Valves (PCV)

Use a low-pressure regulator to control the pressure in the isocyanate storage tank.

Temperature Indicators (TI)

The temperature of the product may be accurately monitored with a dial-type thermometer inserted in a suitable thermowell. To achieve greater heat transfer for a more accurate reflection of the temperature of the contents, be sure the thermometer is in direct contact with the thermowell.

Level Indicators (LI)

A level indicator should be used to measure product level in the tank and to determine inventory.

Strainers

Steel-cased, dual-line strainers having 100-mesh stainless steel reinforced wire screen baskets are recommended. Units should also be equipped with block valves which permit one side to continue in operation while the other is being serviced. It is strongly recommended that all unloading and process lines be equipped with either strainers or filter; e.g., use strainers on the unloading lines close to the tank and filters on the process lines close to the process.

Filters

Filters should be equipped with elements which are suitable to the product and the

desired flow rate. Twenty-micron, cotton-wound elements with voile-covered steel mesh cores are recommended.

Meters

Use suitably sized meters. Meters should contain no aluminum or aluminum alloys nor any synthetics other than Teflon fluorocarbon and Viton fluoroelastomer. Turbine meters equipped with totalizers have proved satisfactory.

Valves

Cast steel, malleable iron, or 316 stainless steel 150 psig valves are suitable for tank nozzles. Steel, malleable iron, or iron 125 psig valves may be used on lines. Also,


gate, ball, or plug valves may be used, provided no internal lubrication is required. Valve packing, if required, should be non-graphited asbestos, asbestos impregnated with Teflon fluorocarbon fiber, or braided Teflon fluorocarbon fiber. Also, ball valves should have seats of Teflon.

Gaskets

Gaskets of nongraphited asbestos, asbestos impregnated with Teflon fluorocarbon, or braided Teflon fluorocarbon fiber may be used. Spiral-wound Teflon filled gaskets and Garlock Gylon¹ Blue have also proved satisfactory.

¹Trademark of Garlock Inc.

Figure 6 — Isocyanate Component Storage System



VORANATE T-80
Safe Handling and Storage

Hoses

Hoses should be made of either Teflon fluorocarbon or Viton fluoroelastomer. Hoses for permanent and continuous service should be made of flexible seamless metal, steel, or stainless steel.

Electrical

Explosion-proof wiring and equipment should be used in all areas where flammable vapors or dusts are likely to be present. Also, all electrical equipment should be grounded.

Electrical work must conform to all applicable codes and ordinances. When ordering electrically operated equipment, be sure to specify the type of electrical service available.

Foundations

Depending upon load and soil conditions, reinforced concrete pads, concrete rings, reinforced concrete piers, or crushed stone rings may be used. Vertical tank bottoms should be coated and, if out-of-doors, sealed to the foundation with asphalt. Also, if ring foundations are used, the centers should be filled with compacted oiled sand.

Paint

All steel equipment used out-of-doors should be carefully cleaned and coated with a suitable primer.

Dual-Service Equipment

Equipment to be used for two or more products must be so designed that it can be drained and blown dry between products. Manifolds should *not* be used. Instead, switch-hose and quick-coupler connections should be made between dual service equipment and individual product lines.

Drains

All equipment should be provided with drains and should be designed to drain completely. Piping should slope toward low points equipped with drains. Tank areas should be diked; however, there should be no open drains within the diked area.

Ventilation

Indoor storage systems should be housed in a separate room, equipped with exhaust fans and intakes. This will minimize vapor accumulation in the event of a leak or spill.

Miscellaneous

- Waste control, disposal, and air pollution control measures should be carefully considered. Proper systems and operational controls should be instituted and carefully maintained.
- All equipment and facilities, as well as their installation, should conform to the specifications and requirements of appropriate federal, state, and local codes and ordinances.
- All equipment and materials should be compatible with the product to be handled and should be installed in strict compliance with the manufacturer's recommendations.
- All systems should be bonded and grounded. Bonding and grounding cables should be available at all loading and unloading stations.
- All electrical equipment, such as motors, switches, etc., as well as their installation and use, must conform to codes established by Underwriters Laboratories (UL).
- All tanks should be equipped with a stripping connection so that the tank may be completely emptied for cleaning, inspection, or repair.
- All liquid bulk storage systems should be hydrostatically tested prior to lining, insulation, or use.
- All systems, new or old, should be provided with adequate waste control and disposal facilities, as well as sources of air, water, steam, and electric power for both systems operation and cleaning.

CAUTION

- **Toxicology:** Virtually all chemicals possess some degree of toxicity. Before handling a new chemical, therefore, it is essential that its toxicological properties, as well as any potential hazards associated with its handling and use, be thoroughly studied and understood. Based upon this study, appropriate health and safety standards should then be established and maintained. Be sure to obtain a copy of the current Material Safety Data Sheet (MSDS) for the appropriate VORANATE T-80 Toluene Diisocyanate. Copies are available upon request from any Dow sales office or from The Dow Chemical Company, Plastics Group, 2040 Willard H. Dow Center, Midland, MI 48674.
- **Isocyanate:** Equipment containing copper, zinc, or tin, or their alloys, including brass, bronze, or galvanized materials, should *not* be exposed to liquid isocyanate or its vapors. Also, do *not* expose either rubber or synthetics — except Teflon fluorocarbon or Viton fluoroelastomer — to isocyanate liquid or vapor.
- **Silica gel charges:** Silica gel charges in tanks must be removed and the system must be thoroughly cleaned, dried, and purged with a dry pad gas prior to use.

APPENDIX A

Equipment
Manufacturers
and Suppliers:
Bulk Handling
and Storage
Equipment

The following list is representative of manufacturers and suppliers of equipment who may be used in the design and construction of systems for bulk handling and storage of VORANATE T-80 Toluene Diisocyanates. Specific questions about the specifications or suitability of any of the products offered by these firms should be addressed to the firm in question¹. The Dow Chemical Company neither endorses the products offered nor guarantees their performance. Reference to a company or product by name does not imply approval or recommendation by Dow of any product to the exclusion of others that may be suitable for the intended purpose.

¹The names, addresses, ZIP codes, and telephone numbers listed here are accurate as of the date of publication. For current information, consult *Thomas Register*, *Standard & Poor's*, or the *Dun & Bradstreet Reference Book of Manufacturers*.

Couplings-Quick

Dover Corp., OPW Div.
277-T Park Avenue
New York, NY 10172
212-826-7160

Ever-Tite Coupling Co., Inc.
256 W. 54 St.
New York, NY 10019
212-265-1420

Drum Filling

Crandall Filling Machinery, Inc.
P.O. Box 706-T
Buffalo, NY 14217
716-885-2228

Dryers

Lectrodryer Div.
(Ajax Magnethermic Corp.)
P.O. Box 2500
Richmond, KY 40475
606-624-2091

Pall Pneumatic Products Corp.
2200 Northern Blvd.
East Hills, NY 11548
516-484-5400

Permea
11444 Lackland Road
St. Louis, MO 63146
314-694-0158

Sentry Tank Accessories, Inc.
3800 N. Carnation Street
Franklin Park, IL 60131
312-671-1500

Filters

Commercial Filters Div.
(A Sohio Company)
State Rte., 32 W.
P.O. Box 1300
Lebanon, IN 46052
317-482-3900

Cuno, Inc.
(Commercial Shearing, Inc.)
402 Research Pky.
Meriden, CT 06450
203-238-8716

Filterite Brunswick Corp.
Technetics Div.
2033 Greenspring Dr.
Timonium, MD 21093
301-252-0800

Millipore Corp.
80 Ashby Road
Bedford, MA 01730
617-275-9200

Ronningen-Petter Co.
(Div. Dover Corporation)
P.O. Box 188T
Portage, MI 49081
616-323-1313

Gaskets

Crane Packing Co.
6410 Oakton St.
Morton Grove, IL 60053
312-967-2400

Flexitallic Gasket Co.
P.O. Box 848
151 Heller Pl.
Bellmawr, NJ 08031
609-931-2500

Garlock Inc.
Mechanical Packing Division
(Colt Industries, Inc.)
1666 Division St.
Palmyre, NY 14522
315-597-4811

Manville
P.O. Box 5108
Denver, CO 80217
1-800-243-8060

Gauges, Pressure

Ametek, Inc.
U.S. Gauge Div.
P.O. Box 152, Dept. TR
Sellersville, PA 18960
215-257-6531

Dresser Instrument Division
Dresser Industries, Inc.
250 E. Main St.
Stratford, CT 06497
1-800-243-8160

Grease Lubricants (Solvent Resistant)

Penreco
(A Pennzoil Division)
104 S. Main St.
Butler, PA 16001
412-283-5600

Heat Exchangers

ITT Standard
Heat Transfer Technology
175 Standard Pky.
Buffalo, NY 14227
716-897-2800

Nooter Corp.
P.O. Box 451
St. Louis, MO 63166
314-621-6000

Patterson-Kelly Co.
(Div. Harsco Corp.)
Thomas & Muth Sts.
East Stroudsburg, PA 18301
717-421-7500

Smithco Engineering, Inc.
P.O. Box 571330
Tulsa, OK 74157
918-446-4406

Struthers Wells Corp.
1003-T Pennsylvania W.
P.O. Box 8
Warren, PA 16365
814-726-1000

Vilter Mfg. Corp.
2217-T S. First St.
Milwaukee, WI 53207
414-744-0111

Heaters

Crane Company
(Cocrane Environmental
Systems Div.)
P.O. Box 191
King of Prussia, PA 19406
215-265-5050

Hose (Metal)

Aeroquip, U.S. Industrial Group
300 S. East Ave.
Jackson, MI 49203
517-787-8121

Federal Hose Manufacturing Corp.
P.O. Drawer 480
Painesville, OH 44077
216-352-8927 or 1-800-346-4673

Flexonics, Inc.
300-T E. Devon Ave.
Bartlett, IL 60103
312-837-1811

Pentflex Inc.
271 Lancaster Ave.
Frazer, PA 19355
215-644-7400 or 1-800-232-3539

Universal Metal Hose Co.
2135 S. Kedzie Ave.
Chicago, IL 60623
312-277-0700

Hose (Synthetic)

Goodall Rubber Co.
P.O. Box 8237-T
Trenton, NJ 08650
609-587-4000 or 1-800-524-2650

The Goodyear Tire & Rubber Co.
Industrial Products Div.
P.O. Box 52-T
Akron, OH 44309
216-796-2204

R. M. Engineered Products
P.O. Box 5205
North Charleston, SC 29406
803-744-6261

Uniroyal, Inc.
Product Information Center
World Headquarters
Middleburg, CT 06749
203-573-3717

Hose Reels

Hannay, Clifford B. & Son, Inc.
700 E. Main St.
Westerlo, NY 12193
518-797-3791 or 1-800-982-0030

Insulation

The Dow Chemical Company
Plastics Group
2040 Willard H. Dow Center
Midland, MI 48674
517-636-1000

Pittsburgh Corning Corp.
800 Presque Isle Dr.
Pittsburgh, PA 15239
412-327-6100

Joints

(See "SWIVEL JOINTS")

Level Indicators

Emerson Electric Co.
8000-T. W. Florissant Avenue
St. Louis, MO 63136
314-533-2000

Level Indicators (Magnetic)

Midland Mfg. Corp.
7733-T Gross Point Rd.
Skokie, IL 60076
312-677-0333

VORANATE T-80
Safe Handling and Storage

Level Switches

Magnetrol International
5300 Belmont Rd.
Downers Grove, IL 60515
312-969-4000

National Sonics
(Div. of Xertex Corp.)
250-T Marcus Blvd.
Hauppauge, NY 11787
516-273-6600

Linings

Ameron, Inc.
(Ameron Protective Coatings Div.)
4700-T Ramona Blvd.
P.O. Box 3000
Monterey Park, CA 91754
213-268-4111

Bisonite Co., Inc.
2248-T Military Rd.
Tonawanda, NY 14150
716-693-6130

Heresite-Saekaphen, Inc.
822 S. 14th St.
Manitowoc, WI 54220
414-684-6646

Sigma Coatings, Inc.
P.O. Box 826, Dept. TR
Harvey, LA 70059
504-347-4321

Wisconsin Protective Coating Corp.
614 Elizabeth St.
Green Bay, WI 54305
414-437-6561

Meters

Brooks Instrument Div.
(Emerson Electric Co.)
407 W. Vine St.
Hatfield, PA 19440
215-362-3500

The Foxboro Company
86 Neponset Ave.
Foxbor, MA 02035
617-543-8750

Halliburton Services
(Div. Halliburton Company)
Drawer 1431
Duncan, OK 73536
405-251-3760

Liquid Controls Corp.
Dept. TR-31
Wacker Park
N. Chicago, IL 60064
312-689-2400

Rockwell International Corp.
(Measurement & Flow Control Div.)
411 N. Lexington Ave.
Pittsburgh, PA 15208
412-247-3000

Smith Meter Div.
(Geosource, Inc.)
Dept. T
P.O. Box 10428
Erie, PA 16514
814-899-0661

Moisture Detectors

Beckman Instruments, Inc.
2500-T Harbor Blvd.
Fullerton, CA 92634
714-871-4848

E.I. du Pont de Nemours & Co., Inc.
Analytical Instruments Div.
3411 Silverside Rd.
Concord Plaza
Quillen Building
Wilmington, DE 19810
302-772-5500

Teledyne Analytical Instruments
16830 Chestnut Dr.
City of Industry, CA 91748
818-961-9221

Pumps (Canned)

Crane Company
(Chempump Div.)
175 Titus Ave.
Warrington, PA 18976
215-343-6000

Pumps (Centrifugal)

Allis-Chalmers Pump, Inc.
P.O. Box 512
Milwaukee, WI 53201
414-475-2000

The Duriron Company, Inc.
N. Findlay & Thomas Sts.
Dayton, OH 45401
513-226-4000

Goulds Pumps, Inc.
240 Fall St.
Seneca Falls, NY 13148
315-568-2811

Ingersoll-Rand
(Pump Group)
1200 West Belt Drive North
Houston, TX 77043
713-467-2221

Pumps (Magnetic Drive)

Bullen Pump & Equipment, Inc.
P.O. Box 770845
Houston, TX 77215
713-493-4840

The Kontro Co., Inc.
450 W. River St.
Orange, MA 01360
617-544-2536

Pumps (Positive Displacement)

Blackmer Pump
(Div. Dover Corp.)
1809 Century Ave., S.W.
Grand Rapids, MI 49509
616-241-1611

Nichols/Zenith
(Div. of Parker Hannifin Corp.)
P.O. Box 71-T
Waltham, MA 02254
617-894-0650

Roper Pump Co.
P.O. Box 269
Commerce, GA 30529
404-335-5551

Viking Pump — Houdaille, Inc.
George & Wyth Sts.
Cedar Falls, IA 50613
319-266-1741

Waukesha Division
(Abex Corp.)
5510 Lincoln Ave.
Waukesha, WI 53186
414-542-0741

Refrigeration Units

Carrier Corp.
P.O. Box 4808
Syracuse, NY 13221
315-432-6000

Dunham-Bush, Inc.
178 South St.
West Hartford, CT 06110
203-249-8671

Ronningen-Petter
(Div. Dover Corp.)
P.O. Box 188T
Portage, MI 49081
616-323-1313

Vilter Mfg. Corp.
2217-T S. First St.
Milwaukee, WI 53207
414-744-0111

Safety Equipment

American Optical Corp.
(Safety Products Div.)
14 Mechanic St.
Southbridge, MA 01550
617-765-9711

Bausch & Lomb Inc.
P.O. Box 450
Rochester, NY 14692
716-338-6000

E. D. Bullard Co.
2682 Bridgeway
Sausalito, CA 94965
415-332-0410

Mine Safety Appliances Co.
P.O. Box 426
Pittsburgh, PA 15230
1-800-672-2222

Strainers

Cuno, Inc.
(Commercial Shearing, Inc.)
402 Research Pky.
Meriden, CT 06450
203-237-5541 or 1-800-243-6894

Dover Corp., OPW Div.
277-T Park Ave.
New York, NY 10172
212-826-7160

Swivel Joints

FMC Corporation
Fluid Control Operation
1803 Gears Rd.
Houston, TX 77067
713-591-4000

LTV Energy Products Co.
P.O. Box 461388
Garland, TX
214-276-5151

Synthetics

E.I. du Pont de Nemours & Co., Inc.
1007-T Market St.
Wilmington, DE 19898
302-774-2421

Tanks

Buffalo Tank Corp.
P.O. Box 2755-T
Baltimore, MD 21225
1-800-368-2105

Tape

E.I. du Pont de Nemours & Co., Inc.
1007 Market St.
Wilmington, DE 19898
302-774-2421

Thermometers

(Note: Most manufacturers of thermometers also supply thermowells.)

Palmer Instruments, Inc.
3131 Wasson Rd.
Cincinnati, OH 45209
513-871-7800

Princo Instruments, Inc.
1020-T Industrial Highway
Southampton, PA 18966
215-355-1500

Valves

Crane Co.
(Valve Div.)
800 E. Third Ave.
King of Prussia, PA 19406
215-962-0366

Jamesbury Corp.
640 Lincoln St.
Worcester, MA 01605
1-800-243-8160

KTM Industries Inc.
16610-T Barker Springs Rd.
Houston, TX 77084
713-492-8800

The Lunkenheimer Co.
Beekman St. at Waverly Ave.
Cincinnati, OH 45214
513-921-3400

Rockwell International Corp.
401 N. Lexington Ave.
Pittsburgh, PA 15208
412-247-3000

VORANATE T-80
Safe Handling and Storage

Valves (Control)

Fisher Controls International, Inc.
205-T S. Center St.
Marshalltown, IA 50158
515-754-3011

**Masonellian Div.
(McGraw-Edison Co.)**
P.O. Box 4020
Woodlands, TX 77387
713-367-5741

Valves (Relief/Vents)

Crosby Valve & Gage Co.
43 Kendrick St.
Wrentham, MA 02093
617-384-3121

Emerson Electric Co.
8000 W. Florissant Ave.
St. Louis, MO 63136
314-553-2000

**Oceco Division
(Pettibone Corp.)**
4700-T W. Division St.
Chicago, IL 60651
312-772-9300

The Protectoseal Co.
227 Foster Ave.
Bensenville, IL 60106
312-595-0800

Sentry Tank Accessories, Inc.
3800 N. Carnation St.
Franklin, IL 60131
312-671-1500

Vapor Detectors

GMD Systems Inc.
Old Route 619
Hendersonville, PA 15339
412-746-3600

MDA Scientific, Inc.
405 Barclay Blvd.
Lincolnshire, IL 60069
1-800-323-2000
(Illinois: 312-634-2800)

National Draeger, Inc.
P.O. Box 120
Pittsburgh, PA 15230
412-787-8383

APPENDIX B

Equipment
Manufacturers
and Suppliers:
Respiratory
Protective
Equipment

The following list of manufacturers and suppliers* of NIOSH-approved respiratory protective equipment was obtained from the National Institute for Occupational Safety and Health, Morgantown, WV 26505. Questions about the specifications or suitability of any of the products offered by these firms should be addressed to the firm in question. The Dow Chemical Company neither endorses the products offered nor guarantees their performance. Reference to a company or product by name does not imply approval or recommendation by Dow of any product to the exclusion of others that may be suitable for the intended purpose.

*The names, addresses, ZIP codes, and telephone numbers listed here are accurate as of the date of publication. For current information, consult *Thomas Register*, *Standard & Poor's*, or the *Dun & Bradstreet Reference Book of Manufacturers*.

Ace Enterprises
820-T N.W. 144th St.
Miami, FL 33168
305-685-8784

American Optical Corp.
Safety Products Division
14 Mechanic St.
Southbridge, MA 01550
617-765-9711

Andersen Manufacturing Co., Inc.
P.O. Box 318
Furlong, PA 18925
215-794-8121

Binks Manufacturing Co.
9201 W. Belmont Ave.
Franklin Park, IL 60131
312-671-3000

BioMarine Industries, Inc.
45 Great Valley Center
Malvern, PA 19355
215-647-7200

Bowen Tools, Inc.
2400-T Crockett St.
P.O. Box 3186
Houston, TX 77253
713-869-6711

Browning Ferris Industries, Inc.
14701-T St. Mary's Lane
P.O. Box 3151
Houston, TX 77253
713-870-8100

E. D. Bullard Co.
2682 Bridgeway
Sausalito, CA 94965
415-332-0410

Cesco Safety Products
(Parmelee Industries, Inc.)
1535 Walnut St.
P.O. Box 1237
Kansas City, MO 64141
816-842-8500

Clemco Industries
1657 Rollins Rd.
Burlingame, CA 94010
415-570-6000

Clemtex, Inc.
248 McCarthy Dr.
Houston, TX 77029
713-672-8251

Defense Apparel
247-T Addison Rd.
Windsor, CT 06095
203-522-1957

The DeVilbiss Company
P.O. Box 913-T
Toledo, OH 43692
1-800-628-1200, ext. 735

A. E. Draegerwerk
2400 Lubeck 1
Postfach 1339
Moislinger Allee 53/55
West Germany

Eastern Safety Equipment Co., Inc.
59-20-T 56th Ave.
Maspeth, NY 11378
718-894-7900

Empire Abrasive Equipment Corp.
2101 W. Cabot Blvd.
Langhorne, PA 19047
215-752-8800

Encon Manufacturing Co.
P.O. Box 3826-TR
Houston, TX 77253
713-462-4723, Ext. 127

The Fibre Metal Products Co.
Brinton Lake Rd. & Rte. 1
Concordville, PA 19331
215-459-5300

Glendale Optical Co., Inc.
130 Crossways Park Dr.
Woodbury, NY 11797
516-921-5800

Globe Safety Equipment, Inc.
125 Sunrise Place
P.O. Box 7248
Dayton, OH 45407
513-224-7468

HSC Corp.
107 E. Alexander St.
Buchanan, MI 49107
616-695-9663

Kelco Sales & Engineering Co.
Front St. & Paddison Ave.
Norwalk, CA 90650
213-868-9861

Key Houston, Inc.
13911 Atlantic Blvd.
Jacksonville, FL 32225
904-241-4191

Lear Siegler, Inc.
714 N. Brookhurst St.
Anaheim, CA 92803
714-774-1010

APPENDIX C

References

Literature published by the following organizations:

**American Conference of
Governmental Industrial Hygienists**
6500 Glenway Avenue, Building D-7
Cincinnati, OH 45211
513-661-7881

International Isocyanate Institute, Inc.
119 Cherry Hill Road
Parsippany, NJ 07054
201-263-7517

**National Institute for Occupational
Safety and Health**
944 Chestnut Ridge Road
Morgantown, WV 26505
304-291-4126

**Occupational Safety and Health
Administration**
Department of Labor
200 Constitution Avenue N.W.
Washington, DC 20210
202-523-9361]

The Society of the Plastics Industry, Inc.
350 Lexington Ave.
New York, NY 10017
212-573-9400

Mine Safety Appliances Co.

P.O. Box 426
Pittsburgh, PA 15230
1-800-672-2222

Mohawk Industrial Supply Co.

P.O. Box 945
Manchester, CT 06040
203-643-5107

National Draeger, Inc.

P.O. Box 120
Pittsburgh, PA 15230
412-787-8383

**Norton Consumer Products
(A Div. of Siebe North, Inc.)**

P.O. Box 7500
16624 Edwards Road
Cerritos, CA 90701
213-926-0545 or 1-800-421-3841

Pauli & Griffin Co.

907 Cotting Lane
Vacaville, CA 96588
707-447-7000

Pulmosan Safety Equipment Corp.

30-48-T Linden Place
Flushing, NY 11354
718-939-3200

Robertshaw Controls Co.

P.O. Box 26544
Richmond, VA 23261
804-281-0700

Safe-Tex Manufacturing Co.

15 Brandon
Toronto, Ontario, Canada
416-534-4223

Safety and Supply Co.

5510 East Marginal Way
South Seattle, WA 98134
206-762-8500

Schmidt Manufacturing, Inc.

P.O. Box 37
11927 S. Highway 6
Houston, TX 77053
713-434-0581

Scott Aviation

(A Div. of A-T-O Inc.)
2225 Erie St.
Lancaster, NY 14086
716-683-5100

Sellstrom Mfg. Co.

P.O. Box 355
Palatine, IL 60078
312-358-2000

Siebe Gorman Holdings Ltd.

Neptune Works Davis Rd.
Chessington Surrey, England KT9

Standard Safety Equipment Co.

P.O. Box 188
Palatine, IL 60078
312-359-6000

Stewart-Warner Corp.

1826 W. Diversey Pkwy.
Chicago, IL 60614
312-883-6000

3M Company

3M Center
St. Paul, MN 55144
612-733-1110

Titan Abrasive Systems, Inc.

P.O. Box 318-T
Furlong, PA 18925
215-794-5661

United States Safety Service Co.

1535 Walnut St.
P.O. Box 1237
Kansas City, MO 64141
816-842-8500

Willson Safety Products

Div. of WGM Safety Corp.
P.O. Box 622, Dept. T
Reading, PA 19603
215-376-6161

VORANATE T-80
Safe Handling and Storage

Product Stewardship

The Dow Chemical Company has a fundamental concern for all who make, distribute, and use its products, and for the environment in which we live. This concern is the basis for our Product Stewardship philosophy, by which we assess the health and environmental information on our products and then take appropriate steps to protect employee and public health and the environment. Our Product Stewardship program rests with each and every individual involved with Dow products — from the initial concept and research to the manufacture, sale, distribution, use, and disposal of each product.

Customer Notice

The Dow Chemical Company strongly encourages its customers to review both their manufacturing processes and their application of Dow products from the standpoint of human health and environmental quality. To help ensure that Dow products are not used in ways for which they were not intended or tested, Dow personnel are prepared to assist customers in dealing with both ecological and product safety considerations. Your Dow representative can arrange the proper contacts.

CHEMTREC

FOR CHEMICAL EMERGENCY
Spill, Leak, Fire, Exposure, or Accident
CALL CHEMTREC
DAY OR NIGHT

***800-424-9300**

Toll-free in the continental U.S.

*Add long-distance access number if required

483-7616 in District of Columbia

For calls originating outside the
Continental U.S.: 202-483-7616

— Washington, DC, Collect

ALL CALLS ARE RECORDED




CM^A



**DISTRIBUTION EMERGENCY
RESPONSE SYSTEM**

**DISTRIBUTION EMERGENCIES
AND CHEMICAL EMERGENCIES
INVOLVING
EXPOSURES, LEAKS OR SPILLS**
Call: 517-636-4400 (Midland, MI)
409-238-2112 (Freeport, TX)

These condensed "Unloading Procedures" are included here for the convenience of "in-the-field" unloading personnel. For additional information, see Part Two of this bulletin.



VORANATE T-80 Toluene Diisocyanates

Unloading Procedures

Tank Cars Unloading Procedures

VORANATE* T-80 Toluene Diisocyanates are classified as hazardous materials under the Department of Transportation's "Hazardous Material Regulations." The unloading of tank trucks, therefore, must be done in strict accordance with those regulations. Some, but not all, of those regulations are described below.

VORANATE T-80 Toluene Diisocyanates are shipped in insulated, baked-phenolic-lined tank cars, equipped with external heating coils and a safety valve set for 75 psi. Tank cars from The Dow Chemical Company may be unloaded only from the top. The same general unloading


procedures used for tank trucks may be used for tank cars. The following steps are exceptions to the tank truck unloading procedure.

CAUTION: Only properly trained and equipped personnel are permitted to unload tank cars. Operators should wear an approved respiratory protective device and protective clothing, footwear, and gloves. For a detailed discussion of health hazards and safe handling procedures, see the Dow bulletin, *Safe Handling and Storage of VORANATE T-80 Toluene Diisocyanates* (Form No. 109-561-288).

Tank Car

- A — Gauging Device
- B — 3/4" Thermowell
- C — 75# Safety Valve
- D — 2" Top Unloading Valve
- E — 2" Vent Valve
- F — 1/4" Sample Valve
- G — 2" Top Unloading Valve
- H — 2" Steam Coil Outlet
- I — 2" Steam Coil Inlet
- J — Safety Platform

Note: On some 17,000-gallon DOWX series cars there is a variation in the dome valving configuration. The diagram shows the normal configuration. However, in some cars the positions of A (the gauging device) and C (the 75# safety valve) are reversed.



©1982, 1988. The Dow Chemical Company
All rights reserved

NOTICE: Dow believes the information and recommendations herein to be accurate and reliable as of February 1988. However, since any assistance furnished by Dow with reference to the proper use and disposal of its products is provided without charge, and since use conditions and disposal are not within its control, Dow assumes no obligation or liability for such assistance and does not guarantee results from use of such products or other information herein; no warranty, express or implied, is given nor is freedom from any patent owned by Dow or others to be inferred. Information herein concerning laws and regulations is based on U.S. federal laws and regulations except where specific reference is made to those of other jurisdictions. Since use conditions and governmental regulations may differ from one location to another and may change with time, it is the Buyer's responsibility to determine whether Dow's products are appropriate for Buyer's use, and to assure Buyer's workplace and disposal practices are in compliance with all laws, regulations, ordinances, and other governmental enactments applicable in the jurisdiction(s) having authority over the Buyer's operations.

THE DOW CHEMICAL COMPANY • PLASTICS GROUP • MIDLAND, MI 48674



Read and follow carefully each of the safety recommendations and precautions listed below:

1. Tank cars to be unloaded should have the brakes set and the wheels chocked, and should be protected by a "derail" located at least 50 feet from the car. Be sure to attach a signal flag to the rail to indicate that the derail is in position.
2. Verify that the proper car is being unloaded. Carefully check the car number against the bill of lading or other appropriate document. Also, sample the contents to be sure that the material is indeed a VORANATE T-80 Toluene Diisocyanate.
3. Check the temperature of the tank car by removing the 3/4-inch cap from the thermowell (B) and inserting a thermometer approximately 24 inches for 15-20 minutes. The temperature of the contents must be above 60°F (16°C) when the car is unloaded. Should heating be necessary, remove the cover from the magnetic gauge (A) and raise the gauge rod to engage the magnet on the float. Monitor the outage to assure that expansion does not fill the car "liquid full" and cause it to "pressure relieve" through the safety valve. The pressure on the tank car should be carefully monitored during heating. Do *not* allow pressure to go beyond 30 psig. Also dry nitrogen is recommended for padding.
4. Connect the unloading line (which should be clean, dry, and preferably made of flexible metal or either Teflon[®] fluorocarbon or Viton[®] fluoroelastomer hose

which can safely withstand unloading pressures) to the unloading valve (G or D) and the pad gas line to the vent valve or pressure connection (E). All TDI tank cars are equipped with 2-inch removable plugs on the unloading valves and 1-inch plugs on the vent valves. Also, while the safety valve on the car is set at 75 psig, pad gas pressure should be regulated so as *not* to exceed 40 psig. Storage tank pressure should be carefully controlled and monitored during the unloading operation.

5. After the tank car is empty, unloading lines should be blown clear of liquid and blocked in before being disconnected. (Note: Approved respiratory protective equipment should be worn when disconnecting lines.) Return all valves and connections to their original condition.
6. Before releasing, pad the tank car with 10-40 psig of nitrogen. Display DOT approved "RESIDUE" placards and release the car for return to Dow.

Unloading must be *closely monitored*, particularly if there is no automatic "cutoff" in the unloading line. For example, if gas flow is allowed to continue after unloading, the gas flowing into the storage tank could rapidly increase internal pressure. This could cause serious structural damage to the storage vessel.

[®]Trademarks and products of E.I. du Pont de Nemours Co., Inc.

VORANATE T-80 Toluene Diisocyanates

Unloading Procedures

Tank Trucks Unloading Procedures


VORANATE* T-80 Toluene Diisocyanates are classified as hazardous materials under the Department of Transportation's "Hazardous Material Regulations." The unloading of tank trucks, therefore, must be done in strict accordance with those regulations. Some, but not all, of those regulations are described below.

VORANATE T-80 Toluene Diisocyanates are shipped in pressurized and insulated stainless steel tank trucks, equipped for bottom unloading only. Dow recommends

that only DOT specification MC304 or 307 tank trucks be used. CAUTION: Only properly trained and equipped personnel are permitted to unload tank trucks. Operators should wear an approved respiratory protective device and protective clothing, footwear, and gloves. For a detailed discussion of health hazards and safe handling procedures, see the Dow bulletin, *Safe Handling and Storage of VORANATE T-80 Toluene Diisocyanates* (Form No. 109-561-288).

Tank Truck Trailer

- A — 3/4" Steam Inlet
- B — 35# Safety Valve and Pressure Gauge
- C — Manhole
- D — 3/4" Dry air/Nitrogen Connection
- E — 3" Unloading Connection
- F — 1/2" Sample Valve
- G — Steam Outlet
- H — Air Dryer
- I — 2" Loading Line
- J — 2" Vent Line



© 1982, 1988. The Dow Chemical Company
All rights reserved

NOTICE: Dow believes the information and recommendations herein to be accurate and reliable as of February 1988. However, since any assistance furnished by Dow with reference to the proper use and disposal of its products is provided without charge, and since use conditions and disposal are not within its control, Dow assumes no obligation or liability for such assistance and does not guarantee results from use of such products or other information herein; no warranty, express or implied, is given nor is freedom from any patent owned by Dow or others to be inferred. Information herein concerning laws and regulations is based on U.S. federal laws and regulations except where specific reference is made to those of other jurisdictions. Since use conditions and governmental regulations may differ from one location to another and may change with time, it is the Buyer's responsibility to determine whether Dow's products are appropriate for Buyer's use, and to assure Buyer's workplace and disposal practices are in compliance with all laws, regulations, ordinances, and other governmental enactments applicable in the jurisdiction(s) having authority over the Buyer's operations.

THE DOW CHEMICAL COMPANY • PLASTICS GROUP • MIDLAND, MI 48674



Read and follow carefully each of the safety recommendations and precautions listed below:

1. Before attempting to use the following procedure, operators should be thoroughly familiar with the potential hazards associated with the handling and storage of TDI.
2. Position the trailer as level as possible and block the wheels.
3. Carefully check the storage tank into which the contents of the truck are to be unloaded to be certain that it contains the intended VORANATE T-80 Toluene Diisocyanate product and *not* some other chemical or compound. Also, check the gauge on the storage tank to be sure that there is sufficient room to receive the entire contents of the tank truck.
4. Check all "product identification" or "bulk" tags (usually attached to product outlets, valves, or seals) to be certain that the product being unloaded is, in fact, the intended VORANATE T-80 Toluene Diisocyanate.
5. Check the temperature of the contents. The temperature must be *above* 60°F (16°C) when the trailer is unloaded.
6. If heating is required, attach a 25 psi steam supply to the heating coil inlet connection. For better control of the heating process, use a steam pressure of 15 psi. Attach a steam trap, designed for the steam pressure available, to the heating coil outlet connection. Internal coils are not advised because of severe effects due to possible water contamination of the product. Allow the contents to warm until the temperature is at least 68°F (20°C). When the temperature reaches 68°F (20°C), turn off the steam and disconnect the lines. To prevent the heating coils from freezing during cold weather, be sure to drain them or "blow them out." CAUTION: Carefully watch the thermometer during heating. Do *not* allow the temperature to rise above 104°F (40°C).
7. Attach the unloading line. The line should be clean, dry, and preferably made of flexible metal or either Teflon[®] fluorocarbon or Viton[®] fluoroelastomer hose which can safely withstand unloading pressures.
8. Connect the dry purge gas (preferably nitrogen) line to the tank truck. This line should have a pressure gauge, a safety valve set at 30 psig, and a pressure regulator set at 25 psig.
9. Draw off a sample of the contents for analysis. A sample of the contents may be obtained by connecting stainless steel tubing to the sample connection. Flush the sample connection by drawing off at least one gallon of product into a clean, dry container.

The sample to be analyzed may now be drawn off into another clean, dry container of whatever size is necessary for testing. **WARNING:** Do *not* breathe vapors. Wear proper protective equipment whenever there is any possibility of contact with isocyanate liquid or vapors.

- 10a. *If the contents are to be unloaded by purge gas pressure alone*, the storage tank should be fitted with a vent scrubber. This will prevent vapors from being vented into the atmosphere during unloading. (CAUTION: Do *not* exceed 25 psig purge gas pressure to unload the tank truck.) When the tank truck is empty, the pressure gauge will show a drop in pressure. Close the valve at the storage tank connection *first*. Then close the truck unloading valve.
- 10b. *If the contents are to be unloaded by pump*, either a vapor line connecting the storage tank vent to the tank truck should be installed (closed loop) or a low-pressure, replenishable gas pad must be placed on the tank truck. If a gas pad is used, install a vent scrubber on the storage tank vent. These precautions will not only prevent isocyanate vapors from being vented to the atmosphere, but will prevent a vacuum from being pulled on the tank truck during unloading. (CAUTION: Do *not* use a closed loop system unless the dead air space in the storage tank is free of moisture; i.e., -40°F (-40°C) dew point. Also, connection hoses should be purged with dry air or nitrogen before hookup.) When the trailer is empty, allow the unloading hose to vent down to the storage tank. Be sure to close the valve at the storage tank connection *first*. Then close the tank truck unloading valve.
11. Shut off the purge gas to the tank truck. Close the tank truck purge gas valve and disconnect the purge gas line. If a closed loop system was used in conjunction with pump unloading, close the tank truck connection valve and the tank vent valve. Then disconnect the hose connecting the two. All connection hoses should now be cleaned, dried, and capped for storage.

CAUTION: Unloading must be *closely monitored*, particularly if there is no automatic "cutoff" in the unloading line. For example, if gas flow is allowed to continue after unloading, the gas flowing into the storage tank could rapidly increase internal pressure. This could cause serious structural damage to the storage vessel.

The tank truck should *not* be cleaned by the customer, nor should the manway be opened for inspection. The cleaning and inspection of the tank truck should be handled by the shipper under carefully controlled conditions, designed to safeguard personnel and equipment. **WARNING:** Under no circumstances should personnel enter any "empty" tank truck.

[®]Trademarks and products of E. I. du Pont de Nemours Co., Inc.



DOW CHEMICAL U.S.A.

An Operating Unit of The Dow Chemical Company

PLASTICS GROUP

URETHANES DEPARTMENT

2040 WILLARD H. DOW CENTER

MIDLAND, MICHIGAN 48674

Major Urethanes Sales Offices of Dow Chemical U.S.A.

ATLANTA Suite 2005, 20 Perimeter Center East, Atlanta, GA 30346 • 404-394-4141
(for: AL, AR, FL, GA, KY (western), MS, NC, TN, VA)

CHICAGO Suite 800, 10 Gould Center, 2840 Golf Road, Rolling Meadows, IL 60008 • 312-228-2700
(for: IL, IN, MN, MO (eastern), ND, SD, WI)

DALTON 2864 North Dug Gap Road, Dalton, GA 30720 • 404-277-1133
(for: all states — carpet business only)

DETROIT Suiter 415, Travelers Tower, 26555 Evergreen Road, Southfield, MI 48076 • 313-358-1300
(for: KY (eastern), MI, OH, PA (western), WV)

HOUSTON P.O. Box 4269, 400 West Belt South, Houston, TX 77210 • 713-978-3700
(for: CO, IA, KS, LA, MO (western), NE, MN, OK, TX, WY)

LOS ANGELES 17870 Castleton St., P.O. Box 881, City of Industry, CA 91747 • 818-810-8050
(for: AK, AZ, CA, HI, ID, MT, NV, OR, UT, WA)

PHILADELPHIA 505 S. Lenola Road, Moorestown, NJ 08057 • 609-234-0400
(for: CT, DE, MA, MD, ME, NH, NJ, NY, PA (eastern), RI, VT)

For product and technical literature

Contact: INQUIRY & DISTRIBUTION SERVICES


Saginaw Road Bldg., The Dow Chemical Company, Midland, MI 48640 • 1-800-258-CHEM 8 a.m. - 5 p.m. E.S.T.

For information on products, applications, prices, ordering, billing, and delivery

Contact: URETHANES CUSTOMER SERVICE CENTER

400 West Belt South, P.O. Box 4265, Houston, TX 77210 • 1-800-258-2333 8 a.m. - 6 p.m. E.S.T.

NOTICE: Dow believes the information and recommendations herein to be accurate and reliable as of February 1988. However, since any assistance furnished by Dow with reference to the proper use and disposal of its products is provided without charge, and since use conditions and disposal are not within its control, Dow assumes no obligation or liability for such assistance and does not guarantee results from use of such products or other information herein; no warranty, express or implied, is given nor is freedom from any patent owned by Dow or others to be inferred. Information herein concerning laws and regulations is based on U.S. federal laws and regulations except where specific reference is made to those of other jurisdictions. Since use conditions and governmental regulations may differ from one location to another and may change with time, it is the Buyer's responsibility to determine whether Dow's products are appropriate for Buyer's use, and to assure Buyer's workplace and disposal practices are in compliance with all laws, regulations, ordinances, and other governmental enactments applicable in the jurisdiction(s) having authority over the Buyer's operations.



Drawing 3.01
 Wakefield Massy
 Flexible Polyurethane
 Foam Mfg. Process
 Process Flow Diagram
 7-5-89 JSP

Page 91B

4.03 Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.

Yes (1)
No 2

4.04 For each activity that uses the listed substance, circle all the applicable number(s) corresponding to each physical state of the listed substance during the activity listed. Physical states for importing and processing activities are determined at the time you import or begin to process the listed substance. Physical states for manufacturing, storage, disposal and transport activities are determined using the final state of the product.

CBI
☐

Activity	Physical State				
	Solid	Slurry	Liquid	Liquified Gas	Gas
Manufacture	1	2	3	4	5
Import	1	2	3	4	5
Process	1	2	(3)	4	5
Store	1	2	(3)	4	5
Dispose	1	2	3	4	5
Transport	1	2	3	4	5

☐ Mark (X) this box if you attach a continuation sheet.

- 4.05 Particle Size -- If the listed substance exists in particulate form during any of the following activities, indicate for each applicable physical state the size and the percentage distribution of the listed substance by activity. Do not include particles ≥ 10 microns in diameter. Measure the physical state and particle sizes for importing and processing activities at the time you import or begin to process the listed substance. Measure the physical state and particle sizes for manufacturing storage, disposal and transport activities using the final state of the product.

CBI

☐

Physical State		Manufacture	Import	Process	Store	Dispose	Transport
Dust	<1 micron			NA			
	1 to <5 microns			NA			
	5 to <10 microns			NA			
Powder	<1 micron			NA			
	1 to <5 microns			NA			
	5 to <10 microns			NA			
Fiber	<1 micron			NA			
	1 to <5 microns			NA			
	5 to <10 microns			NA			
Aerosol	<1 micron			NA			
	1 to <5 microns			NA			
	5 to <10 microns			NA			

☐ Mark (X) this box if you attach a continuation sheet.

SECTION 5. ENVIRONMENTAL FATE

PART A RATE CONSTANTS AND TRANSFORMATION PRODUCTS

5.01 Indicate the rate constants for the following transformation processes.

a. Photolysis:

Absorption spectrum coefficient (peak) UK (1/M cm) at _____ nm
Reaction quantum yield, ϕ UK at _____ nm
Direct photolysis rate constant, k_p , at ... UK 1/hr _____ latitude

b. Oxidation constants at 25°C:

For 1O_2 (singlet oxygen), k_{ox} UK 1/M hr
For RO_2 (peroxy radical), k_{ox} UK 1/M hr

c. Five-day biochemical oxygen demand, BOD_5 ... UK mg/l

d. Biotransformation rate constant:

For bacterial transformation in water, k_b ... UK 1/hr
Specify culture UK

e. Hydrolysis rate constants:

For base-promoted process, k_b UK 1/M hr
For acid-promoted process, k_a UK 1/M hr
For neutral process, k_n UK 1/hr

f. Chemical reduction rate (specify conditions) UK

g. Other (such as spontaneous degradation) ... UK

☐ Mark (X) this box if you attach a continuation sheet.

PART B PARTITION COEFFICIENTS

5.02 a. Specify the half-life of the listed substance in the following media.

<u>Media</u>	<u>Half-life (specify units)</u>
Groundwater	<u>UK</u>
Atmosphere	<u>UK</u>
Surface water	<u>UK</u>
Soil	<u>UK</u>

b. Identify the listed substance's known transformation products that have a half-life greater than 24 hours.

<u>CAS No.</u>	<u>Name</u>	<u>Half-life (specify units)</u>	<u>Media</u>
<u>UK</u>			in
			in
			in
			in

5.03 Specify the octanol-water partition coefficient, K_{ow} ... UK at 25°C
Method of calculation or determination

5.04 Specify the soil-water partition coefficient, K_d UK at 25°C
Soil type

5.05 Specify the organic carbon-water partition coefficient, K_{oc} UK at 25°C

5.06 Specify the Henry's Law Constant, H UK atm-m³/mole

☐ Mark (X) this box if you attach a continuation sheet.

5.07 List the bioconcentration factor (BCF) of the listed substance, the species for which it was determined, and the type of test used in deriving the BCF.

<u>Bioconcentration Factor</u>	<u>Species</u>	<u>Test</u> ¹
<u>UK</u>		

¹Use the following codes to designate the type of test:

F = Flowthrough
S = Static

☐ Mark (X) this box if you attach a continuation sheet.

6.04 For each market listed below, state the quantity sold and the total sales value of the listed substance sold or transferred in bulk during the reporting year.

☐

Market	Quantity Sold or Transferred (kg/yr)	Total Sales Value (\$/yr)
<i>Not Required</i>		
Retail sales		
Distribution -- Wholesalers		
Distribution -- Retailers		
Intra-company transfer		
Repackagers		
Mixture producers		
Article producers		
Other chemical manufacturers or processors		
Exporters		
Other (specify)		

6.05 Substitutes -- List all known commercially feasible substitutes that you know exist for the listed substance and state the cost of each substitute. A commercially feasible substitute is one which is economically and technologically feasible to use in your current operation, and which results in a final product with comparable performance in its end uses.

☐

Substitute	Cost (\$/kg)
<i>UK</i>	

☐

Mark (X) this box if you attach a continuation sheet.

SECTION 7 MANUFACTURING AND PROCESSING INFORMATION

General Instructions:

For questions 7.04-7.06, provide a separate response for each process block flow diagram provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the information is extracted.

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.

CBI

☐ Process type *Flexible Polyurethane Foam Manufacturing Process*

See attached drawing 7.01

☒ Mark (X) this box if you attach a continuation sheet.

- 7.03 In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

See attached drawing 7.01

☐ Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
<u>7.1</u>	<u>Bulk Stge. Tank</u>	<u>18-32</u>	<u>543</u>	<u>Mild Steel</u>
<u>7.2</u>	<u>Day Tanks</u>	<u>18-32</u>	<u>Atmospheric</u>	<u>Stainless Steel</u>
<u>7.3</u>	<u>Bulk Stge. Tank</u>	<u>18-32</u>	<u>543</u>	<u>Mild Steel</u>
<u>7.4</u>	<u>Tank Vent</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Mild Steel</u>
<u>7.5</u>	<u>Bulk Stge. Tank</u>	<u>18-32</u>	<u>543</u>	<u>Mild Steel</u>
<u>7.6</u>	<u>Filter</u>	<u>18-32</u>	<u>543</u>	<u>Cast Iron</u>
<u>7.7</u>	<u>Metering Pump</u>	<u>18-32</u>	<u>3300</u>	<u>Steel</u>
<u>7.8</u>	<u>Mixing Head</u>	<u>18-32</u>	<u>1,100</u>	<u>Steel</u>
<u>7.9</u>	<u>Plastic Can</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Polyethylene</u>
<u>7.10</u>	<u>Trough, Fall Plates, Conveyor</u>	<u>24-66</u>	<u>Atmospheric</u>	<u>Wood, Aluminum</u>

☒ Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

☐ Process type Continued

Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
<u>7.11</u>	<u>Vent. Fan</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Steel</u>
<u>7.12</u>	<u>Conveyor System</u>	<u>20-100</u>	<u>Atmospheric</u>	<u>Steel & Aluminum</u>
<u>7.13</u>	<u>Vent. Fan</u>	<u>32-40</u>	<u>Atmospheric</u>	<u>Steel</u>
<u>7.14</u>	<u>Cut-Off Saw</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Steel</u>
<u>7.15</u>	<u>Vent. Fan</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Steel</u>
<u>7.16</u>	<u>Pen Curing Bldg.</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Brick</u>
<u>7.17</u>	<u>Vent. Fan</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Steel</u>
<u>7.18</u>	<u>Fabrication Bldg.</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Brick</u>
<u>7.19</u>	<u>Carts with Wheels</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Wood & Steel</u>
<u>7.20</u>	<u>Shipping & Rec. Bldg.</u>	<u>Ambient</u>	<u>Atmospheric</u>	<u>Brick</u>

☐ Mark (X) this box if you attach a continuation sheet.

7.05 Describe each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

Process Stream ID Code	Process Stream Description	Physical State ¹	Stream Flow (kg/yr)
<u>7A</u>	<u>Polycol: Regular and Graft</u>	<u>OL</u>	<u>2,664,347</u>
<u>7B</u>	<u>Tin Catalyst</u>	<u>OL</u>	<u>9,231</u>
<u>7C</u>	<u>Amine Catalyst</u>	<u>OL</u>	<u>6,203</u>
<u>7D</u>	<u>Silicone Surfactant</u>	<u>OL</u>	<u>23,954</u>
<u>7E</u>	<u>Water</u>	<u>AL</u>	<u>106,574</u>
<u>7F</u>	<u>Dyes, Artistat, Plasticizer, etc.</u>	<u>OL</u>	<u>5,662</u>
<u>7G</u>	<u>Blowing Agent</u>	<u>OL</u>	<u>126,616</u>
<u>7H</u>	<u>TDI</u>	<u>OL</u>	<u>6,692,362</u>

¹Use the following codes to designate the physical state for each process stream:

- GC = Gas (condensable at ambient temperature and pressure)
- GU = Gas (uncondensable at ambient temperature and pressure)
- SO = Solid
- SY = Sludge or slurry
- AL = Aqueous liquid
- OL = Organic liquid
- IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

☒ Mark (X) this box if you attach a continuation sheet.

7.05 Describe each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

☐ Process type Continued

Process Stream ID Code	Process Stream Description	Physical State ¹	Stream Flow (kg/yr)
7 I	Polyurethane Reacting Mixture	OL	4,643,030
7 J	Mix Head Flesh	OL	1,920
7 K	Polyurethane Flexible Foam	SO	4,254,454

¹Use the following codes to designate the physical state for each process stream:

- GC = Gas (condensable at ambient temperature and pressure)
- GU = Gas (uncondensable at ambient temperature and pressure)
- SO = Solid
- SY = Sludge or slurry
- AL = Aqueous liquid
- OL = Organic liquid
- IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

☐ Mark (X) this box if you attach a continuation sheet.

7.06 Characterize each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the CBI instructions for further explanation and an example.)

☐ Process type Flexible Polyurethane Foam Manufacturing Process

a.	b.	c.	d.	e.
Process Stream ID Code	Known Compounds ¹	Concentrations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
<u>7A</u>	<u>Polyol</u>	<u>100% A/W</u>	<u>NA</u>	<u>NA</u>
<u>7B</u>	<u>Stearic Octoate</u>	<u>48% A/W</u>	<u>Various Organic Compds.</u>	<u>2%</u>
	<u>Diethyl Phthalate</u>	<u>50% A/W</u>	<u>NA</u>	<u>NA</u>
<u>7C</u>	<u>Triethylene diamine</u>	<u>33% A/W</u>	<u>NA</u>	<u>NA</u>
	<u>Dipropylene Glycol</u>	<u>67% A/W</u>	<u>NA</u>	<u>NA</u>

7.06 continued below

☒ Mark (X) this box if you attach a continuation sheet.

7.06 Characterize each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the CBI instructions for further explanation and an example.)

☐ Process type

a.	b.	c.	d.	e.
Process Stream ID Code	Known Compounds ¹	Concentrations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
7D	Organosilicone Compounds	100%/E/W	NA	NA
7E	Water	100%/E/W	NA	NA
7F	Milliken Reactant Dyes	100%/E/W	UK	UK
	LaroStat 377 DPG	100%/E/W	UK	UK

7.06 continued below

☒ Mark (X) this box if you attach a continuation sheet.

7.06 Characterize each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the CBI instructions for further explanation and an example.)

☐ Process type Continuation

a.	b.	c.	d.	e.
Process Stream ID Code	Known Compounds ¹	Concentrations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
<u>7G</u>	<u>Fluoro Trichloro Methane</u>	<u>100% A/W</u>	<u>NA</u>	<u>NA</u>
<u>7H</u>	<u>Toluene Diisocyanate</u>	<u>99.97% A/W</u>	<u>Hydrolyzable Chloride</u>	<u>0.1%</u>
<u>7I</u>	<u>7A through 7H</u>	<u>90% E/W</u>	<u>Carbon Dioxide</u>	<u>10%</u>

7.06 continued below

☒ Mark (X) this box if you attach a continuation sheet.

7.06 Characterize each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the CBI instructions for further explanation and an example.)

☐ Process type *Continued*

a.	b.	c.	d.	e.
Process Stream ID Code	Known Compounds ¹	Concentrations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
<u>7J</u>	<u>7I</u>	<u>10-20/E/W</u>	<u>NA</u>	<u>NA</u>
	<u>FluoroTrichloroMethane</u>	<u>80-90/E/W</u>	<u>NA</u>	<u>NA</u>
<u>7K</u>	<u>Polyurethane Flexible Foam</u>	<u>100/E/W</u>	<u>NA</u>	<u>NA</u>

7.06 continued below

☐ Mark (X) this box if you attach a continuation sheet.

7.06 (continued)

¹For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
<u>1</u>	<u>NA</u>	
<u>2</u>		
<u>3</u>		
<u>4</u>		
<u>5</u>		

²Use the following codes to designate how the concentration was determined:

A = Analytical result
E = Engineering judgement/calculation

³Use the following codes to designate how the concentration was measured:

V = Volume
W = Weight


☐ Mark (X) this box if you attach a continuation sheet.

PART A RESIDUAL TREATMENT PROCESS DESCRIPTION

8.01 In accordance with the instructions, provide a residual treatment block flow diagram which describes the treatment process used for residuals identified in question 7.01.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process



☐ Mark (X) this box if you attach a continuation sheet.

PART B RESIDUAL GENERATION AND CHARACTERIZATION

8.05 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI ☐ Process type Flexible Polyurethane Foam Manufacturing Process

a.	b.	c.	d.	e.	f.	g.
Stream ID Code	Type of Hazardous Waste ¹	Physical State of Residual ²	Known Compounds ³	Concentrations (% or ppm) ^{4,5,6}	Other Expected Compounds	Estimated Concentrations (% or ppm)
<u>7.4</u>	<u>H, R</u>	<u>GU</u>	<u>80% TDI</u>	<u>UK</u>	<u>NA</u>	<u>NA</u>
<u>7.6</u>	<u>H, R</u>	<u>OL</u>	<u>80% TDI</u>	<u>50% E/W</u>	<u>NA</u>	<u>NA</u>
		<u>SO</u>	<u>Polyurea Solids</u>	<u>50% E/W</u>	<u>NA</u>	<u>NA</u>
<u>7.9</u>	<u>T</u>	<u>OL</u>	<u>Fluoro Trichloromethane</u>	<u>50-80% E/W</u>	<u>NA</u>	<u>NA</u>
		<u>OL</u>	<u>Polyol</u>	<u>15-45% E/W</u>		
		<u>SO</u>	<u>Polyurethane</u>	<u>5-20% E/W</u>		
<u>7.11</u>	<u>H, T</u>	<u>GU</u>	<u>TDI</u>	<u>3ppm E/W</u>	<u>NA</u>	<u>NA</u>
		<u>GU</u>	<u>Fluoro Trichloromethane</u>	<u>4,500 ppm E/W</u>		
		<u>GU</u>	<u>Carbon Dioxide</u>	<u>7,200 ppm E/W</u>		

8.05 continued below

☒ Mark (X) this box if you attach a continuation sheet.

PART B RESIDUAL GENERATION AND CHARACTERIZATION

8.05 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI

[]

Process type

a.	b.	c.	d.	e.	f.	g.
Stream ID Code	Type of Hazardous Waste ¹	Physical State of Residual ²	Known Compounds ³	Concentrations (% or ppm) ^{4,5,6}	Other Expected Compounds	Estimated Concentrations (% or ppm)
7.13	T, H	GU	TDI	0.5 ppm / E/W	NA	NA
		GU	Fluorotrichloromethane	300 ppm / E/W		
		GU	Carbon Dioxide	500 ppm / E/W		
7.15	H, T	GU	TDI	0.5 ppm / E/W	NA	NA
		GU	Fluorotrichloromethane	300 ppm / E/W		
		GU	Carbon Dioxide	500 ppm / E/W		
7.17	H, T	GU	TDI	UK	NA	NA
		GU	Fluorotrichloromethane	UK		
		GU	Carbon Dioxide	UK		
7.19	NA	SO	Flexible Polyurethane Foam	100% / E/W	NA	NA

8.05 continued below

[] Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

¹Use the following codes to designate the type of hazardous waste:

I = Ignitable
C = Corrosive
R = Reactive
E = EP toxic
T = Toxic
H = Acutely hazardous

²Use the following codes to designate the physical state of the residual:

GC = Gas (condensable at ambient temperature and pressure)
GU = Gas (uncondensable at ambient temperature and pressure)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below

☐ Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

³For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column d. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
<u>1</u>	<u>NA</u>	
<u>2</u>		
<u>3</u>		
<u>4</u>		
<u>5</u>		

⁴Use the following codes to designate how the concentration was determined:

A = Analytical result
E = Engineering judgement/calculation

8.05 continued below

☐ Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

⁵Use the following codes to designate how the concentration was measured:

V = Volume

W = Weight

⁶Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

<u>Code</u>	<u>Method</u>	<u>Detection Limit</u> <u>(± ug/l)</u>
<u>1</u>	<u>NA</u>	<u> </u>
<u>2</u>	<u> </u>	<u> </u>
<u>3</u>	<u> </u>	<u> </u>
<u>4</u>	<u> </u>	<u> </u>
<u>5</u>	<u> </u>	<u> </u>
<u>6</u>	<u> </u>	<u> </u>

☐ Mark (X) this box if you attach a continuation sheet.

- 8.06 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

a.	b.	c.	d.	e.		f.	g.
Stream ID Code	Waste Description Code ¹	Management Method Code ²	Residual Quantities (kg/yr)	Management of Residual (%)		Costs for Off-Site Management (per kg)	Changes in Management Methods
				On-Site	Off-Site		
<u>7.9</u>	<u>A01</u>	<u>1A</u>	<u>1,920</u>	<u>0</u>	<u>100%</u>	<u>\$2.00</u>	<u>Eliminate Solvent Flush</u>
<u>7.6</u>	<u>B82</u>	<u>5SR</u>	<u>2</u>	<u>100%</u>	<u>NA</u>	<u>NA</u>	<u>None</u>
		<u>5S</u>	<u>0.4</u>	<u>100%</u>	<u>NA</u>	<u>NA</u>	<u>None</u>
<u>7.19</u>	<u>B90</u>	<u>2TR</u>	<u>1,060,000</u>	<u>100%</u>	<u>NA</u>	<u>NA</u>	<u>None</u>

¹Use the codes provided in Exhibit 8-1 to designate the waste descriptions

²Use the codes provided in Exhibit 8-2 to designate the management methods

☐ Mark (X) this box if you attach a continuation sheet.

8.22 Describe the combustion chamber design parameters for each of the three largest (by capacity) incinerators that are used on-site to burn the residuals identified in your process block or residual treatment block flow diagram(s).

☐ *Not Required*

Incinerator	Combustion Chamber Temperature (°C)		Location of Temperature Monitor		Residence Time In Combustion Chamber (seconds)	
	Primary	Secondary	Primary	Secondary	Primary	Secondary
1						
2						
3						

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

Yes 1
No 2

8.23 Complete the following table for the three largest (by capacity) incinerators that are used on-site to burn the residuals identified in your process block or residual treatment block flow diagram(s).

☐

Incinerator	Air Pollution Control Device ¹	Types of Emissions Data Available
1	NA	
2		
3		

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

Yes 1
No 2

¹Use the following codes to designate the air pollution control device:

S = Scrubber (include type of scrubber in parenthesis)
E = Electrostatic precipitator
O = Other (specify) _____

☐ Mark (X) this box if you attach a continuation sheet.

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01 Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data element the year in which you began maintaining records and the number of years the records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

☐

Data Element	Data are Maintained for:		Year in Which Data Collection Began	Number of Years Records Are Maintained
	Hourly Workers	Salaried Workers		
Date of hire	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Age at hire	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Work history of individual before employment at your facility	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Sex	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Race	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Job titles	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Start date for each job title	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
End date for each job title	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Work area industrial hygiene monitoring data	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Personal employee monitoring data	<u>X</u>	<u>NA</u>	<u>1983</u>	<u>3</u>
Employee medical history	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Employee smoking history	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Accident history	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Retirement date	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Termination date	<u>X</u>	<u>X</u>	<u>1975</u>	<u>3</u>
Vital status of retirees	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Cause of death data	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>

☐ Mark (X) this box if you attach a continuation sheet.

9.02 In accordance with the instructions, complete the following table for each activity in which you engage.

CBI

☐

a.	b.	c.	d.	e.
Activity	Process Category	Yearly Quantity (kg)	Total Workers	Total Worker-Hours
Manufacture of the listed substance	Enclosed	NA	NA	NA
	Controlled Release	NA	NA	NA
	Open	NA	NA	NA
On-site use as reactant	Enclosed	NA	NA	NA
	Controlled Release	1,692,360	8	8,000
	Open	2	3	1,200
On-site use as nonreactant	Enclosed	NA	NA	NA
	Controlled Release	NA	NA	NA
	Open	NA	NA	NA
On-site preparation of products	Enclosed	NA	NA	NA
	Controlled Release	NA	NA	NA
	Open	NA	NA	NA

☐ Mark (X) this box if you attach a continuation sheet.

9.03 Provide a descriptive job title for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance.

CBI

☐

Labor Category

Descriptive Job Title

A

Foam Machine Operator I

B

Foam Machine Operator II

C

Foam Machine Helper

D

Cut Off Saw Operator

E

Cart Operator

F

Fork Lift Operator

G

H

I

J

☐ Mark (X) this box if you attach a continuation sheet.

9.04 In accordance with the instructions, provide your process block flow diagram(s) and indicate associated work areas.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

*See Drawing For 7.01
(copy attached)*

☒ Mark (X) this box if you attach a continuation sheet.

9.05 Describe the various work area(s) shown in question 9.04 that encompass workers who may potentially come in contact with or be exposed to the listed substance. Add any additional areas not shown in the process block flow diagram in question 7.01 or 7.02. Photocopy this question and complete it separately for each process type.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

Work Area ID

Description of Work Areas and Worker Activities

1

Pull Storage and Pumping Area; Operate valves + pumps.

2

Metering and Mixing Control Area; Operate Control Console.

3

Side Film Rewind Area; Remove full rolls, replace with empty cores.

4

Cut Off Saw Area; Cut Buns to length and mark identity.

5

Bun Curing Area; Move Buns from Production Line to Curing Area.

6

7

8

9

10

☐ Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

☐ CBI Process type Flexible Polyurethane Foam Manufacturing Process
 Work area 1

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<u>A</u>	<u>1</u>	<u>skin Contact</u>	<u>OL</u>	<u>B</u>	<u>93</u>
<u>A</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>B</u>	<u>250</u>
<u>B</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>B</u>	<u>250</u>

¹Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensable at ambient temperature and pressure)	SY = Sludge or slurry
GU = Gas (uncondensable at ambient temperature and pressure; includes fumes, vapors, etc.)	AL = Aqueous liquid
SO = Solid	OL = Organic liquid
	IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

²Use the following codes to designate average length of exposure per day:

A = 15 minutes or less	D = Greater than 2 hours, but not exceeding 4 hours
B = Greater than 15 minutes, but not exceeding 1 hour	E = Greater than 4 hours, but not exceeding 8 hours
C = Greater than one hour, but not exceeding 2 hours	F = Greater than 8 hours

☒ Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

☐ CBI Process type Continued

Work area 2

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<u>A</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>D</u>	<u>250</u>
<u>B</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>D</u>	<u>250</u>
<u>C</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>D</u>	<u>250</u>

¹Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensable at ambient temperature and pressure)	SY = Sludge or slurry
GU = Gas (uncondensable at ambient temperature and pressure; includes fumes, vapors, etc.)	AL = Aqueous liquid
SO = Solid	OL = Organic liquid
	IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

²Use the following codes to designate average length of exposure per day:

A = 15 minutes or less	D = Greater than 2 hours, but not exceeding 4 hours
B = Greater than 15 minutes, but not exceeding 1 hour	E = Greater than 4 hours, but not exceeding 8 hours
C = Greater than one hour, but not exceeding 2 hours	F = Greater than 8 hours

☒ Mark (X) this box if you attach a continuation sheet.

9.06. Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type *Continued*

Work area 3

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<i>A</i>	<i>1</i>	<i>inhalation</i>	<i>GL</i>	<i>A</i>	<i>250</i>

¹Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensable at ambient temperature and pressure)
 GU = Gas (uncondensable at ambient temperature and pressure; includes fumes, vapors, etc.)
 SO = Solid

SY = Sludge or slurry
 AL = Aqueous liquid
 OL = Organic liquid
 IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

²Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
 B = Greater than 15 minutes, but not exceeding 1 hour
 C = Greater than one hour, but not exceeding 2 hours

D = Greater than 2 hours, but not exceeding 4 hours
 E = Greater than 4 hours, but not exceeding 8 hours
 F = Greater than 8 hours

☒ Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

☐ Process type Continued

Work area 4

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<u>D</u>	<u>1</u>	<u>inhalation</u>	<u>GL</u>	<u>D</u>	<u>250</u>
<u>E</u>	<u>6</u>	<u>inhalation</u>	<u>GL</u>	<u>D</u>	<u>250</u>

¹Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensable at ambient temperature and pressure)
 GU = Gas (uncondensable at ambient temperature and pressure; includes fumes, vapors, etc.)
 SO = Solid

SY = Sludge or slurry
 AL = Aqueous liquid
 OL = Organic liquid
 IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

²Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
 B = Greater than 15 minutes, but not exceeding 1 hour
 C = Greater than one hour, but not exceeding 2 hours

D = Greater than 2 hours, but not exceeding 4 hours
 E = Greater than 4 hours, but not exceeding 8 hours
 F = Greater than 8 hours

☒ Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type Continued

Work area 5

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<u>F</u>	<u>1</u>	<u>inhalation</u>	<u>GU</u>	<u>D</u>	<u>250</u>

¹Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensable at ambient temperature and pressure)
 GU = Gas (uncondensable at ambient temperature and pressure; includes fumes, vapors, etc.)
 SO = Solid

SY = Sludge or slurry
 AL = Aqueous liquid
 OL = Organic liquid
 IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

²Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
 B = Greater than 15 minutes, but not exceeding 1 hour
 C = Greater than one hour, but not exceeding 2 hours

D = Greater than 2 hours, but not exceeding 4 hours
 E = Greater than 4 hours, but not exceeding 8 hours
 F = Greater than 8 hours

☐ Mark (X) this box if you attach a continuation sheet.

9.07 For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process
 Work area 1

Labor Category	8-hour TWA Exposure Level (ppm, mg/m ³ , other-specify)	15-Minute Peak Exposure Level (ppm, mg/m ³ , other-specify)
<u>A</u>	<u>UK</u>	<u>UK</u>
<u>B</u>	<u>UK</u>	<u>UK</u>
<u>C</u>	<u>UK</u>	<u>UK</u>
<u>D</u>	<u>UK</u>	<u>UK</u>
<u>E</u>	<u>UK</u>	<u>UK</u>
<u>F</u>	<u>UK</u>	<u>UK</u>

☐ Mark (X) this box if you attach a continuation sheet.

PART B WORK PLACE MONITORING PROGRAM

9.08 If you monitor worker exposure to the listed substance, complete the following table.

CBI

☐

Sample/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples ¹	Analyzed In-House (Y/N)	Number of Years Records Maintained
Personal breathing zone	1-5	1	UK	D	N	UK
General work area (air)	1-5	1	UK	D	N	UK
Wipe samples	NA					
Adhesive patches	NA					
Blood samples	NA					
Urine samples	NA					
Respiratory samples	NA					
Allergy tests	NA					
Other (specify)	NA					
Other (specify)	NA					
Other (specify)	NA					

¹Use the following codes to designate who takes the monitoring samples:

A = Plant industrial hygienist

B = Insurance carrier

C = OSHA consultant

D = Other (specify) OSHA + Mass. Dept. of Hygiene

☐ Mark (X) this box if you attach a continuation sheet.

9.09 For each sample type identified in question 9.08, describe the type of sampling and analytical methodology used for each type of sample.

<input type="checkbox"/>	Sample Type	Sampling and Analytical Methodology
	UK	UK

9.10 If you conduct personal and/or ambient air monitoring for the listed substance, specify the following information for each equipment type used.

<input type="checkbox"/>	Equipment Type ¹	Detection Limit ²	Manufacturer	Averaging Time (hr)	Model Number
	UK	UK	UK	UK	UK

¹Use the following codes to designate personal air monitoring equipment types:

- A = Passive dosimeter
- B = Detector tube
- C = Charcoal filtration tube with pump
- D = Other (specify) _____

Use the following codes to designate ambient air monitoring equipment types:

- E = Stationary monitors located within work area
- F = Stationary monitors located within facility
- G = Stationary monitors located at plant boundary
- H = Mobile monitoring equipment (specify) _____
- I = Other (specify) _____

²Use the following codes to designate detection limit units:

- A = ppm
- B = Fibers/cubic centimeter (f/cc)
- C = Micrograms/cubic meter (μm^3)

☐ Mark (X) this box if you attach a continuation sheet.

9.11 If you conduct routine medical tests for monitoring the health effects of exposure to the listed substance, specify the type and frequency of the tests.

CBI

☐

Test Description

Frequency
(weekly, monthly, yearly, etc.)

NA

NA

☐ Mark (X) this box if you attach a continuation sheet.

PART C ENGINEERING CONTROLS

9.12 Describe the engineering controls that you use to reduce or eliminate worker exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type Flexible Polyurethane Manufacturing Process
 Work area 1-5

Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:				
Local exhaust	<u>Y</u>	<u>1975</u>	<u>Y</u>	<u>1987</u>
General dilution	<u>N</u>		<u>N</u>	<u>N</u>
Other (specify)	<u>NA</u>			
Vessel emission controls	<u>Y</u>		<u>N</u>	<u>NA</u>
Mechanical loading or packaging equipment	<u>NA</u>			
Other (specify)	<u>NA</u>			

☐ Mark (X) this box if you attach a continuation sheet.

9.13 Describe all equipment or process modifications you have made within the 3 years prior to the reporting year that have resulted in a reduction of worker exposure to the listed substance. For each equipment or process modification described, state the percentage reduction in exposure that resulted. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type NA

Work area

Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)

☐ Mark (X) this box if you attach a continuation sheet.

PART D PERSONAL PROTECTIVE AND SAFETY EQUIPMENT

9.14 Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process
Work area 7 1

Equipment Types	Wear or Use (Y/N)
Respirators	<u>N</u>
Safety goggles/glasses	<u>Y</u>
Face shields	<u>Y</u>
Coveralls	<u>N</u>
Bib aprons	<u>N</u>
Chemical-resistant gloves	<u>Y</u>
Other (specify)	
<u>Self Contained Demand Type Masks</u>	<u>Y</u>
_____	_____

☒ Mark (X) this box if you attach a continuation sheet.

PART D PERSONAL PROTECTIVE AND SAFETY EQUIPMENT

9.14 Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

☐ Process type Continued

Work area 2

<u>Equipment Types</u>	<u>Wear or Use (Y/N)</u>
Respirators	<u>N</u>
Safety goggles/glasses	<u>Y</u>
Face shields	<u>N</u>
Coveralls	<u>N</u>
Bib aprons	<u>N</u>
Chemical-resistant gloves	<u>N</u>
Other (specify)	
_____	<u>NA</u>
_____	<u>NA</u>

☐ Mark (X) this box if you attach a continuation sheet.

9.15 If workers use respirators when working with the listed substance, specify for each process type, the work areas where the respirators are used, the type of respirators used, the average usage, whether or not the respirators were fit tested, and the type and frequency of the fit tests. Photocopy this question and complete it separately for each process type.

CBI

☐ Process type NA

<u>Work Area</u>	<u>Respirator Type</u>	<u>Average Usage¹</u>	<u>Fit Tested (Y/N)</u>	<u>Type of Fit Test²</u>	<u>Frequency of Fit Tests (per year)</u>
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

¹Use the following codes to designate average usage:

A = Daily
 B = Weekly
 C = Monthly
 D = Once a year
 E = Other (specify) _____

²Use the following codes to designate the type of fit test:

QL = Qualitative
 QT = Quantitative

☐ Mark (X) this box if you attach a continuation sheet.

PART E WORK PRACTICES

- 9.19 Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this question and complete it separately for each process type and work area.

CBI

☐

Process type Flexible Polyurethane Foam Manufacturing Process

Work area 1 and 2

Authorized workers only, Safety glasses, Hazardous Material Labels, Training program

- 9.20 Indicate (X) how often you perform each housekeeping task used to clean up routine leaks or spills of the listed substance. Photocopy this question and complete it separately for each process type and work area.

Process type Flexible Polyurethane Foam Manufacturing Process

Work area 1 and 2

Housekeeping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
Sweeping	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Vacuuming	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Water flushing of floors	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Other (specify) <u>See Below</u>	<u>X</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>

Routine leaks and spills are eliminated by engineering controls. If one should occur, the material is immediately absorbed, placed in a proper container, and disposed of according to Hazardous Material Guidelines for local, State, and Federal rules.

☐

Mark (X) this box if you attach a continuation sheet.

9.21 Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?

Routine exposure

Yes *NR* 1

No 2

Emergency exposure

Yes 1

No 2

If yes, where are copies of the plan maintained?

Routine exposure: _____

Emergency exposure: _____

9.22 Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response.

Yes (1)

No 2

If yes, where are copies of the plan maintained? Work Area, Plant Office

Has this plan been coordinated with state or local government response organizations? Circle the appropriate response.

Yes (1)

No 2

9.23 Who is responsible for monitoring worker safety at your facility? Circle the appropriate response.

Plant safety specialist *NR* 1

Insurance carrier 2

OSHA consultant 3

Other (specify) _____ 4

☐ Mark (X) this box if you attach a continuation sheet.

SECTION 10 . ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

PART A GENERAL INFORMATION

10.01 Where is your facility located? Circle all appropriate responses.

CBI

- ☐ Industrial area 1
- Urban area 2
- Residential area 3
- Agricultural area 4
- Rural area 5
- Adjacent to a park or a recreational area 6
- Within 1 mile of a navigable waterway 7
- Within 1 mile of a school, university, hospital, or nursing home facility 8
- Within 1 mile of a non-navigable waterway 9
- Other (specify) _____ 10

☐ Mark (X) this box if you attach a continuation sheet.

10.02 Specify the exact location of your facility (from central point where process unit is located) in terms of latitude and longitude or Universal Transverse Mercader (UTM) coordinates.

Latitude 71° 21' 44"

Longitude 42° 28' 44"

UTM coordinates Zone _____, Northing _____, Easting _____

10.03 If you monitor meteorological conditions in the vicinity of your facility, provide the following information.

Average annual precipitation inches/year

Predominant wind direction ... Not Required

10.04 Indicate the depth to groundwater below your facility.

Depth to groundwater Not Required meters

10.05 For each on-site activity listed, indicate (Y/N/NA) all routine releases of the listed substance to the environment. (Refer to the instructions for a definition of Y, N, and NA.)

CBI

☐

On-Site Activity

Environmental Release

Manufacturing

Air

Water

Land

NA

NA

NA

Importing

NA

NA

NA

Processing

Y

NA

NA

Otherwise used

NA

NA

NA

Product or residual storage

NA

NA

NA

Disposal

NA

NA

NA

Transport

NA

NA

NA

☐ Mark (X) this box if you attach a continuation sheet.

10.06 Provide the following information for the listed substance and specify the level of precision for each item. (Refer to the instructions for further explanation and an example.)

CBI

☐

Quantity discharged to the air	<u>85</u>	kg/yr ± <u>10</u> %
Quantity discharged in wastewaters	<u>NA</u>	kg/yr ± ____ %
Quantity managed as other waste in on-site treatment, storage, or disposal units	<u>0.4</u>	kg/yr ± <u>25</u> %
Quantity managed as other waste in off-site treatment, storage, or disposal units	<u>NA</u>	kg/yr ± ____ %

☐ Mark (X) this box if you attach a continuation sheet.

10.08 Describe the control technologies used to minimize release of the listed substance for each process stream containing the listed substance as identified in your process block or residual treatment block flow diagram(s). Photocopy this question and complete it separately for each process type.

CBI

☐ Process type Flexible Polyurethane Foam Manufacturing Process

<u>Stream ID Code</u>	<u>Control Technology</u>	<u>Percent Efficiency</u>
<u>7.4</u>	<u>Controlled venting</u>	<u>99 %</u>
<u>7.5</u>	<u>Closed Tank</u>	<u>99.9%</u>
<u>7.6</u>	<u>Sealed Filter</u>	<u>99.99%</u>
<u>7.7</u>	<u>Metering Pump/mechanical seals</u>	<u>99.99%</u>
<u>7.8, 7I</u>	<u>Sealed Mix Chamber and Tubing</u>	<u>100%</u>
<u>7.10-7.17</u>	<u>Enclosed Areas with Exhaust Fans</u>	<u>99.99%</u>

☐ Mark (X) this box if you attach a continuation sheet.

PART B RELEASE TO AIR

- 10.09 Point Source Emissions -- Identify each emission point source containing the listed substance in terms of a Stream ID Code as identified in your process block or residual treatment block flow diagram(s), and provide a description of each point source. Do not include raw material and product storage vents, or fugitive emission sources (e.g., equipment leaks). Photocopy this question and complete it separately for each process type.

CBI

☐

Process type

Flexible Polyurethane Foam Manufacturing Process

Point Source
ID Code

Description of Emission Point Source

<i>7.6</i>	<i>Solids Filter, opened for maintenance 1 time per month</i>
<i>7.11</i>	<i>Vent Fan on Hood enclosing Reaction Zone</i>
<i>7.13</i>	<i>Vent Fans on Hooded Conveyor Section</i>
<i>7.15</i>	<i>Vent Fans on Cut Off Saw</i>
<i>7.17</i>	<i>Vent Fans in Curing Area</i>

☐ Mark (X) this box if you attach a continuation sheet.

☐ Mark (X) this box if you attach a continuation sheet.

10.10 Emission Characteristics -- Characterize the emissions for each Point Source ID Code identified in question 10.09 by completing the following table.

CBI

☐

Point Source ID Code	Physical State ¹	Average Emissions (kg/day)	Frequency ² (days/yr)	Duration ³ (min/day)	Average Emission Factor ⁴	Maximum Emission Rate (kg/min)	Maximum Emission Rate Frequency (events/yr)	Maximum Emission Rate Duration (min/event)
7.6	OV	NA	12	15	NA	UK	12	15
7.11	V	0.42	250	120	0.00006	0.004	400	30
7.13	V	0.06	250	120	0.000009	0.0007	400	30
7.15	V	0.06	250	120	0.000009	0.0007	400	30
7.17	V	UK	250	360	UK	UK	UK	UK

¹Use the following codes to designate physical state at the point of release:

G = Gas; V = Vapor; P = Particulate; A = Aerosol; O = Other (specify) Organic Solid

²Frequency of emission at any level of emission

³Duration of emission at any level of emission

⁴Average Emission Factor -- Provide estimated (\pm 25 percent) emission factor (kg of emission per kg of production of listed substance)

10.11 Stack Parameters -- Identify the stack parameters for each Point Source ID Code identified in question 10.09 by completing the following table.

CBI

☐

Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m) ¹	Building Width(m) ²	Vent Type ³
7.11	7.93	0.61	23.9	15.9	4.9	80	V
7.13	7.93	1.02	37.8	18.6	4.9	80	V
7.15	7.93	0.61	26.7	15.9	4.9	80	V

¹Height of attached or adjacent building

²Width of attached or adjacent building

³Use the following codes to designate vent type:

H = Horizontal

V = Vertical

☐ Mark (X) this box if you attach a continuation sheet.

10.12 If the listed substance is emitted in particulate form, indicate the particle size distribution for each Point Source ID Code identified in question 10.09.
Photocopy this question and complete it separately for each emission point source.

CBI

☐

Point source ID code NA

Size Range (microns)

Mass Fraction (% ± % precision)

< 1

≥ 1 to < 10

≥ 10 to < 30

≥ 30 to < 50

≥ 50 to < 100

≥ 100 to < 500

≥ 500

Total = 100%

☐ Mark (X) this box if you attach a continuation sheet.

PART C FUGITIVE EMISSIONS

10.13 Equipment Leaks -- Complete the following table by providing the number of equipment types listed which are exposed to the listed substance and which are in service according to the specified weight percent of the listed substance passing through the component. Do this for each process type identified in your process block or residual treatment block flow diagram(s). Do not include equipment types that are not exposed to the listed substance. If this is a batch or intermittently operated process, give an overall percentage of time per year that the process type is exposed to the listed substance. Photocopy this question and complete it separately for each process type.

CBI ☐ Process type Flexible Polyethylene Foam Manufacturing Process
 Percentage of time per year that the listed substance is exposed to this process type 9.0 %

Equipment Type	Number of Components in Service by Weight Percent of Listed Substance in Process Stream					Greater than 99%
	Less than 5%	5-10%	11-25%	26-75%	76-99%	
Pump seals ¹						
Packed	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Mechanical	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>1</u>	<u>NA</u>	<u>2</u>
Double mechanical ²	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Compressor seals ¹	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Flanges	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>2</u>	<u>NA</u>	<u>4</u>
Valves						
Gas ³	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Liquid	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>1</u>	<u>NA</u>	<u>8</u>
Pressure relief devices ⁴ (Gas or vapor only)	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>2</u>
Sample connections						
Gas	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>2</u>
Liquid	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>1</u>
Open-ended lines ⁵ (e.g., purge, vent)						
Gas	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
Liquid	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>

¹ List the number of pump and compressor seals, rather than the number of pumps or compressors

10.13 continued on next page

☐ Mark (X) this box if you attach a continuation sheet.

10.13 (continued)

² If double mechanical seals are operated with the barrier (B) fluid at a pressure greater than the pump stuffing box pressure and/or equipped with a sensor (S) that will detect failure of the seal system, the barrier fluid system, or both, indicate with a "B" and/or an "S", respectively

³ Conditions existing in the valve during normal operation

⁴Report all pressure relief devices in service, including those equipped with control devices

⁵ Lines closed during normal operation that would be used during maintenance operations

10.14 Pressure Relief Devices with Controls -- Complete the following table for those pressure relief devices identified in 10.13 to indicate which pressure relief devices in service are controlled. If a pressure relief device is not controlled, enter "None" under column c.

[]

[illegible]

¹Refer to the table in question 10.13 and record the percent range given under the heading entitled "Number of Components in Service by Weight Percent of Listed Substance" (e.g., <5%, 5-10%, 11-25%, etc.)

²The EPA assigns a control efficiency of 100 percent for equipment leaks controlled with rupture discs under normal operating conditions. The EPA assigns a control efficiency of 98 percent for emissions routed to a flare under normal operating conditions

☐ Mark (X) this box if you attach a continuation sheet.

10.16 Raw Material, Intermediate and Product Storage Emissions - - Complete the following table by providing the information on each liquid raw material, intermediate, and product storage vessel containing the listed substance as identified in your process block or residual treatment block flow diagram(s).

CBI	<input type="checkbox"/>	Vessel Type ¹	Floating Roof ² Seals	Composition of Stored Materials ³	Throughput (liters per year)	Vessel Filling Rate (gpm)	Vessel Filling Duration (min)	Vessel Inner Diameter (m)	Vessel Height (m)	Operating Vessel Volume (l)	Vessel Emission Controls ⁴	Design Flow Rate ⁵	Vent Diameter (cm)	Control Efficiency (%)	Basis for Estimate ⁶	
		TDI 01 H	NA	100%	693,591	50	90	2.8	4.7	28,800	Pressure Relief Valve	>50 cfm	8.5	100%	S	Valve has never opened
		TDI 02 H	NA	100%	693,591	50	90	2.8	4.7	28,800	Pressure Relief Valve	>50 cfm	8.5	100%	S	Valve has never opened

¹Use the following codes to designate vessel type:

F = Fixed roof
 CIF = Contact internal floating roof
 NCIF = Noncontact internal floating roof
 EFR = External floating roof
 P = Pressure vessel (indicate pressure rating)
 H = Horizontal
 U = Underground

²Use the following codes to designate floating roof seals:

MS1 = Mechanical shoe, primary
 MS2 = Shoe-mounted secondary
 MS2R = Rim-mounted, secondary
 LM1 = Liquid-mounted resilient filled seal, primary
 LM2 = Rim-mounted shield
 LMW = Weather shield
 VM1 = Vapor mounted resilient filled seal, primary
 VM2 = Rim-mounted secondary
 VMW = Weather shield

³Indicate weight percent of the listed substance. Include the total volatile organic content in parenthesis

⁴Other than floating roofs

⁵Gas/vapor flow rate the emission control device was designed to handle (specify flow rate units)

⁶Use the following codes to designate basis for estimate of control efficiency:

C = Calculations
 S = Sampling

PART E NON-ROUTINE RELEASES

10.23 Indicate the date and time when the release occurred and when the release ceased or was stopped. If there were more than six releases, attach a continuation sheet and list all releases.

Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)
1	NA			
2				
3				
4				
5				
6				

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	Humidity (%)	Temperature (°C)	Precipitation (Y/N)
1					
2					
3					
4					
5					
6					

Not Required

☐ Mark (X) this box if you attach a continuation sheet.

10.25 Complete the following information for each media into which the listed substance was released. Any volatile substance that was released to land, but that was expected to volatilize, should be listed as a release to air.

Release No. NA

<u>Media</u>	<u>Quantity (kg)</u>	<u>Method of Release</u>	<u>Migration Beyond Boundaries (Y/N)</u>	<u>Quantity Migrated (kg)</u>
Land	_____	_____	_____	_____
Air	_____	_____	_____	_____
Groundwater	_____	_____	_____	_____
Surface water	_____	_____	_____	_____

10.26 Specify the physical state and concentration of the listed substance at the time and point of release.

Release No. NA

Point of release _____

Physical state _____

Concentration (%) _____

☐ Mark (X) this box if you attach a continuation sheet.

10.27 Circle all appropriate responses relating to the cause and the effects of the release.

Release No.

NA

Cause of Release

- Equipment failure 1
- Operator error 2
- Bypass condition 3
- Upset condition 4
- Fire 5
- Unknown 6
- Other (specify) 7

Results of Release

- Spill 1
- Vapor release 2
- Explosion 3
- Fire 4
- Other (specify) 5

☐ Mark (X) this box if you attach a continuation sheet.

10.28 Specify which authorities were notified of the release.

Release No. 177

a. Federal

Agency

[illegible][illegible][illegible][illegible]

[]
State

Telephone Number [] [] [] - [] [] [] - [] [] [] []

Date Notified
Mo. Day Year

Time Notified [] [] [] [] am/pm

b. State

[illegible][illegible][illegible][illegible][illegible]

State

Telephone Number () () () - () () () - () () () ()

Date Notified
Mo. Day Year

Time Notified [] [] [] [] am/pm

10.28 continued below

☐ Mark (X) this box if you attach a continuation sheet.

10.28 (continued)

c. Local

Agency

Office _____

Contact Person []

[illegible]

City

[] []
State

Telephone Number [] [] [] - [] [] [] - [] [] [] []

Date Notified
Mo. Day Year

Time Notified [] [] [] [] am/pm

10.29 For each of the proximities listed below, indicate whether the population living within that proximity was notified of, or evacuated because of the release. Specify who notified the population, the number of people evacuated, if any, and the date and time of day the evacuation began.

Release No. NA

<u>Proximity to the Release</u>	<u>Notified of Release (Y/N)</u>	<u>Notifying Person</u>	<u>Notifying Person's Telephone Number</u>	<u>Area Evacuated (Y/N)</u>	<u>Number of Persons Evacuated</u>	<u>Date and Time of Day Evacuation Began</u>
1/4 mile						
1/2 mile						
1 mile						
Other (specify)						

☐ Mark (X) this box if you attach a continuation sheet.

10.30 Specify the number of personal injuries or casualties resulting from the release.

Release No. N7

Number of injuries to facility employees

Number of injuries to general population _____

Number of deaths to facility employees _____

Number of deaths to general population

10.31 Indicate who conducted cleanup activities, and the dates over which the cleanup was performed.

Release No. NA

Name

[illegible]

Street

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

City

$$[\overline{1}][\overline{1}] \quad [\overline{1}][\overline{1}][\overline{1}][\overline{1}][\overline{1}] = [\overline{1}][\overline{1}][\overline{1}][\overline{1}]$$

State

Zip

Telephone Number [] [] [] - [] [] [] - [] [] [] []

Date Cleanup Initiated [] [] [] []

Mo.

Year

Date Cleanup Completed (or expected) [] [] [] []

Mo.

Year

10.32 Briefly describe the release prevention practices and policies (backup systems, containment systems, training programs, etc.) in place at the facility at the time the release occurred.

Release No. NA

☐ Mark (X) this box if you attach a continuation sheet.

10.33 Indicate which of the prevention practices and policies listed in question 10.32 were ineffective in preventing the release from reaching the environment.

Release No. NA

10.34 Describe all repairs and/or preventive measures (management practices, operational changes, etc.) made to equipment or operations as a result of the release.

Release No. NA

10.35 Describe additional preventive measures that will be taken to minimize the possibilities of recurrence.

Release No. NA

☐ Mark (X) this box if you attach a continuation sheet.

APPENDIX I: List of Continuation Sheets

Attach continuation sheets for sections of this form and optional information after this page. In column 1, clearly identify the continuation sheet by listing the question number to which it relates. In column 2, enter the inclusive page numbers of the continuation sheet for each question number.

[illegible]

☐ Mark (X) this box if you attach a continuation sheet.



HOOD INDUSTRIES, INC

108 PARKER STREET
NEWBURYPORT, MA 01950

Document Processing Center
Office of Toxic Substances, TS-790
U.S. Environmental Protection Agency
401 M. Street SW
Washington, D.C. 20460

Attn: CAIR Reporting Office

• • • RETURN REQUESTED • • •



CERTIFIED

P 285 600 612

MAIL